

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1522542546 **229137** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SRO State Com #43	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-41141
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	17	26S	28E	190'	North	990'	West	Eddy

Latitude 32.0492096 Longitude -104.1149597

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 9 bbls	Volume Recovered: 5 bbls
Source of Release: Oil Hauler	Date and Hour of Occurrence: 10/19/2015 5:30 pm	Date and Hour of Discovery: 10/19/2015 5:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT

NOV 10 2015

RECEIVED



Describe Cause of Problem and Remedial Action Taken.*

While pulling a load of oil the truck driver overfilled his truck causing the oil to spill onto the location. A vacuum truck was able to recover 5 bbls of fluid. This release was caused by a third party oil hauler, Gibson Energy.

Describe Area Affected and Cleanup Action Taken.*

The impacted area remained on the pad near the LACT. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 11/12/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input checked="" type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO <input type="checkbox"/>	
Date: November 1, 2015 Phone: 575-748-6940	LATER THAN: 12/12/15	

* Attach Additional Sheets If Necessary

2RP-3350

Patterson, Heather, EMNRD

From: Amanda Trujillo Davis <ATrujillo@concho.com>
Sent: Monday, November 09, 2015 5:10 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: (Notification/C-141) SRO State Com #43H (30-015-41141)
Attachments: 10-19-2015 SRO State Unit #43H (TB) Initial.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release on the SRO State Com #43H (30-015-41141)
Unit D Section 17, Township 26S Range 28E
The release occurred at 10/19/2015 at 5:30 am
Released: 9 bbls Oil
Recovered: 5 bbls Oil

While pulling a load of oil the truck driver overfilled his truck causing the oil to spill onto the location. A vacuum truck was able to recover 5 bbls of fluid. **This release was caused by a third party oil hauler, Gibson Energy. Gibson Energy submitted a C-141 on our behalf. We would like to void their submitted C-141 and replace it with ours. It is our policy not to have C-141s submitted on our behalf. Attached is a C-141 for your consideration.** If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo Davis
Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



2RP-3350

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.