111 S. First S., Arcias, NM 8210 Oil Conservation Division Some Notal, Auter, NM 8740 Satuta Fe, NM 87505 Statuta Fe, NM 87505 Release Notification and Corrective Action Address Oil Conservation Division Statu Fe, NM 87505 Release Notification and Corrective Action Address Oil Conservation Division Name of Company Oxy Permian Lid. OPERATOR Initial Report Address Operation of Company Oxy Permian Lid. Contact Casey Summers Address Operation of Company Oxy Permian Lid. LOCATION OF RELEASE Unit Letter Section Address Operation Of Release Oil and Produced water Address Operation of Release Oil and Produced water Operation of Release Oil and Produced water Ope	French Dr., Hóbbs, NM 88240 Energy Minerals III Oil Conse o Brazos Road, Aztec, NM 87410 1220 Sout N St. Francis Dr., Santa Fe, NM 87505 Santa F Release Notificatio All LOO 554 655 Oil Conse c of Company Oxy Permian Ltd. UA400 ess 6 Desta Drive, Midland, TX 79705 Its Press tty Name McKittrick Hills Central Tank Battery Its Press ce Owner BLM Mineral Owner - LOCATIO Its Press etter Section Township Range Iter Section Township Range Nature Iter Section Township Range Nature	and Natura ervation Div h St. France Fe, NM 875 on and Ce OPERA Contact Telephone I Facility Typ ON OF RE	al Resources vision cis Dr. 505 Drrective A TOR Casey Summers No. (575) 513 pe Battery	DEC 3 1 Submit Cop RECEIV ction 28289	Form C-14 2015 Revised August 8. 201 by to appropriate District Office i accordance with 19.15.29 NMAC
District III (000 Ho Branch II) (200 Kin Branch Dr. Sama Fe, NM 8700 (200 Kin Branch Dr. Sama Fe, NM 8700) (200 Kin Branch Dr. Sama Fe, NM 8700 (200 Kin Branch Dr. Sama Fe, NM 8700 (200 Kin Branch Dr. Sama Fe, NM 8700) (200 Kin Branch Dr. Sama Fe, NM 8700 (200 Kin Branch Dr. Sama Fe, NM 8700) (200 Kin Branch Dr. Sama Fe, NM 870	III Oil Conse 0 Brazos Road, Aztec. NM 87410 1220 Sout IV 1220 Sout St. Francis Dr., Santa Fe, NM 87505 Santa F Release Notificatio B14005544555 04403 cof Company Oxy Permian Ltd. ess 6 Desta Drive, Midland, TX 79705 ty Name McKittrick Hills Central Tank Battery ce Owner BLM	th St. Franc Fe, NM 875 on and Co OPERA Contact Telephone I Facility Typ ON OF RE	cis Dr. 505 Drrective A TOR Casey Summers No. (575) 513 pe Battery	RECEIV	ED
Release Notification and Corrective Action MAB1600554655 OPERATOR Initial Report Name of Company Oxy Permian Lid. OPERATOR Initial Report Address 6 Desta Drive, Midland, TX 79705 Telephone No. (575) 513-8289 Facility Name McKittrick Hills Central Tank Battery Facility Type Battery Surface Owner BLM Mineral Owner API No. 30-015-2101 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County A 14 235 24E LocAtTON OF RELEASE Volume of Release 20 bils oil. County ATURE OF RELEASE Type of Release Oil and Produced water Volume Recovered Volume of Release 20 bils oil. Volume Recovered	Release Notificatio B1400554655 B4403 cof Company Oxy Permian Ltd. 004403 ess 6 Desta Drive, Midland, TX 79705 004403 ty Name McKittrick Hills Central Tank Battery 000000000000000000000000000000000000	On and Co OPERA' Contact C Telephone I Facility Typ	Drrective A TOR Casey Summers No. (575) 513 pe Battery	-8289	tial Report 🔲 Final Rep
MAB1400554455 OPERATOR Initial Report Name of Company Oxy Permian Ld. Contact Casey Summers Address 6 Desta Drive, Midland, TX 79705 Telephone No. (575) 513-5289 Facility Name McKitrick Hills Central Tark Battery Facility Type Battery Surface Owner BLM Mineral Owner API No. 30-015-2101 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County, I Latitude N 32.39755* Longitude W 104.46100° Nature Concerned Koles produced water Volume of Release 20 bits oil. Volume Recovered 160 bits Source of Release Oil and Produced water Volume of Release 20 bits oil. Volume Recovered 160 bits 100 bits could water 100 bits produced water 100 bits overed/1020015 100 bits 100 bits could water 100 bits 100 bits could water 100 bits	BILDD 554655 of Company Oxy Permian Ltd. Intervention 1000000000000000000000000000000000000	OPERA Contact Telephone I Facility Typ	TOR Casey Summers No. (575) 513 pe Battery	-8289	tial Report 🔲 Final Rep
Name of Company Oxy Permian Ltd. UPUC Contact Casey Summers Address 6 Desta Drive, Midland, TX 79705 Telephone No. (\$75) 513-8289 Facility Name Mineral Owner API No. 30-015-2101 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County A 14 225 24E Volume OF RELEASE Volume M 104.46109° NATURE OF RELEASE Type of Release Oil and Produced water Volume Of Release 20 bils oil, Volume Recovered 160 bils produced water 160 bils produced water 160 bils produced water 160 bils Source of Release Caid arms to warm of a tank overfill Date and Hour of Occurrence Date and Hour of Occurrence Date and Hour of Occurrence 1209/2015 Was Immediate Notice Given? Yes No Not Required Mike Bratcher-NMOCD: Shelly Tucker-BLM By Whom? Cliff Brunson @ BBC International Date and Hour of 20/05 @ 5:00 pm Was a Watercourse Reached? Yes No If a Watercourse was Impacted, Describe Fully*	ce Owner BLM Mineral Owner Ce	Contact C Telephone I Facility Typ	Casey Summers No. (575) 513 pe Battery	-8289	
Facility Name McKittrick Hills Central Tank Battery Facility Type Battery Surface Owner BLM Mineral Owner API No. 30-015-2101 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County A 14 225 24E Latitude N 32,39755° Longitude W 104.46109° NATURE OF RELEASE Type of Release Oil and Produced water Yolume of Release 20 hils oil, 160 bils produced water Source of Release Lack of alarms to warn of a tank overfill Date and Hour of Occurrence 160 bils produced water Date and Hour of Discove 120/9/2015 Was Immediate Notice Given? Xes No Not Required Mike Bratcher-NMOCD: Shelly Tucker-BLM By Whon? Cliff Branson @ BBC International Date and Hour of 20/0/215 @ 5:00 pm If YES, Volume Impacting the Watercourse. If a Watercourse Reached? Yes No If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully* Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water	ty Name McKittrick Hills Central Tank Battery ce Owner BLM Mineral Owner - LOCATIO Letter Section Township Range Feet from the North 14 22S 24E Latitude N 32.39755 NATURE	Facility Typ	pe Battery		
Surface Owner BLM Mineral Owner API No. 30-015-2101 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County A 14 225 24E North/South Line Feet from the East/West Line County A 14 225 24E North/South Line Feet from the East/West Line County Eddy County, 1 Latitude N 32.39755* Longitude W 104.46109* North/South Line Feet from the Part Part Part Part Part Part Part Part	ce Owner BLM Mineral Owner - LOCATIO Letter Section Township Range Feet from the North 14 22S 24E Latitude N 32.39755 NATURE	ON OF RE		APIN	<u></u>
LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County A 14 22S 24E Latitude N 32.39755° Longitude W 104.46109° NATURE OF RELEASE Type of Release Oil and Produced water Volume of Release 20 bbls oil. Volume Recovered 160 bbls produced water Uobls produced water 160 bbls Date and Hour of Occurrence Date and Hour of Occurrence 209/2015 Was Immediate Notice Given? Yes No Not Required Mike Bratcher.NMOCD: Shelly Tucker-BLM By Whom? Cliff Brunson @ BBC International Date and Hour 12/10/2015 @ 5:00 pm Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted. Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused at ank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved to NMOCD and the BLM. I hereby c	LOCATIO Letter Section Township Range Feet from the North 14 22S 24E Latitude N 32.39755 NATURE		LEASE	1 1 1 1	lo 30-015-21010
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County A 14 228 24E Latitude N 32.39755° Longitude W 104.46109° NATURE OF RELEASE Type of Release Oil and Produced water Volume of Release 20 bhls oil, 160 bbls produced water Volume Recovered 160 bbls Source of Release Oil and Produced water Volume of Release 20 bhls oil, 160 bbls Volume Recovered 160 bbls Source of Release Lack of alarms to warn of a tank overfill Date and Hour of Occurrence 12009/2015 Date and Hour of Cocurrence 12009/2015 Was Immediate Notice Given? Yet No No Required Mike Bratcher-NMOCD: Shelly Tucker-BLM By Whon? Cliff Brunson @ BBC International Date and Hour 12/10/2015 @ 5:00 pm Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* No If YES, Volume Impacting the watercourse. If YES, Volume Impacting the vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corre	Letter Section Township Range Feet from the North 14 22S 24E Latitude N 32.39755 NATURE		L.P.A.N.P.		10. 30-013-21010
Latitude N 32.39755° Longitude W 104.46109° NATURE OF RELEASE Type of Release Oil and Produced water Volume Recovered 160 bbls produced water Lob bbls Date and Hour of Ceurrence Date and Hour of Decurrence Source of Release Lack of alarms to warm of a tank overfill Date and Hour of Occurrence Date and Hour of Discove Was Immediate Notice Given? Yes No Not Required Mike Bratcher-NMOCD: Shelly Tucker-BLM By Whom? Cliff Brunson @ BBC International Date and Hour 12/10/2015 @ 5:00 pm If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? Yes No If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved to NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCT regulations all operators are required to report and/or file catina release notificati	Latitude <u>N 32.39755</u> NATURE			East/West Line	County
Latitude N 32.39755° Longitude W 104.46109° NATURE OF RELEASE Type of Release Oil and Produced water Volume Recovered 160 bbls produced water Lob bbls Date and Hour of Ceurrence Date and Hour of Decurrence Source of Release Lack of alarms to warm of a tank overfill Date and Hour of Occurrence Date and Hour of Discove Was Immediate Notice Given? Yes No Not Required Mike Bratcher-NMOCD: Shelly Tucker-BLM By Whom? Cliff Brunson @ BBC International Date and Hour 12/10/2015 @ 5:00 pm If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? Yes No If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved to NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCT regulations all operators are required to report and/or file catina release notificati	Latitude <u>N 32.39755</u> NATURE				Eddy County NM
NATURE OF RELEASE Type of Release Oil and Produced water Volume of Release 20 bils oil. Volume Recovered Source of Release Lack of alarms to warn of a tank overfill Date and Hour of Occurrence Date and Hour of Occurrence Source of Release Lack of alarms to warn of a tank overfill Date and Hour of Occurrence Date and Hour of Occurrence Was Immediate Notice Given? Yes No Not Required Mike Bratcher-NMOCD: Shelly Tucker-BLM By Whom? Cliff Brunson @ BBC International Date and Hour 12/10/2015 @ 5:00 pm Was a Watercourse Reached? Was a Watercourse Reached? Yes No If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved b NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCI regulations all operators are required to report and/or file certain release notifications and perform	NATURE			0°	[200] County, 111
Type of Release Oil and Produced water Volume of Release 20 bils oil. (160 bbls produced water Volume Recovered (160 bbls produced water Source of Release Lack of alarms to warn of a tank overfill Date and Hour of Occurrence (12/09/2015 Date and Hour of Occurrence Was Immediate Notice Given? If YES. To Whom? If YES. To Whom? Mike Bratcher-NMOCD: Shelly Tucker-BLM By Whom? Cliff Brunson @ BBC International Date and Hour 12/10/2015 @ 5:00 pm Was a Watercourse Reached? Yes No If a Watercourse was Impacted, Describe Fully.* If YES, Volume Impacting the Watercourse. Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved b NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCI as all operators are required to report and/or file certain release notifications and perform corrective actions have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of resp				<u></u>	
Source of Release Lack of alarms to warn of a tank overfill Date and Hour of Occurrence Date and Hour of Occurrence Was Immediate Notice Given? Wes No No No Required Mike Bratcher-NMOCD: Shelly Tucker-BLM By Whom? Cliff Brunson @ BBC International Date and Hour 12/10/2015 @ 5:00 pm Was a Watercourse Reached? Was a Watercourse Reached? Yes No If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved to NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may public health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for compliance with federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION OIL CONSERVATION DIVISION	of Release Oil and Produced water	Volume of	f Release 20 bbls	oil. Volum	e Recovered
12/09/2015 Was Immediate Notice Given? If YEs No Not Required Mike Bratcher-NMOCD: Shelly Tucker-BLM By Whom? Cliff Brunson @ BBC International Date and Hour 12/10/2015 @ 5:00 pm Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted. Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved to NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of the environment. The acceptance of a C-141 report does not relieve the operator for responsibility for compliance with federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION	e of Release Lack of alarms to warm of a tank overfill				
Yes No Not Required Mike Bracher-NMOCD: Shelly Tucker-BLM By Whom? Cliff Brunson @ BBC International Date and Hour 12/10/2015 @ 5:00 pm Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* If YES, Volume Impacting the Watercourse. Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* The affected and Cleanup Action Taken.* The affected and Cleanup Action Taken.* I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with federal, state, or peal laws and/or regulations. OIL CONSERVATION DIVISION		12/09/201	5		
Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved to NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCI regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION				elly Tucker-BL	vi
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved to NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCI regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may public health or the environment. The acceptance of a C-141 report does not relieve the operator should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with federal, state, or pical laws and/or regulations. OIL CONSERVATION DIVISION					
Describe Cause of Problem and Remedial Action Taken.* Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered fluids and the alarm issue was corrected. Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved to NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCT regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with federal, state, or peal laws and/or regulations.		If YES, V	olume Impacting	he Watercourse.	
Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved to NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCI regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION	of alarms caused a tank to overfill spilling 20 bbls of oil and 160 b	bls of produce	ed water onto the g	round. A vacuu	m (nuck recovered 160 bbls of
The affected area is approximately 75' x 50' on location. Remediation will be completed in accordance with a remediation plan approved to NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCI regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with federal, state, or peal laws and/or regulations.					
NMOCD and the BLM. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCI regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION	ibe Area Affected and Cleanup Action Taken.*				
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with federal, state, or peal laws and/or regulations.		will be comple	eted in accordance	with a remediati	on plan approved by both
	ations all operators are required to report and/or file certain release thealth or the environment. The acceptance of a C-141 report by to d their operations have failed to adequately investigate and remedi- environment. In addition, NMOCD acceptance of a C-141 report	notifications a the NMOCD r ate contamina	and perform corre- narked as "Final F tion that pose a the we the operator of	ctive actions for eport" does not reat to ground wa responsibility fo	releases which may endanger relieve the operator of liability ater, surface water, human health r compliance with any other
Approved by Environmental Specialist:	- <u>4</u>	Approved by			N DIVISION
Printed Name: Cases/Summers Title: NM Environmental Advisor Approval Date:		Approval D	ale: 11511		on Date: NA
E-mail Address: Casey Summers@oxy.com	Address: Casey Summers@oxy.com				
Date: 12/30/15 Phone: (575) 513-8289 SUBMIT REMEDIATION PROPOSAL ND			REMEDIATION	í •	L ND

Patterson, Heather, EMNRD

, Kathy Purvis <kathy@bbcinternational.com></kathy@bbcinternational.com>
Wednesday, December 30, 2015 4:43 PM
Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Casey_Summers@oxy.com; dusty_wilson@oxy.com; Jennifer_duarte@oxy.com;
frank_barnett@oxy.com;
kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Initial C-141s for McKittrick Hills CTB and Cedar Canyon 28 Federal #6
Initial C-141, McKittrick Hills CTB.pdf; Initial C-141, Cedar Canyon 28 Federal #6.pdf

1

Attached are the initial C-141s for two leaks occurring at the McKittrick Hills CTB on 12/09/2015 and the Cedar Canyon 28 Federal #6 on 12/20/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240 Phone: (575) 397-6388 Fax: (575) 397-0397 Email: <u>kathy@bbcinternational.com</u>