

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company DCP Midstream, LLC	Contact Patricia Grajeda
Address 10 Desta Drive, Suite 400 W, Midland, TX 79705	Telephone No. 432-620-5403
Facility Name M Extension Line	Facility Type Pipeline

Surface Owner BLM	Mineral Owner	API No.
-------------------	---------------	---------

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	5	19S	31E					LEA

Latitude N32.6955 Longitude W103.8857

NATURE OF RELEASE

Type of Release Gas and Liquid	Volume of Release ~1500 Mscf/15 bbls	Volume Recovered 0
Source of Release Pipeline	Date and Hour of Occurrence 4Jan12 1444hrs	Date and Hour of Discovery Same
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? Johnnie Bradford	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A	<div>RECEIVED</div> <div>MAR 5 2012</div> <div>NMOCD ARTESIA</div>	
Describe Cause of Problem and Remedial Action Taken.* Pipe developed a hole on the bottom of the pipeline due to corrosion. Line was isolated, then replaced with poly pipe. All saturated soil that was excavated during repair, was stockpiled on plastic for transport during the remediation phase.		
Describe Area Affected and Cleanup Action Taken.* The affected area was a two-track ROW road and the immediate area near the point of release. The affected part of the road was approx 3'W x 1000'L. The area near the point of release was approx 30'W x 100'L x 10'D. Both areas were excavated with the material being stockpiled for transportation to a division approved facility. Soil samples were obtained and results presented to NM OCD's Mike Bratcher for closure approval. Approval was given and the area was backfilled with clean material, contoured and seeded with a BLM approved seed mixture. BLM's Jim Amos was notified by phone of the work plan as well and advised we could proceed. Jim was advised that the release remained on the ROW and no other area was affected.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Patricia Grajeda	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 5/11/10	Expiration Date: N/A
E-mail Address: PGrajedaDeBabb@depdmidstream.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 1Mar12 Phone: 432-620-5403		

* Attach Additional Sheets If Necessary

MLB120545-1603

ZRP-1043