NM OIL CONSERVATION

ARTESIA DISTRICT

JUL **0 1** 2016

Form C-141 Revised August 8, 2011

2RP-370

Submit 1 Copy to appropriate District Office in RECEIVED dance with 19.15.29 NMAC.

State of New Mexico Energy Minerals and Natural Resources

District II
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fc, NM 87505

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240

District II

Date: 7/1/2016

* Attach Additional Sheets If Necessary

Phone: 432-661-0571

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Santa 1	c, 141/1 67505	
Release Notification and Corrective Action		
nAB11018836105	OPERATOR	
Name of Company: BOPCO, L.P.	Contact: Amy Ruth	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: JRU #55 Battery Facility Type: Exploration and Production		
Surface Owner: Federal Mineral Owner:	Federal	API No. 30-015-27589
LOCATION OF RELEASE		
Unit Letter Section Township Range Feet from the North	South Line Feet from the East	/West Line County
F 17 23S 31E 2060 North	1850 West	t Eddy
Latitude 32.306040° Longitude -103.802369°		
NATURE OF RELEASE		
Type of Release Produced Water and Crude Oil	Volume of Release 7 bbls PW 3 bbls oil	Volume Recovered 2 bbls PW 1 bbl oil
Source of Release Oil circulating line	Date and Hour of Occurrence 6/22/2016 time unknown	Date and Hour of Discovery 6/22/2016 1 pm
Was Immediate Notice Given?	If YES, To Whom?	0/22/2010 1 MI
☐ Yes ☐ No ☒ Not Required	N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse. N/A	
☐ Yes ☒ No	N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
IVA		
Describe Cause of Problem and Remedial Action Taken.*		
Leak occurred on the oil circulating steel line in the portion buried in the tank earthen berm. Leak was due to a hole developing in the line due to external corrosion. Line was clamped until section can be repaired.		
Describe Area Affected and Cleanup Action Taken.*		
Leak affected 347 ft ² of caliche within the tank earthen berm. Standing fluids were recovered.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and		
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability		
should their operations have failed to adequately investigate and remedia	te contamination that pose a threat to	ground water, surface water, human health
or the environment, in addition, NMOCD acceptance of a C-141 report of federal, state, or local laws and/or regulations.	loes not relieve the operator of respon	sibility for compliance with any other
reucrai, state, or local laws appror regulations.	OIL CONSER	VATION DIVISION
	<u>OID COINDER</u>	
Signature: wy This		
Printed Name: Amy C. Ruth	Approved by Environmental Speciali	ist: Mrb/UL
Title: EHS Remediation Specialist	Approval Date:	Expiration Date: NA
E-mail Address: ACRuth@basspet.com	Conditions of Approval:	_
Z man / coress. //Cichingpussiper.com	emediation per O.C.D. Rule	s & Guidelinesched

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN:_

Patterson, Heather, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>

Sent: Friday, July 01, 2016 2:47 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Cc: Tucker, Shelly

Subject: JRU 55 Battery 6-22-16 Initial C-141 **Attachments:** Initial C-141 JRU 55 Battery 6-22-16.pdf

Had a spill within the earthen berm at the tank battery due to line corrosion. Spill was contained within the berm and standing fluids were recovered. Please find the attached initial form C-141. Thank you and have a safe holiday ©



Amy C. Ruth

BOPCO, L.P.

EH&S Remediation Specialist 522 W. Mermod, Suite 704 Carlsbad, NM 88220

Office: (575)887-7329 Fax: (575)887-7473 Cell: (432)661-0571