NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 21 2016

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 8, 2011

RECEIVED
Submit I Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NABIUAU736693 OPERATOR 🖂 II											Final Report	
Name of Company: Devon Energy Production Co LP						☐ Initial Report ☐ Final Report Contact: Brian Kuh, Devon Completions Foreman						
(6137) [D]3*/ Address: PO Box 250 Artesia, NM 88211						Telephone No. 575-616-1540						
Facility Nat	ne: (Cotton Drav	v Unit 23	38H	F	Facility Type: Oil Well						
Surface Owner: Federal Mineral Owner:						Federal API No. 30-015-43269					3269	
LOCATION OF RELEASE												
Unit Letter E	Section 13	Township 25S	Range 31E	Feet from the 2560		South Line orth	Feet from the 140	East/West I West		County Eddy		
Latitude: <u>32.145352</u> Longitude: <u>-103.739623</u>												
NATURE OF RELEASE												
Type of Rele	ase: Tre	ated Water				Volume of Release: 8 BBLS			Volume Recovered: 0 BBLS			
Source of Release: Water Transfer Line						Date and Hour of Occurrence 4/26/2016, 9:20 PM			Date and Hour of Discovery 4/26/2016, 9:20 PM			
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? BLM: Jim Amos					
By Whom? Brian Kuh, Devon Completions Foreman						Date and Hour: 4/27/2016, 1:50 PM						
Was a Water	course Reac		Yes 🗵] No		If YES, Volume Impacting the Watercourse. N/A						
If a Watercourse was Impacted, Describe Fully.* N/A												
Describe Cause of Problem and Remedial Action Taken.* A water transfer road crossing line was damaged by possible malicious mischief causing an 8 barrel spill of treated water on the lease road approximately 3220 feet to the north of the Cotton Draw Unit 238H. Line pinchers were applied to both the upstream and downstream lines to isolate the leak and the damaged line and left flange were replaced.												
Describe Area Affected and Cleanup Action Taken.* 8 barrels of treated water were spilled on the lease road and 0 barrels were recovered. The spill ran in a southwest direction covering an approximate 40 foot by 40 foot area. The contaminated soil was placed on a plastic liner to prevent further leakage. An environmental company will be contacted for remediation.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Signature: Doniso Monoud						OIL CONSERVATION DIVISION						
Printed Nam	e: Denis	e Menoud				Approved by Environmental Specialist:						
Title:	Field A	Admin Suppo	ort	A	Approval Date: 912216 Expiration Date: NA							
E-mail Addr	ess: Denise	.Menoud@dv	n.com		q	বিষ্ণাভিষ্ণেরিতিস চুজা O.C.D. Rules & Guidelines						
Date: 4/29/2016 Phone: 575-746-5544 SUBMIT REMEDIATION PROPOSAL NO												
' Attach Addi	Attach Additional Sheets If Necessary LATER THAN: 10/2010 1999-3899											