

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION State of New Mexico
ARTESIA DISTRICT Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

SEP 11 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 11 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

RECEIVED

Release Notification and Corrective Action

NAB1725731304 **OPERATOR** Initial Report Final Report

Name of Company	WPX Energy Inc/RKI 246289	Contact	Karolina Blaney
Address	5315 Buena Vista Dr.	Telephone No.	970 589 0743
Facility Name:	RDX 16-10	Facility Type:	Well Pad

Surface Owner: State Mineral Owner: State API No. 30-015-38292

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	16	26S	30E	330	FNL	2110	FEL	Eddy

Latitude: 32.04897719N Longitude -103.88439621W

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 25 Bbls	Volume Recovered: 25 Bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Tank	8/27/2017	8/27/2017 - 12:30 hrs MT
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	NMOCD Crystal Weaver & Michael Bratcher, SLO - Amber Groves	
By Whom? Karolina Blaney	Date and Hour: 8/28/2017/2017 - 10:40 hrs MT	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.*		
The spill was caused by power outage; water transfer pump stopped working and caused tanks to overflow. Approximately 25 bbls of produced water was spilled into lined SPCC containment. The containment liner was inspected immediately after the spill occurred. Based on the inspection, there is no evidence that the spilled fluids have left the containment.		
Describe Area Affected and Cleanup Action Taken.*		
All spilled fluids were recovered from the lined containment with vacuum trucks and the transfer pump.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Karolina Blaney</i>	OIL CONSERVATION DIVISION	
Printed Name: Karolina Blaney	Approved by Environmental Specialist: <i>Crystal Weaver</i>	
Title: Environmental Specialist	Approval Date: 9/11/17	Expiration Date: NIA
E-mail Address: Karolina.blaney@wpenergy.com	Conditions of Approval: FINAL	
Date: 9/11/17 Phone: 970-589-0743	Attached 246-4385	

* Attach Additional Sheets If Necessary

Alvin...

Weaver, Crystal, EMNRD

From: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>
Sent: Monday, September 11, 2017 1:41 PM
To: Weaver, Crystal, EMNRD; 'agroves@slo.state.nm.us'
Cc: Bratcher, Mike, EMNRD
Subject: RE: WPX/RKI RDX 16-10 - C-141
Attachments: RDX 16-10 - C-141.doc

Good afternoon,
Attached is the initial and final C-141 for the RDX 16-10 spill.
Please let me know if you have any questions or concerns.
Thank you,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Monday, August 28, 2017 10:39 AM
To: 'Weaver, Crystal, EMNRD' <Crystal.Weaver@state.nm.us>; 'agroves@slo.state.nm.us' <agroves@slo.state.nm.us>
Cc: 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>
Subject: WPX/RKI RDX 16-10 - initial spill notification

Good morning,

WPX had a spill yesterday, 8/27/17, at the RDX 16-10 well pad; API 30-015-38292, B-16-26S-30E. The cause of this spill is equipment failure; water transfer pump failed due to power outage which resulted in overfilling a tank by 25 bbls. All fluids were contained inside lined SPCC containment and did not impact the environment.

I will be sending the C-141 report in the next 15 days.
Please let me know if you have any questions or concerns.
Thank you,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com