

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 17 2018

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
DISTRICT II-ARTESIA O.C.D.

Release Notification and Corrective Action

NAB1811339556

OPERATOR

Initial Report Final Report

Name of Company	WPX Energy Inc/RKI * # 246289	Contact	Karolina Blaney
Address	5315 Buena Vista Dr.	Telephone No.	970 589 0743
Facility Name:	RDX 28-9H	Facility Type:	Well Pad

Surface Owner: Federal	Mineral Owner: Federal	API No. 30- 015-43294
------------------------	------------------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	28	26S	30E	360	FNL	1345	FWL	Eddy

Latitude: 32.0195424 N Longitude: -103.8900057W

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 30 Bbls	Volume Recovered: 30 Bbls
Source of Release Tank Battery	Date and Hour of Occurrence 4-8-18	Date and Hour of Discovery 4-8-18 - 10:00 hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Crystal</i> NMOCD Heather Patterson & Michael Bratcher, BLM Shelly Tucker	
By Whom? Karolina Blaney	Date and Hour: 4-9-18 8:12 hrs MT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

The cause is mechanical failure; nipple on a water transfer pump failed due to corrosion which resulted in spilling 30 bbls of produced water inside lined SPCC containment. All fluids were recovered. The containment liner was inspected immediately after the spill occurred. Based on the inspection, there is no evidence that the spilled fluids have left the containment.

Describe Area Affected and Cleanup Action Taken.*

The environment was not impacted by this spill. All fluids were contained inside lined SPCC containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Karolina Blaney</i>	OIL CONSERVATION DIVISION	
Printed Name: Karolina Blaney	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: 4/23/18	Expiration Date: N/A
E-mail Address: Karolina.blaney@wpxenergy.com	Conditions of Approval: <i>Final</i>	Attached: <i>2RP-4711</i>
Date: 4-17-18 Phone: 970-589-0743		

* Attach Additional Sheets If Necessary

Weaver, Crystal, EMNRD

From: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>
Sent: Tuesday, April 17, 2018 9:38 AM
To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD; 'Tucker, Shelly'
Cc: Raley, Jim
Subject: RE: WPX/RKI RDX 28-9 - initial spill notification
Attachments: RDX 28-9 - Final Report C-141.doc

Good morning,

Attached is the initial and final C-141 for the RDX 28-9 spill. All fluids were contained inside lined SPCC containment and the spill did not impact the environment.

Please let me know if you need any additional information.

Thank you and have a great day,

Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Monday, April 09, 2018 8:12 AM
To: 'Weaver, Crystal, EMNRD' <Crystal.Weaver@state.nm.us>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; Tucker, Shelly <stucker@blm.gov>
Cc: Raley, Jim <james.rale@wpxenergy.com>
Subject: WPX/RKI RDX 28-9 - initial spill notification

Good morning,

WPX had a spill yesterday, 4/8/2018, at the RDX 28-9 well pad; API 30-015-43294, C-28-26S-30E. The cause of this spill is equipment failure; nipple on a water transfer pump failed due to corrosion which resulted in spilling 30 bbls of produced water inside lined SPCC containment. All fluids were contained inside lined SPCC containment and did not impact the environment.

I will be sending the C-141 report in the next 15 days.

Please let me know if you have any questions or concerns.

Thank you and have a great day,

Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

Weaver, Crystal, EMNRD

From: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>
Sent: Monday, April 9, 2018 8:12 AM
To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD; Tucker, Shelly
Cc: Raley, Jim
Subject: WPX/RKI RDX 28-9 - initial spill notification

Good morning,

WPX had a spill yesterday, 4/8/2018, at the RDX 28-9 well pad; API 30-015-43294, C-28-26S-30E. The cause of this spill is equipment failure; nipple on a water transfer pump failed due to corrosion which resulted in spilling 30 bbls of produced water inside lined SPCC containment. All fluids were contained inside lined SPCC containment and did not impact the environment.

I will be sending the C-141 report in the next 15 days.

Please let me know if you have any questions or concerns.

Thank you and have a great day,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com