

Bratcher, Mike, EMNRD

From: Lucas Middleton <lucas.middleton@soudermiller.com>
Sent: Monday, July 23, 2018 4:05 PM
To: Bratcher, Mike, EMNRD
Subject: RE: C141- Initial Matador Resources ,MARBOB STATE #001,30-015-26040

Mike,
It was equipment failure NOT illegal dumping . Yes there was one but I have not been able to get the haul tickets yet.
Thank you for clarifying with me.

From: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Sent: Monday, July 23, 2018 1:33 PM
To: Lucas Middleton <lucas.middleton@soudermiller.com>
Cc: rmann@slo.state.nm.us; Casey Snow <CSnow@matadorresources.com>; Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>
Subject: RE: C141- Initial Matador Resources ,MARBOB STATE #001,30-015-26040

Lucas,

In one block of this C-141, it indicates the source of release was illegal dumping. The description of the release indicates equipment failure. Do you know which one is correct? The document also indicates a vac truck was onsite to recover standing fluids, but recovery volume is listed as unknown. We can go with unknown, but just wanted to check.

Thanks,

Mike Bratcher
NMOCD District 2
811 South First Street
Artesia, NM 88210
575-748-1283 Ext 108

From: Lucas Middleton <lucas.middleton@soudermiller.com>
Sent: Monday, July 23, 2018 12:25 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Cc: rmann@slo.state.nm.us
Subject: C141- Initial Matador Resources ,MARBOB STATE #001,30-015-26040

Good Afternoon,
On behalf of Matador Resources, SMA is submitting a C141- Initial for a release that occurred on their location MARBOB STATE #001 , 30-015-26040.
See attached document.

Lucas Middleton
Staff GeoScientist
(575) 499-9244 (mobile)

Bratcher, Mike, EMNRD

From: Lucas Middleton <lucas.middleton@soudermiller.com>
Sent: Monday, July 2, 2018 5:22 PM *
To: Bratcher, Mike, EMNRD
Cc: rmann@slo.state.nm.us
Subject: Initial Release Notifications for Matador Resources

Mike,
Below are two initial release notifications for Matador Resources.

MATADOR PRODUCTION COMPANY

SST #003

API: 30-015-26457

Oil Well

GPS Location: 32.694977°, -104.115822°

Surface Land Owner: State of New Mexico

Cause of Release: Illegal Dump.

Pathway: The illegal dumping affected three well pads, as well as the lease roads associated. No waterways were reached.

Estimated surface release area: 5,114 square yards

Estimated Date of Release: unknown

Date of Discovery : 6/29/18 4:00 p.m.

Estimated Volume loss: unknown

An illegal dumping took place at an unknown time. An environmental firm was called to the location on June 29th, 2018 to assess and delineate the site. It was at this time that the full extent of the dumping was learned

MATADOR PRODUCTION COMPANY

MARBOB STATE #001

API: 30-015-26040

Salt Water Disposal

GPS Location: 32.6518211, -104.1077576

Surface Land Owner: State of New Mexico

Cause of Release: Equipment Failure.

Pathway: The release occurred within the tank battery. Two areas one North and one south allow for the liquid to run over the berm and down in to the pad and pasture. No waterways were reached.

Estimated surface release area: 5,114 square yards

Estimated Date of Release: 7/1/18

Date of Discovery : 7/2/18 7:00 a.m.

Estimated Volume loss: ~127 bbls produced water

Lucas Middleton
Staff GeoScientist
(575) 499-9244 (mobile)



Souder, Miller & Associates