District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Received
Hobbs

Form C-141 Revised October 10, 2003

district Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

	٠.				OP	ERATOR	Ve.	52334	ZI Z Biria	al Report	\boxtimes	Final Report	
Name of Company ConocoPhillips Company						Contact Kenneth N. Andersen							
Address 4001 Penbrook, Odessa, TX 79762-5917						Telephone No. 505.391.3158							
Facility Name MCA Unit Btry # 1						Facility Type Oil and Gas							
Surface Owner BLM Mineral Ov						wner BLM				Lease No LC-029410A			
				LOCA	TIO	N OF REI	LEASE	· !				,	
Unit Letter	Section	Township	Range	Feet from the		h/South Line	Feet from the	East/V	Vest Line	County			
E	29	17S	32E	1395	N		1295	w		Lea			
Latitude 32.81186N Longitude -103.79115W NATURE OF RELEASE													
Type of Release						Volume of Release				Volume Recovered			
Produced Water						90 bbl (0 oil, 90 water)				(0 oil, 80 water)			
Source of Release						Date and Hour of Occurrence				Date and Hour of Discovery			
MCA Btry # 1 4" fiberglass produced water transfere trunk line ~ 400 yrds NNE of MCA # 369.						10/19/04 @ 1330hrs				10/19/04 @ 1400hrs			
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom?							
						Silvia Dickey							
By Whom? Ken Andersen Was a Watercourse Reached?						Date and Hour 10/20/04 @ 1100hrs If YES, Volume Impacting the Watercourse.							
Yes No						Do, voiame ii	inputting the wat		·•	•			
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*													
The spill was caused by the dresser sleave bolts corroding allowing the sleave to come apart and start leaking. The sleave was removed and a collar and flange where installed.													
Describe Area Affected and Cleanup Action Taken.*													
				h no cows pres									
approval at a later date. A remediation plan was submitted and approved. Three feet of top soil was removed as per BLM requirement and hauled to CRI for disposal, and the site was contoured and seeded with BLM # 2 seed and the spill site was closed.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature: Lennett M. Andersen						OIL CONSERVATION DIVISION							
Printed Name: Kenneth N. Andersen						Approved by District Supervisor:							
Title: HSER PSM Lead						Approval Date: 43-06 ENVIKUIVILLA 90-day							
E-mail Address: ken.n.andersen@conocophillips.com						Conditions of Approval: Refart Attached							
Date:		Pho	one: 505.	391.3158	- 1	delivertion of Cl. TAN. BUX							
Attach Additional Sheets If Necessary facility - FPACO61662558 > 100 mident-nPACO616625662 application - PACO616625953 April 922													
Umud	ent	110001	~~~ <u> </u>		401		~ F			KIM	Ide	~	