<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

Release Notification and Corrective Action

						OPERA?	ΓOR	🛛 Initia	al Report	Final Report	
Name of Co	mpany Ch	evron			Contact Wayne Minchew						
Address HO			ton, N.M	1. 88260	Celephone No. 505-396-4414						
Facility Name Central Vacuum Unit Tank Btry. Facility Type Production Btry.											
Surface Owner State of NM Mineral Owner St							State of NM Lease No. 857943				
Surface Owner State of NM Mineral Owner State of NM Lease No. 857943											
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the	North		Feet from the	West Line	County		
E	31	17S	35E	1987			620		Lea		
								<u>L</u>	I		
LatitudeLongitude											
NATURE OF RELEASE											
Type of Release Produced Water Volume of Release 250 Bbls. Volume Recovered 210 Bbls.											
Source of Release 4" Fiberglass water transfer line							Date and Hour of Occurrence Date and Hour of Discovery				
							7/19/2006 7:00 P.M. 7/19/2006 7:30 PM				
Was Immediate Notice Given?						If YES, To Whom?					
							Pat Caperton				
By Whom? Wayne Minchew						Date and Hour 7/20/2006 8:00 A.M.					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
	☐ Yes ☒ No										
If a Watercou	If a Watercourse was Impacted, Describe Fully.*										
									5 2 3 3		
										e Sign	
Describe Cause of Problem and Remedial Action Taken.* Fiberglass line cracked releasing 250 barrels of produced water to btry. yard- Line was shut in and isolated -											
Describe Cause of Problem and Remedial Action Taken.*											
Fiberglass line cracked releasing 250 barrels of produced water to btry. yard- Line was shut in and isolated -											
Describe Cause of Problem and Remedial Action Taken.* Fiberglass line cracked releasing 250 barrels of produced water to btry. yard- Line was shut in and isolated -											
								120	10 m	5/	
Describe Area Affected and Cleanup Action Taken.*											
Btry. yard - Vacuum truck picked up water.											
									C65515 000	3.	
I hereby certi	fy that the	information g	iven above	e is true and comp	lete to th	ne best of my	knowledge and u	inderstand that purs	suant to NMOC	D rules and	
								ctive actions for rel			
								eport" does not rel			
								eat to ground water responsibility for c			
federal, state,											
_ ^						OIL CONSERVATION DIVISION					
Signature: RW Mind											
						Annuary of hy District Supervises					
Printed Name: P. W. Minchew						Approved by District Supervisor:					
Title: Operations Supervisor						Approval Date: Expiration		Date:			
E-mail Address: pminchew@chevron.com						Conditions of Approval:			Attached		
											Date: 7/20/2006 Phone: 396-4414
Attach Addi	tional She	ets If Necess	sary	. 4	1	00 01	000270	07			
KUH	976	ſ	as Pil	tent -	nff	7(° ,(*)Q	208210	8/			
Attach Additional Sheets If Necessary RPH 976 incident - NPACO620837087 application-PPACO620837323											
		\bigcirc	solu	cotion -	n PH	(0000	(0 8 3 73	\sim			
		U	ffin	juiter of) · ·						
			•								