District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action OPERATOR x Initial Report

						OPERATOR x Initial Report					Final Report		
Name of Company Plains Marketing, LP						Contact Car							
Address 5805 East Hwy. 80, Midland, TX 79706						Telephone No. 505-441-0965							
Facility Name Saunders 8" #5						Facility Type 8"Steel Pipeline							
Surface Owner State Of New Mexico Mineral Owner						Lease No.							
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/West Li					
Н	14	148	33E						Lea				
L	L	L		<u>I</u>			<u> </u>						
Latitude_33°06'21.8" Longitude_103°34'47.6"													
NATURE OF RELEASE													
Type of Release Crude Oil							Volume of Release 15barrels Volume Recovered 0 barrels						
Source of Release 8" Steel Pipeline							Date and Hour of Occurrence			Date and Hour of Discovery			
									-04 @ 17:50				
Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Required						10-1-04 @ 15:00 10-1-04 @ 17:50 17					5 >		
Dr. W/hom? Von Dutton							Date and Hour 10.2 04 @ 10:15						
By Whom? Ken Dutton Was a Watercourse Reached?						If YES Volume Impacting the Watercours 2							
☐ Yes ☒ No						Date and Hour 10-2-04 @ 10:15 If YES, Volume Impacting the Watercours OF DUT 2003							
If a Watercov	ree was Im	nacted Decor	he Fully		1			2 1.					
☐ Yes ☑ No If a Watercourse was Impacted, Describe Fully.* Yes ☑ No OCT 2003 Co													
								,	15	OCD	57		
									(c)		3		
Describe Cause of Problem and Remedial Action Taken.* Internal corrosion of the 8" steel pipeline. A line clamp was installed to help the release.													
The line is an 8 inch steel transmission pipeline that produces approximately 1,400 barrels of crude per day. The pressure on the line varies from 25 to 30													
psi and the gravity of the sweet crude oil is 38-42. The sweet crude has an H ₂ S content of less than 10 ppm													
·· · · · · · · · · · · · · · · · · · ·													
,													
Describe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was													
2,220 ft ² .													
				is true and comple									
				d/or file certain re									
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
				tance of a C-141 r									
federal, state,	or local lay	vs and/or regu	lations.	<u></u>					····				
						OIL CONSERVATION DIVISION							
Signature: Camelle Krundas											ļ		
							Approved by District Supervisor:						
Printed Name	: Camille R	eynolds					District Super vist	" Aus	Weller	me			
Title: Remediation Coordinator						Approval Dat	5/2/09	Evaient	ion Date: 6	1.1.			
i inc. Remedi	anon Coor	JIII AIUI				white ar na	<u>0/2-/04</u>	Expirat	IOII Date: 6	121/2	<u>'</u>		
E-mail Addre		ds@paalp.com				Conditions of	Approval: Me	ed fenel	Attache	ed 🔲	i		
Date: 10/4/04				Phone:505-441-09	65	uport	}	0					
Attach Addit	tional Shee	ets If Necess	ary	20 B	7 -	$\sim 1 < 1$	76			_ ,	HAR		
				/ Vassas		ス/()/ ′	υψ			QD)	T110		
					•	l				1/1			