District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			Energy Mi Oil C 1220	nerals Conse Sout	rvation Div	ico ico l Resources visiotig 2007 is Drceived	1011121314151	Form C-14 Revised October 10, 200 Submit 2 Copies to appropriat District Office in accordanc with Rule 116 on bac side of form
میں افغان میں جب ایک افغان میں میں وہ میں اور		1. 17 1896 (P. 4 16		the street to		orrective A	cțion $ ho$	ORRECTER
						FOR 7717.02		al Report [] Final Rep
Name of Company         Centurion Pipeline, LP           Address         2200 East County Road 90 Midland, TX 79706					Contact Be	cky Moore No. 432-686-68		
Facility Name Gladiola Station					Facility Typ	and the second se		
Surface Owner Mr.	Burris		Mineral (	Dwner	•	·····	Lease N	No.
			LOCA	ATIC	N OF REI	LEASE		
Unit Letter Section	Township	Range	Feet from the	Nort	h/South Line	Feet from the	East/West Line	County
5	12-8	38-E	<u> </u>			<u> </u>		Lea
,			Latitude 33*	*18'12	2" Longitud	le <u>103*06'35"</u>	٨	TED DATE
			NAT	UR	E OF REL	EASE	CORRE	ato en
Type of Release Crude Oil					Volume of Release 17 bbls.       Volume Recovered 15 bbls.         Date and Hour of Occurrence       Date and Hour of Discovery			
Source of Release Pipeline					05/17/2007 25/18/07 at 11:18 AM			
Was Immediate Notice Given?					If YES, To Whom? d Larry Johnson (OCD – Hobbs Office) Left Message at 4:44 pm on 5/18/07.			
By Whom? Darrel Lester					Date and Hour 05/18/07 at 4:44 pm			
Was a Watercourse Reached?					If YES, Volume Impacting the Watercourse.			
If a Watercourse was Ir								
	npacted, Desci	ibe runy.						
N/A Describe Cause of Prob	lem and Reme	dial Actio	n Taken *		<u> </u>	<u></u>	<u></u>	Terrent States
occurring failures. The regulatory guidance lin	leak was cont its as outlined	ained with in the NM	in the station proj 10CD Rule 116.	perty.				d in an effort to prevent re- blended on-site within
Describe Area Affected	and Cleanup	Action Ta	ken.*					
to stop the leak and corr contaminated soil. The Information Requested The size of the line = 2 The average throughput H2S is not present at th Est. Age of pipeline = 2	tainment of im e clean up crev inch ball valve t of the line = $4$ is "sweet" crue 2 years.	pacted so vs worked line 2 gallons le oil pipe	ils. A third party through the week per month line station site.	enviro end an	nmental remed d will continue	iation company is working until the	in the process of o site is clean and v	n included immediate response delineating and excavating the work is completed. Additional
regulations all operators public health or the env should their operations	s are required t ironment. The have failed to a addition, NMC	o report and acceptant adequately OCD accept	nd/or file certain r ce of a C-141 repo y investigate and r	elease ort by f emedi	notifications a he NMOCD m ate contaminati	nd perform correct arked as "Final Ration that pose a three	tive actions for rel eport" does not rel eat to ground wate	suant to NMOCD rules and leases which may endanger lieve the operator of liability er, surface water, human health compliance with any other
Signature: RAMOOR					OIL CONSERVATION DIVISION Approved by District Supervisor:			
Printed Name: Becky Moore					ENVIRONMENTAL ENGINEER			
Title: HES/Regulatory Compliance Coordinator					Approval Date: 9.26.07 Expiration Date:			
E-mail Address: Rebec	ca_Moore@o>	y.com			Conditions of	f Approval:		Attached 🛛
Date: 05/18/07 (Re-vis	ed on 8/03/07)		Phone: 432-686-	6805				Autonou M
Attach Additional Ch	ate If Masses	~				17	P# 13	53

August 3, 2007

Mr. Larry Johnson Environmental Engineer New Mexico Oil Conservation Division 1625 North French Hobbs, New Mexico 88240

Subject: C-141 <u>Revised Initial Submittal</u> Centurion LMEP # 308-07-025

Re: Centurion Pipeline, LP Gladiola Station Sec 5, T-12-S, R-38-E Lea County, New Mexico

Dear Mr. Johnson:

Centurion Pipeline, L.P. (Centurion) previously submitted this attached initial C-141 for the above referenced leak site located on land owned by Mr. Burris.

We inadvertently put the wrong date of the leak on the initial report. Please accept this revised submittal showing the correct date of the leak as 5/18/07.

If you have any questions or need additional information, please call me at (432) 978-8067.

Sincerely, Centurion Pipeline, LP

loore

HES/Regulatory Compliance Coordinator

