


FRED POOL DRILLING, INC.



P.O. Box 1393

Roswell, New Mexico 88201

April 18, 1988

Mr. David Catanach, Engineer
State of New Mexico
Oil Conservation Division
P. O. Box 2088
Santa Fe, NM 87504-2088

RE: P.J. "A" State #9
2420' FWL & 1470' FSL, Sec. 1, T19S, R29E, Eddy County, NM

Mr. Catanach;

Please accept our apologies for two mistakes that were made in our letter dated March 17, 1988 in regards to the above referenced well.

- 1) The location, after being surveyed by Dan Reddy, is 2420' FWL & 1470' FSL, not 1650' FSL as stated.
- 2) Herman J. Ledbetter is the offset operator, not Tenneco Oil Co., as stated in our letter.

We have notified Mr. Ledbetter of our intentions, when I receive a waiver back from him I will forward it to you. I have also enclosed a plat showing the lease ownerships, ie. offset operator.

Once again I am sorry for the confusion this may have caused, and I hope this will straighten out the matter.

Sincerely

Fred F. Pool, III
Engineer

Encl. - 1

FFP/deb

<p>19</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>19</p>	<p>20</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>20</p>	<p>21</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>21</p>	<p>22</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>22</p>	<p>23</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>23</p>	<p>24</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>24</p>	<p>25</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>25</p>	<p>26</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>26</p>	<p>27</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>27</p>	<p>28</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>28</p>	<p>29</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>29</p>	<p>30</p> <p>So Roy (Removal) 1944 L 2413 2355 1341</p> <p>NZ HBC 1944 78 L 1513 1513 55 55</p> <p>Marble Inc. 1944 78 L 1513 1513 55 55</p> <p>30</p>
--	--	--	--	--	--	--	--	--	--	--	--