

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

October 24, 2007

Devon Energy Production Co., L.P.

PO Box 250

Artesia, NM 88210

ATTN: Jerry Mathews, Production Foreman

Reference: North Pure Gold 9 #1 (30-015-27178)


Dear Mr. Mathews

I have received your work plan for the release on this well and will accept this plan of action with one stipulation.

Soils/wastes within and beneath the area of the leak, spill or release should be evaluated to determine the type and extent of contamination at the site. In order to assess the level of contamination, observations should be made of the soils at the surface and samples of the impacted soils should be taken in the leak, spill or release area. Observations should note whether previous leaks, spills or releases have occurred at the site. Additional samples may be required to completely define the lateral and vertical extent of contamination. Soil samples should be obtained according to the sampling procedures in Sections V.A. and V.B. This may be accomplished using a backhoe, drill rig, hand auger, shovel or other means.

After laboratory analysis of the samples, the results must be submitted to OCD for approval prior to back filling the release area.

Respectfully,


Gerry Guye
Compliance Officer
NMOCD District II, Artesia
(505) 748-1283 ext 105
Cell (505) 626-0843

e-mail: gerry.guye@state.nm.us



ENERGY PRODUCTION COMPANY, L.P.

P. O. Box 250
Artesia, New Mexico 88210

Telephone: (505) 748-3371
Fax: (505) 746-9072



OCT 23 2007
OCD-ARTESIA

State of New Mexico
Oil Conservation Division
Attn: Mr. Gerry Guye
1301 W. Grand
Artesia, NM 88210

Re: North Pure Gold 9 #1
Sec. 9, T23S, R31E
Eddy County, NM

Dear Mr. Guye:

Attached please find a plan of action/clean up schedule that we are submitting to you for your approval on the North Pure Gold #9.

At your approval work will commence on this cleanup, we will follow up with a C-141 for your final approval when the work is completed.

Respectfully,

Gerry Mathews
Production Foreman
Devon Energy Production Co., LP
Cell: (575) 748-5234

JM/av
Attachment

OCT 23 2007
OCD-ARTESIA

October 22, 2007

Devon Energy
Attn. Jerry Mathews
Artesia, NM 88211RE: North Pure Gold #1
Unit Letter N Sec 9-T236-R31E

Clean up schedule

1. APSI to complete "one-call"
 - a. Spot all lines, piping and electrical. Work will begin when all lines are spotted
2. Dig out one (1) foot of soil. Approximately 30 to 35 yards inside the containment wall at tank battery
3. Replace with clean soil
4. Haul removed soil to CRI landfill

Devon Energy representative will sign upon completion of all work

Signature/Print name_____
Date

If you have any questions please contact me at (432) 202-0957 or Shawn McCormick (505) 746-7803

Thank you,

Rusty Adams
Remediation Supervisor
American Production Services, Inc.

PO Box 11061 Artesia, NM 88210 * Phone (505) 746 1096 * Fax (505) 746.3530 * Tollfree (877) 879.8899

PO Box 12874 * Odessa, TX 79768 * Phone (432) 552 7625 * Fax (432) 303 0198

email americanisafety@earthlink.net