

Jones, William V., EMNRD

From: Jones, William V., EMNRD
Sent: Friday, December 28, 2007 4:15 PM
To: 'tripp@nikaenergy.com'
Cc: Ezeanyim, Richard, EMNRD
Subject: FW: Plastic Coated Tubing

Tripp:

I will issue an amended or corrected order - basically giving the option to require additional tests and no plastic coating up to our Aztec office.

William V. Jones PE
New Mexico Oil Conservation Division
1220 South St. Francis
Santa Fe, NM 87505
505-476-3448

From: Perrin, Charlie, EMNRD
Sent: Friday, December 28, 2007 3:45 PM
To: Jones, William V., EMNRD; Villanueva, Enriques, EMNRD
Subject: RE: Plastic Coated Tubing

Will

Annual test will be fine for the first few years,
please leave it up to the district to make the exception

thanks
Charlie

12/28/2007

Jones, William V., EMNRD

From: Jones, William V., EMNRD
Sent: Friday, December 28, 2007 3:15 PM
To: 'tripp schwab'
Subject: RE: UIC Permit

Tripp:
Am running this by Charlie in Aztec - he or I will get back to you.

William V. Jones PE
New Mexico Oil Conservation Division
1220 South St. Francis
Santa Fe, NM 87505
505-476-3448

From: tripp schwab [mailto:tripp@nikaenergy.com]
Sent: Friday, December 28, 2007 12:58 PM
To: Jones, William V., EMNRD
Subject: UIC Permit

William,
I received the injection permit. Thank you for all your help. As a condition of the permit I saw that internally plastic coated tubing was required.
May we use a non-coated tubing in this well or is plastic coated tubing an "absolute" condition of this permit. We are currently drilling the well and I have a completion rig lined up for the 2nd week of January. The coaters are backed up several weeks. I plan to use new 3-1/2" J-55 tubing in order to reduce friction, which we have seen to be a problem with CO2 tainted water. We always have had an aggressive corrosion control program in place and intend to on this well, as well as bactericide treatments of the surface tankage, piping, etc.
Any help in this would be greatly appreciated.

Tripp Schwab
Nika Energy, LLC.
Box 2677
Durango, CO 81302
970.259.2701 office
970.385.1598 fax

This inbound email has been scanned by the MessageLabs Email Security System.

12/28/2007