Form 3160-5			0.05		
	UNITED STATE PARTMENT OF THE I EAU OF LAND MAN	NTERIOR	9CD-AR7 JUN - 2 200	ESIA Lease Serial No. LC 029303C	FORM APPROVED OMB No 1004-0137 Expires March 31, 2007
SUNDRY N Do not use this f	NOTICES AND REPO form for proposals t Use Form 3160-3 (A	ORTS ON WELLS	S nter an	LC 029303C 6 If Indian, Allot	
	T IN TRIPLICATE – Other	instructions on page	2.		Agreement, Name and/or No art Queen Sand Unit
1 Type of Well I Type of Well I Gas Well	Vell Other			8. Well Name and VS Unit #106	l No
2 Name of Operator COG OPERATING				9. API Well No. 30-015-05576	
3a Address 550 W Texas, Ste 1300 Midland, TX 79701		3b Phone No <i>(inclua</i> (432) 686-3021	le area code)	10. Field and Poo Shugart Y.SR.	l or Exploratory Area Q.G.
4 Location of Well (Footage, Sec., T., A 660 North 660 East Sec 17, 18S, 31E	R., M., or Survey Description,			11. Country or Pa EDDY CO.	rish, State
12. CHEC	CK THE APPROPRIATE BO	X(ES) TO INDICATE	NATURE OF NOT	CE, REPORT OR C	DTHER DATA
TYPE OF SUBMISSION	-)	TYPE OF AC	TION	
Notice of Intent	Acidize	Deepen Fracture Trea		duction (Start/Resum lamation	e) Water Shut-Off Well Integrity
Subsequent Report	Casing Repair	New Constru	=	omplete	Other
Final Abandonment Notice	Convert to Injection	Plug Back	Wa	er Disposal	
1) Set CIBP @ 2,925'. Cap w/ 25s	x cmt	fill in		0	
5) Perf & Sqz 60sx cmt @ 650' - 55	1,740'. WOC-Tag. DC-Tag. 50'. WOC-Tag.	5. Not	Needed		·
3) Perf & Sqz 40 sx cmt @ 1,840' - ✦4) Tbg to 830'. Spot 40sx cmt. WC ✦5) Perf & Sqz 60sx cmt @ 650' - 55	1,740'. WOC-Tag. DC-Tag. 50'. WOC-Tag.	5. Not	Needed	6" (sg mt to to sa, SEE/	2 100 Squeeze circ. all annulu Fax. ATTACHED FOR
3) Perf & Sqz 40 sx cmt @ 1,840' - €4) Tbg to 830'. Spot 40sx cmt. WC 5) Perf & Sqz 60sx cmt @ 650' - 55 6) Perf & Sqz 30sx cmt @ 100' - su 100' - su ★ See Attached	1,740'. WOC-Tag. DC-Tag. 50'. WOC-Tag. Irface.	5. Not	Needed 7° ± 85 iguate c cll bore	6" (sg mt to to sa, SEE/	2 100 Squeeze circ. all annulu Fax. ATTACHED FOR
3) Perf & Sqz 40 sx cmt @ 1,840' - ✦4) Tbg to 830'. Spot 40sx cmt. WC ✦5) Perf & Sqz 60sx cmt @ 650' - 55	1,740'. WOC-Tag. DC-Tag. 50'. WOC-Tag. Irface.	5. Not 6. fert wo(ad and w	Needed 7° ± 85 iguate c cll bore	6" (sg mt to to sa, SEE/	2 100 Squeeze circ. all annulu Fax. ATTACHED FOR
 3) Perf & Sqz 40 sx cmt @ 1,840' - 4) Tbg to 830'. Spot 40sx cmt. WC 5) Perf & Sqz 60sx cmt @ 650' - 55 6) Perf & Sqz 30sx cmt @ 100' - su 4) Thereby certify that the foregoing is the Name (Printed/Typed) 	1,740'. WOC-Tag. DC-Tag. 50'. WOC-Tag. Irface.	5. Not 6. fert w(ad and w on Proced	Needed 7° ± 85 equate c ell bore	6" (sg mt to to sa, SEE/	2 100 Squeeze circ. all annulu Face.
3) Perf & Sqz 40 sx cmt @ 1,840' - 4) Tbg to 830'. Spot 40sx cmt. WC 5) Perf & Sqz 60sx cmt @ 650' - 55 6) Perf & Sqz 30sx cmt @ 100' - su 16) Perf & Sqz 30sx cmt @ 100' - su 14 I hereby certify that the foregoing is the Name (Printed Typed) Gary Eggleston	1,740'. WOC-Tag. DC-Tag. 50'. WOC-Tag. Irface. Irrue and correct	5. Not 6. fert w(ad and w on Proced	Needed 7° ± 85 equate ell Dore P&A Supervisor 05/21/2009	6" (sg mt to to sa, SEE / CONI	
3) Perf & Sqz 40 sx cmt @ 1,840' - 4) Tbg to 830'. Spot 40sx cmt. WC 5) Perf & Sqz 60sx cmt @ 650' - 55 6) Perf & Sqz 30sx cmt @ 100' - su 16) Perf & Sqz 30sx cmt @ 100' - su 14 I hereby certify that the foregoing is the Name (Printed Typed) Gary Eggleston	1,740'. WOC-Tag. DC-Tag. 50'. WOC-Tag. Irface. Irrue and correct	5. Not 6. ferf wo(ad and wo on Procee Title Date FOR FEDERAL	Needed 7° ± 85 Guert C ell Borc P&A Supervisor 05/21/2009 OR STATE OF	6" (sg mt to to sa, SEE / CONI	2 100 Squeeze circ. all annulu Face. ATTACHED FOR DITIONS OF APPROVAL
3) Perf & Sqz 40 sx cmt @ 1,840' - 4) Tbg to 830'. Spot 40sx cmt. WC 5) Perf & Sqz 60sx cmt @ 650' - 55 6) Perf & Sqz 30sx cmt @ 100' - su 14 I hereby certify that the foregoing is the Name (Printed/Typed) Gary Eggleston Signature	1,740'. WOC-Tag. DC-Tag. 50'. WOC-Tag. Inface. Recland: rue and correct THIS SPACE d Approval of this notice does itle to those rights in the subject thereon	5. Not 6. ferf 10 (ad and 10 Title Date FOR FEDERAL	Needed 7° ± 85 Gunt 6 ell Dorc P&A Supervisor 05/21/2009 OR STATE OF Fitle Office	fice use	DITIONS OF APPROVED

٠		- 11 M	11 1 1	TT 17 17121 11	,					地 ママイ/ ママロ
05/14/2007 17:15 IFAX fax@cl	laytonwilliams	.con				→ ਸ	oward,	Down	171	008/007
04/23/2007 14:41 505393			-8	NRD-0 6	D	- 11	onara,	рамд		05/07
Before				•	•					
PLUGEING & ABANDA		ngingu			() STR	nin rs				•
t for a constant of the state o	operato	(2)	11	la D	Pornt	ine			•	,
	I LEASENIAL	E Pa	næ	SCO -	ihu an Weil	1.7	Licent	5ANO	chit	
			6mm20 6	20.0	WHED		_00	<u>Compose</u>	* 7	
	8ect From		"N#	VN Bi	CONSTRUCTION OF	RNG Erw L	ferenza series			
	TD:		29 (1794)	FOR	MANTON	[<i>6</i> 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
	PBTD:			FOR	MATION	I Ø FB	D.			
	A A A A A A A A A A A A A A A A A A A	TSIZE	T		100			989		
	SURFACE		┢╴			1400-1000			,	
	INTIMED 1		Ĺ							
	INTMED 2								`•	
	PROP	1 SIZE	ļ.,	TOP	FOT	1922	DETADLA			
	LINERT	1 OILE	-			<u>han</u>		Real of the second		1
	· LINER 2				1					
O.G.		CUT A	PUL	LQ		TO	? - 190	TTOR		
	85/8 INTMED 1				PIZEOTE		<u>م</u>			
TOC 50 5/5	INTIMED 2	PROD								
· · ·	· ADDITED FO	1 AST DE0726	CFR		a to the company					
	STAR BRANCTON	I	e	800	TYPE	SACO	DEM	fiz I		
	141113				nuito -	.	·			
		<u></u>		COLLENS					i	1
	CIAVIDO CIAVIDO	<u> </u>		725061 98350/8	OH DROS	25 558 59 558	990 07094	Station of the local division of the local d	•	
				FLORGED	CERAF		SIQ		1	i
	CARCELLINGOT		ø	746993	<u>Canp</u>	25.203	509	Ø I		
				rebosa	<u>A</u> TUR	MB	44947-1	Contraction of the local division of the loc		
				100000	STAR AND	20152			•	
	CENTERCUNAS					1993	<u> </u>			
	EXPRESSION		1000	135002						•
<i>1</i> 7 <i>K</i>	-06257.535			775533					•	. •
			6	FIC208				- <u>-</u>		
TOC IR AS				nieros 197990				<u> </u>	•	
				110007					4	:
-				FEROUS				i	:	3
•	420			1965 3 99						
				FLATIO FO						
	Nicel			190010 190010						
-	mert ·									
	Accessa						-			
TD <u>3/87</u>							a]	•	
	60,000				•				. rai	7
	i de sa								変換調査	

·

.

••

.

· · ·

", "4

			נויט ענויט							변 년 년 년 년 년 년 년 년 년 년 년 년 년 년 년 년 년 년 년
05/14/2007 17:			. com	en ci	RB-SCD		→ Нот	vard. Dawn		006/007 86/87
• • •		0720			-9-9-9	و سیز اور خدید است. م			PHOL	10100
$\neq A$	ter									
Pluggn	g & Abando	NUZENT WY	irksh	es.	5_1	(), STRE	ng Can	10) ·	• •	
		OPERATO	<u> </u>	6	OPer !	Atil 5		-	•	
		· LEASENAG			1	White			•	
.'	14+342	68277		TW	2.1		CALCA "	<u>IN</u> e		
3	OSISCAN	8ect From		'NIS	L		en l	and the second sec		
11	ort + Ser z orxs cul por tosorture	TD:	College Street	,	FOR	MATION	an.	Part of the second second		
		PBTD:			FOR	HATION	0 P8)	D.		
	(Calculation of the second s		رواندهم			C. C			
			SIZE	8	et (e)	100	TOCIDED	ULCROOD BY		
		SURFACE							•	
		INTMED 2	1						•	
I L P	it + Saiz:	PROD								
6	05x5 (mt		SIZE		OP	BOT	TOC	DIDENDED IN		
ATTL.C	50.72550	LINER 1			ا الماصل بي محمد الن					
	ESOCATIN'	· LINER 2	CUTAI	<u>जता</u>				- BOTTOM		
CONT	55/5	INTIMED 1	<u>pural</u>	-UL	- 94	PIZEOTS				
To ha	O SAN	INTMED 2				CROSSER	l	\$		
HTAQ T	0C 50315	PROD						·		
	,	ANGLOOK	tor death		po los constantes	10,213 CR 10,213				
`		THE REAL PROPERTY.		Ø	8200	TIRE	SACKS	Denta		
		1000			CUM62.EI	FLUED .	1.79492		:	
					7217961	09	25505	5.50	1	ł
			1		20000'E	503	1988	STOP LING	1	:
0.	f + 5gz 40 x5 187061740 Det Thg				<u>TUMA</u>	COROF		<u>sist</u> .	i	é
Per les	15 19 40 61740	ever and the second			R16361	CERP	25.228	\$565	(
wi	CETAG		<u> </u>		schoose		69803	4995-5705 893	:	
	5				20000	STAR 400	201528	0.10°		
M	ISCIAT 20-57 -	Camprounds	+				1 CX FOR	and the second	ļ	•
122220 cil	SCINT 29 572 252 P 29 25	Electronices			6735 (P B					
	1711	263/5/011	1		740783				•	. •
	gineine sector				144964	<u> </u>				
م له	<u>0.3025</u> .		<u> </u>		FLEDOB	<u> </u>	+			•
ų,	VY_HO		+		110060	1	+	· ·		<u>t</u> :
	-		1		FEDSEC		1.	i		
		458	T]	110000	L				
•				STREET, STREET	RESIDES		1			
					FILTO D	1	<u> </u>			
			1		<u>19906</u>					
		ATERA	1							
	ZIOM	5411557		ļ						••
	D <u>3/87</u>		1			<u> </u>	-			·.
	_	<u> </u>		Į.		1	-			
- Inder the Long of the second second second second		1 Denterman	ul.	Л	L.		dun di sur	the second starting to the	2.40	

*,

.

. .

•

•. 9

.

· · ·

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed prior to commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration ... conditions of approval will be developed and furnished to you.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E Greene St Carlsbad, New Mexico 88220-6292 www blm gov/nm



In Reply Refer To 1310

Reclamation (Interim/Final) Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of . Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Terry Gregston Environmental Protection Specialist 575,234-5958

Bobby Ballard Environmental Protection Specialist 575-234-2230

Randy Rust Environmental Protection Specialist 575-234-5943

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Justin Frye Environmental Protection Specialist 575-234-5922 Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Doug Hoag Civil Engineering Technician 575-234-5979