# STATE OF NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT OIL CONSERVATION DIVISION

# CASE NO. 13713 ORDER NO. R-12572

APPLICATION OF THE NEW MEXICO OIL CONSERVATION DIVISION FOR AN ORDER REQUIRING THE ESTATE OF REUBEN F. MOMSEN TO PLUG ONE WELL AND ORDERING A FORFEITURE OF APPLICABLE FINANCIAL ASSURANCE IN EVENT OF OPERATOR'S NON-COMPLIANCE, EDDY COUNTY, NEW MEXICO.

## **ORDER OF THE DIVISION**

#### **BY THE DIVISION:**

This case came on for hearing at 8:15 a.m. on June 8, 2006, at Santa Fe, New Mexico, before Examiner William V. Jones.

NOW, on this 21<sup>st</sup> day of June, 2006, the Oil Conservation Division ("Division") Director, having considered the testimony, the record, and the recommendations of the Examiner,

## FINDS THAT:

(1) Due public notice has been given, and the Division has jurisdiction of this case and its subject matter.

(2) The Division seeks an order requiring The Estate of Reuben F. Momsen ("operator") to plug and abandon the following well in accordance with 19.15.4.201 NMAC by a date certain, and in the event of non-compliance, authorizing the Division to plug the well in accordance with a Division-approved plugging program, to forfeit any applicable financial assurance, and to take the necessary and appropriate measures to recover from the operator any costs of plugging the subject well in excess of the amount of the applicable financial assurance:

Well_Name	API	Location
North State Well No. 1	30-015-00931	Unit G, Section 23, T18S, R27E
	Eddy Count	y, New Mexico

(3) In accordance with the provisions of 19.15.14.1207 NMAC, notice of this hearing was mailed to the address of record of the operator and to the surety company. No party other than the applicant entered an appearance or was present at the hearing.

49

- (4) The evidence presented by the Division demonstrates that:
  - a) the last operator of record for the subject well is The Estate of Reuben F. Momsen;
  - b) the operator has posted a \$5,000 one-well surety bond (number A-E-71334-40) issued by American Employers Insurance Company;
  - c) the subject well has been inactive for a period in excess of one year plus 90 days;
  - d) the well was never approved for temporary abandonment in accordance with 19.15.4.203 NMAC; and
  - e) the well has not been permanently plugged and abandoned in accordance with 19.15.4.202 NMAC;

(5) The Estate of Reuben F. Momsen should be formally required to plug and abandon this well in accordance with 19.15.4.202 NMAC on or before August 1, 2006.

(6) Should The Estate of Reuben F. Momsen not meet this August 1, 2006 compliance deadline, the Division Director should then be authorized to (i) plug and abandon the subject well in accordance with Division-approved plugging programs, (ii) forfeit the applicable financial surety for plug and abandonment costs, and (iii) take necessary and appropriate measures to recover from the operator any costs of plugging the subject well in excess of the amount of the applicable financial assurance.

## **IT IS THEREFORE ORDERED THAT:**

(1) The Estate of Reuben F. Momsen ("operator") is hereby directed to plug and abandon the following well in accordance with 19.15.4.202 NMAC on or before August 1, 2006:

Well Name	API	Location
North State Well No. 1	30-015-00931	Unit G, Section 23, T18S, R27E
	Eddy County	y, New Mexico

(2) Prior to beginning work on this well, the operator shall obtain approval for any such work from the supervisor of the Division's district office in Artesia and shall notify the Artesia District Office of the date and time this work is to commence so the Division may witness the work.

(3) In the event the operator fails to plug this well as directed above, then:


a) the Division is authorized to plug and abandon the subject well and reclaim the well location;

b) the Division is authorized to forfeit any applicable financial assurance for plug and abandonment and reclamation costs; and

c) the Division is authorized to take necessary and appropriate measures to recover from the operator any costs of plugging the subject well and costs of cleanup of the well site in excess of the amount of any applicable financial assurance.

(4) Jurisdiction of this case is retained for the entry of such further orders as the Division may deem necessary.

DONE at Santa Fe, New Mexico, on the day and year hereinabove designated.



STATE OF NEW MEXICO OIL CONSERVATION DIVISION 2/2/2

MARK E. FESMIRE, P.E. Director (are 13713

# Inactive Well List

Total Well Count:1 Inactive Well Count:1 Since:3/25/2006

District	Well	ULSTR	OCD Unit	OGRID	Operator	Lease Type	Well Type	Last Production	Formation/Notes Status	Ðaγs in TA
2 30-015-00931	NORTH STATE #001	G-23-18S-27E	G	19092	REUBEN F MONSEN	s	0	05/1987		_
(	#001				HONSEN			1		

http://www.emnrd.state.nm.us/OCD/OCDPermitting/Report/Stats/InactiveWellList.aspx?P... 6/18/2007

8-Jun-0	7	Well In	spection	n History			
.PI Numb	er: 30-015-00931-00	)-00 Well	Name & No.:	NORTH STAT	E		
Operate	or: REUBEN F MON	ISEN,	District:	ARTESIA	County Na	ame: EDDY	
Fie	d: NORTH STATE		Legal:	S: 23 T: 18S	R: 27E		
Well ⊺yp	De: OIL (PRODUCIN	IG)					
nsp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
/13/2006	Routine/Periodic	Normal Routine Activity	iCLB060443	337	212		
	Well is reportedly an orpl	han well. Location is in fair shape	(tank batterv h	as verv heavv hist	oric hardpan con	tamination aro	und tank bases
	Location is becoming over	han well. Location is in fair shape er grown. PJ attached to rod in ho ohan well status, no new violation Normal Routine Activity	ole, power and b	pelts on motor, pol			
/11/2003	Location is becoming over closed in 2003 due to orp	er grown. PJ attached to rod in ho ohan well status, no new violation Normal Routine Activity	ole, power and b opened.	pelts on motor, pol	ish rod is dull, pu		
/11/2003	Location is becoming over closed in 2003 due to orp Compliance Verification	er grown. PJ attached to rod in ho ohan well status, no new violation Normal Routine Activity	ole, power and b opened.	pelts on motor, pol 46	ish rod is dull, pu		
/11/2003 /17/2003	Location is becoming over closed in 2003 due to orp Compliance Verification No action taken to bring v Routine/Periodic	er grown. PJ attached to rod in ho ohan well status, no new violation Normal Routine Activity well into compliance.	ble, power and b opened. iGEG03223 iMLB031073	pelts on motor, pol 46 391	ish rod is dull, pu 209 211	ılleys rusted. F Y	
/11/2003 /17/2003	Location is becoming over closed in 2003 due to orp Compliance Verification No action taken to bring v Routine/Periodic	er grown. PJ attached to rod in ho ohan well status, no new violation Normal Routine Activity well into compliance. Normal Routine Activity	ble, power and b opened. iGEG03223 iMLB031073	pelts on motor, pol 46 391 prted 5/87. Idle we	ish rod is dull, pu 209 211	ılleys rusted. F Y	
/11/2003 /17/2003 0/5/1999	Location is becoming over closed in 2003 due to orp Compliance Verification No action taken to bring Routine/Periodic Well appears idle. Electric Routine/Periodic	er grown. PJ attached to rod in ho ohan well status, no new violation Normal Routine Activity well into compliance. Normal Routine Activity ic meter has been removed. Last	iGEG03223 iMLB03107 production repo	pelts on motor, pol 46 391 prted 5/87. Idle we	ish rod is dull, pu 209 211 II. Violation Rule	ılleys rusted. F Y	
/11/2003 /17/2003 0/5/1999	Location is becoming over closed in 2003 due to orp Compliance Verification No action taken to bring Routine/Periodic Well appears idle. Electric Routine/Periodic	er grown. PJ attached to rod in ho ohan well status, no new violation Normal Routine Activity well into compliance. Normal Routine Activity ic meter has been removed. Last Status Check	iGEG03223 iMLB03107 production repo	pelts on motor, pol 46 391 prted 5/87. Idle we 87a	ish rod is dull, pu 209 211 II. Violation Rule	ılleys rusted. F Y	

:

Total Inspections Performed: 5

**1**D

ł