

Warnell, Terry G, EMNRD

From: Richard Prentice [RPrentice@conchoresources.com]
Sent: Tuesday, June 08, 2010 7:27 AM
To: Warnell, Terry G, EMNRD
Subject: Jenkins B WFX-861 Revision
Attachments: Jenkins B Federal # 15 Wellbore diagram.xls; Jenkins B Federal # 11 Wellbore diagram.xls

Terry,

I discovered yesterday that the well bore schematics that I used to apply for the injection permits on the Jenkins B #11 and #15 incorrectly listed the existing perfs. Therefore, the requested injection interval did not include all of the existing Yeso perfs. Here is a summary of the mistake:

	Requested & Approved Interval	Existing Yeso Perfs
Jenkins B #11	4,418'-4,666'	4,259'-4,632'
Jenkins B #15	4,312'-4,716'	4,272'-4,686'

Attached are the corrected well bore schematics.

Dick Prentice
Reservoir Engineer

COG OPERATING LLC
550 W. Texas Avenue, Suite 100
Midland, Texas 79701
p.432.685.4341
f.432.685.4398



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.