


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company COG OPERATING LLC 229/37 Contact Pat Ellis
Address 550 W. Texas, Suite 100, Midland, TX 79701 Telephone No. 432-230-0077
Facility Name Harper State #10 Facility Type Flowline

Surface Owner State _____ Mineral Owner _____ Lease No. (API#) 30-015-34870

LOCATION OF RELEASE

Unit Letter <u>P</u>	Section <u>16</u>	Township <u>17S</u>	Range <u>30E</u>	Feet from the	North/South Line	Feet from the	East/West Line	County <u>Eddy</u>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude 32 49.741 Longitude 103 58.142

NATURE OF RELEASE

Type of Release <u>Produced fluid</u>	Volume of Release <u>10bbls</u>	Volume Recovered <u>0bbls</u>
Source of Release <u>Flowline</u>	Date and Hour of Occurrence <u>02/07/2011</u>	Date and Hour of Discovery <u>02/07/2011 1:30 p.m.</u>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Steel flowline spilt due to freezing temperatures. The split joint of flowline has been replaced with a new one and returned to service.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbls of produced fluid was released from the split Harper State #10 flowline located behind the Harper State Tank Battery. The fluid traveled 10' x 50' outside of the facility dike walls. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Josh Russo

Title: HSE Coordinator

E-mail Address: jrusso@conchoresources.com

Date: 02/16/2011 Phone: 432-212-2399

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Approval Date: 3/3/11

Expiration Date:

Conditions of Approval:
Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION**

Attached ☐

PROPOSAL NOT LATER THAN:

4/3/11

2 RP-609

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Friday, February 18, 2011 1:17 PM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis; Tavaréz, Ike; Dorey, Kim; tom.k.franklin@tetrattech.com
Subject: C-141 - Harper State #10 flowline
Attachments: HARPER STATE #10 FLOWLINE -- DATE OF RELEASE -- 02-07-2011.PDF

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred on 02/07/2011 behind our Harper State Tank Battery.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.