

Bratcher, Mike, EMNRD

From: Alan & Cheryl [ahowell@pvtnetworks.net]
Sent: Thursday, November 19, 2009 5:38 PM
To: Bratcher, Mike, EMNRD
Subject: Routh Deep SWD #2
Attachments: 11-10-09_1519.jpg; 11-10-09_1523.jpg; 11-10-09_1522.jpg; 11-10-09_1524.jpg; 11-10-09_1530.jpg; 11-10-09_1527.jpg


Hi Mike,



Here are some pictures from the day of the leak. When we arrived one vacuum truck was leaving and they were moving contaminated soil into the fenced area so the cows could not get into it. Fluid was standing on the ground in the pasture, the road, the location, etc. I don't have any good pictures of the pasture so I attached what I have. I will send some more pictures in another email.



Thanks Again,

Cheryl

This inbound email has been scanned for malicious software and transmitted safely to you using Webroot Email Security.







Bratcher, Mike, EMNRD

From: Alan & Cheryl [ahowell@pvtnetworks.net]
Sent: Friday, November 20, 2009 6:41 AM
To: Bratcher, Mike, EMNRD
Subject: After Clean up Routh
Attachments: Routh SWD Leak 001.jpg; Routh SWD Leak 003.jpg; Routh SWD Leak 004.jpg; Routh SWD Leak 007.jpg; Routh SWD Leak 010.jpg; Routh SWD Leak 018.jpg

Mike,

This was returned by your system so I removed some of the pictures. Please call me after you have reviewed. 703-6159

Thanks Again,

Cheryl

----- Original Message -----

From: Alan & Cheryl
To: mike.bratcher@state.nm.us
Sent: Thursday, November 19, 2009 5:47 PM
Subject: Routh

Mike,

Here are some pictures I took yesterday. I could not get a good picture of the shimmer on the surface.

Cheryl

This inbound email has been scanned for malicious software and transmitted safely to you using Webroot Email Security.

