

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 748-1471

OIL CONSERVATION DIVISION
RECEIVED
93 FEB 15 AM 9 02
S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

February 10, 1993

State of New Mexico
Oil Conservation Division
P.O. Box 2088
Santa Fe, NM 87501

Attention: Mr. Ben Stone

Re: Shooting Star "AEA" State #1
SWD-498

Dear Mr. Stone:

Yates Petroleum Corporation respectfully requests your approval to amend SWD-498 to extend the perforated interval within the Bone Spring formation. The Order currently authorizes perforations from 8134 feet to 8555 feet. We are requesting authorization to perforate from 6945 to 8742, which is still within the Bone Spring formation.

I contacted Mitchell Energy, the only other operator within one-half mile of the Shooting Star SWD. Mr. Dan Tuffley, engineer, had no objection to the amendment. Mitchell's well, the State "JR" #1, located in P-11-18S-35E, Lea County, has its cement top at 6406 feet.

Thank you for your consideration in this matter.

Sincerely yours,

James S. Brown
Operations Engineer Manager

JB/sj

XC: Mr. Dan Tuffley
Mitchell Energy

Mr. Jerry Sexton
NMOCD Division Director, Hobbs, NM

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

January 11, 1993

State of New Mexico
OIL CONSERVATION DIVISION
P. O. Box 2088
Santa Fe, NM 87501

Attn: Mr. Ben Stone

RE: Shooting Star AEA C-108

Dear Mr. Stone:

Please find enclosed two cement bond logs on the Reeves "ADQ" State #1, a well within the area of review for the Shooting Star C-108 application.

One bond log was run on 4-16-86, and the other on 4-17-86 with 1000 psi pressure. The 4-17-86 bond log indicates a cement top at 4980'. Please substitute this information to the previously submitted information on this topic.

Sincerely yours,

James S. Brown
Operations Engineering Supervisor