

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other Instructions on the reverse side

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

Coleman Oil & Gas, Inc.

3a. Address

P.O. Drawer 3337, Farmington, NM 87499

3b. Phone No. (include area code)

505-327-0356

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

790' FNL and 875' FWL SEC 18, T26N, R11W, NMPM

5. Lease Serial No.

NOO-C-14-20-5390

6. If Indian, Allottee, or Tribe Name

NAVAJO - NAPI

7. If Unit or CA Agreement Designation

8. Well Name and No.

Ricky #1

9. API Well No.

30-045-25976

10. Field and Pool, or Exploratory Area

Basin Fruitland Coal

11. County or Parish, State

San Juan

NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Altering Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and abandon

☐ Plug back

☐ Production (Start/ Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will be performed or provide the Bond No. on file with the BLW BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)



Coleman Oil & Gas, Inc., Proposes To Plug and Abandon this well as follows.
See attached procedure.

BEFORE THE
OIL CONSERVATION DIVISION
Case No. 13279 Exhibit No. 3
Submitted By:
NM Pro Energy
Hearing Date: June 24, 2004

14. I hereby certify that the foregoing is true and correct.

Name (Printed/ Typed)

MICHAEL T. HANSON

Title

ENGINEER

Signature

Date

February 12, 2003

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

2/21/03

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOCD

Wednesday, February 12, 2003

Well: Ricky #1

Field: Basin Fruitland Coal
1194-1198
1220-1224

PLUG AND ABANDON PROCEDURE.

1. MOL with cementers, hold safety meeting, blow well down and kill with water if necessary.
2. Connect cement truck to 2 7/8" casing and fill 40 sacks (47 Cu. Ft.) Class B cement, add 1/2# per sack of celloflake to first 5 sacks of cement. Pump cement until casing stands full of cement. Volumes based on 18% excess.
3. Install dry hole marker.
4. Location will not be reclaimed. Well pad will be used for Ricky #1R.