

BEFORE EXAMINER

CH. CONTR. WITHN. OPINION

OCD

EXHIBIT NO.

7

CASE NO.

12976

OIL CONSERVATION DIVISION

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-041-20615

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
V-39

7. Lease Name or Unit Agreement Name
Rhonda "PG" State

8. Well No. 1

9. Pool name or Wildcat
Todd Upper San Andres

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Paul Bliss

3. Address of Operator
1301 E. Highland Dr.


4. Well Location
Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line
Section 35 Township 7 S Range 35 E NMPM Roosevelt County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRN WS unit & P/A Equip.
- POOH w/ rods & BHP; lay down in singles
- Install BOP. POOH w/ 2 3/8" Tbg.; Tag bottom & tally out.
- RIH w/ Tbg., open ended.
- Spot 50 sx. cnt. plug from 4270'-3805'. (Across part's.)
- POOH w/ Tbg. & let cnt. set. RIH w/ Tbg. & tag TOC.
- Circ. 4 1/2" csg. w/ M&F. Lay down. Tbg. as needed.
- Spot 50sx cnt. plug from 2143'-1678'. Spot 50sx cnt. plug ^{from} 365'-0'
- Squeeze 50sx. cnt. down annulus. 8 5/8" x 4 1/2"
- Cut off WH & install DH Marker



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paul Bliss TITLE owner DATE 11-12-01

TYPE OR PRINT NAME Paul Bliss TELEPHONE NO. 392-7760

(This space for State Use)

APPROVED BY Glenn W. Wink TITLE NATURAL SCIENCE MANAGER DATE NOV 19, 2001

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.