



417

ConocoPhillips
San Juan Business Unit
Land Department
P.O. Box 4289
Farmington, NM 87499-4289

February 28, 2013

Bureau of Land Management
6251 College Blvd, Suite A
Farmington, NM 87402

Oil Conservation Division
State of New Mexico
1220 S. Saint Francis Drive
Santa Fe, NM 87505

Commissioner of Public Lands
State of New Mexico
Post Office Box 1148
Santa Fe, NM 87501-1148

Re: 2013 Plan of Development
San Juan 30-5 Unit #14-08-001-346
Rio Arriba County, New Mexico

Ladies and Gentlemen:

The following Participating Areas currently exist in the SAN JUAN 30-5 UNIT:

FORMATION	EXPANSION	EFFECTIVE DATE
FRUITLAND COAL	037	1-OCT-04
PICTURED CLIFFS	004	1-DEC-05
MESAVERDE	035	1-JUNE-00
DAKOTA	018	1-AUG-00

The 2012 Plan of Development (or amendments thereto) provided for the following activity:

WELL NAME	FORMATION	TYPE	DEDICATION	STATUS
SAN JUAN 30-5 UNIT 114	PICTURED CLIFFS	New Drill-Single	W/2 029-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 116	PICTURED CLIFFS	New Drill-Single	SW4 035-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT COM 1N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 004-030N-005W	COMPLETED
SAN JUAN 30-5 UNIT 8A	MESAVERDE/DAKOTA	New Drill-Commingle	E/2 011-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 8M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 011-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 8N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 011-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 8P	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 011-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 20P	MESAVERDE/DAKOTA	New Drill-Commingle	E/2 008-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 24N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W/2 024-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 28A	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 023-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 28N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 023-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 37N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W/2 008-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 38N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 018-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 39M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 007-030N-005W DK /MC N/2 007-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 39N	MESAVERDE/DAKOTA	New Drill-Commingle	MV W/2 007-030N-005W DK N/2 007-030N-005W	CANCELLED
SAN JUAN 30-5 UNIT 40A	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W/2 033-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 47N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W/2 017-030N-005W	CANCELLED
SAN JUAN 30-5 UNIT 71P	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W/2 022-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 77N	MESAVERDE/DAKOTA	New Drill-Commingle	NSP 036-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 79N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 005-030N-005W DK/MC N/2 005-030N-005W	CARRYOVER

San Juan 30-5 Unit
2013 Plan of Development

WELL NAME	FORMATION	TYPE	DEDICATION	STATUS
SAN JUAN 30-5 UNIT 81Q	MESAVERDE/DAKOTA	New Drill-Commingle	W/2 27-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 82M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 025-030N-005W DK/MC N/2 025-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 83N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W/2 023-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 84A	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV E/2 033-030N-005W DK/MC NSP S/2 33-30N-05W	CARRYOVER
SAN JUAN 30-5 UNIT 86M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV E/2 035-030N-005W DK/MC S/2 035-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 86N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV E/2 035-030N-005W DK/MC S/2 035-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 87F	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	S/2 005-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 91M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 025-030N-005W MC/DK NSP S/2 25-30N-05W	CARRYOVER
SAN JUAN 30-5 UNIT 92M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV E/2 026-030N-005W DK/MC S/2 026-030N-005W	COMPLETED
SAN JUAN 30-5 UNIT 92N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV E/2 026-030N-005W DK/MC S/2 026-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 93M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 026-030N-05W DK/MC N/2 026-030N-05W	CARRYOVER
SAN JUAN 30-5 UNIT 93N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 026-030N-005W DK/MC N/2 026-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 95M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 028-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 100M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 034-030N-005W DK/MC N/2 034-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 105	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 030-030N-005W	CANCELLED
SAN JUAN 30-5 UNIT 112M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	NSP 012-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 112N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	NSP 012-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 112P	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	NSP 012-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 113M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	NSP 011-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 113N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W/2 011-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 248A	FRUITLAND COAL/ PICTURED CLIFFS	New Drill-Commingle	W/2 035-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 270	MESAVERDE/DAKOTA	New Drill-Commingle	MV E/2 029-030N-005W DK S/2 029-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 270N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 029-030N-005W DK/MC S/2 029-030N-005W	CARRYOVER
SAN JUAN 30-5 UNIT 24	PICTURED CLIFFS	Recomplete-Commingle	SW/4 016-030N-005W	CARRYOVER

San Juan 30-5 Unit
2013 Plan of Development

Pursuant to Section 10 of the San Juan 30-5 UNIT Agreement, ConocoPhillips Company, as Unit Operator, hereby submits the **2013 Plan of Development** as follows:

WELL NAME	FORMATION	TYPE	DEDICATION
SAN JUAN 30-5 UNIT 114	PICTURED CLIFFS	New Drill-Single	W/2 029-030N-005W
SAN JUAN 30-5 UNIT 116	PICTURED CLIFFS	New Drill-Single	SW/4 035-030N-005W
SAN JUAN 30-5 UNIT 8A	MESAVERDE/DAKOTA	New Drill-Commingle	E/2 011-030N-005W
SAN JUAN 30-5 UNIT 8M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 011-030N-005W
SAN JUAN 30-5 UNIT 8N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 011-030N-005W
SAN JUAN 30-5 UNIT 8P	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 011-030N-005W
SAN JUAN 30-5 UNIT 20P	MESAVERDE/DAKOTA	New Drill-Commingle	E/2 008-030N-005W
SAN JUAN 30-5 UNIT 21N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W/2 024-030N-005W
SAN JUAN 30-5 UNIT 28A	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 023-030N-005W
SAN JUAN 30-5 UNIT 28N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 023-030N-005W
SAN JUAN 30-5 UNIT 37N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W/2 008-030N-005W
SAN JUAN 30-5 UNIT 38N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 018-030N-005W
SAN JUAN 30-5 UNIT 39M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 007-030N-005W DK /MC N/2 007-030N-005W
SAN JUAN 30-5 UNIT 40A	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W/2 033-030N-005W
SAN JUAN 30-5 UNIT 71P	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W/2 022-030N-005W
SAN JUAN 30-5 UNIT 77N	MESAVERDE/DAKOTA	New Drill-Commingle	NSP 036-030N-005W
SAN JUAN 30-5 UNIT 79N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 005-030N-05W DK/MC N/2 005-030N-05W
SAN JUAN 30-5 UNIT 81Q	MESAVERDE/DAKOTA	New Drill-Commingle	W/2 27-030N-005W
SAN JUAN 30-5 UNIT 82M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	NSP 025-030N-005W
SAN JUAN 30-5 UNIT 83N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	W2 023-030N-005W
SAN JUAN 30-5 UNIT 84A	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV E/2 033-030N-005W DK/MC S/2 033-030N-005W
SAN JUAN 30-5 UNIT 86M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV E/2 035-030N-005W DK/MC S/2 035-030N-005W
SAN JUAN 30-5 UNIT 86N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV E/2 035-030N-005W DK/MC S/2 035-030N-005W
SAN JUAN 30-5 UNIT 87F	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	S/2 005-030N-005W
SAN JUAN 30-5 UNIT 91M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W2 025-030N-005W MC/DK NSP S2 25-30N-5W
SAN JUAN 30-5 UNIT 92N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV E/2 026-030N-005W DK/MC S/2 026-030N-005W
SAN JUAN 30-5 UNIT 93M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 026-030N-05W DK/MC N/2 026-030N-05W
SAN JUAN 30-5 UNIT 93N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 026-030N-005W DK/MC N/2 026-030N-005W
SAN JUAN 30-5 UNIT 95M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	E/2 028-030N-005W
SAN JUAN 30-5 UNIT 100M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 034-030N-005W DK/MC N/2 034-030N-005W
SAN JUAN 30-5 UNIT 112M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	NSP 012-030N-005W
SAN JUAN 30-5 UNIT 112N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	NSP 012-030N-005W
SAN JUAN 30-5 UNIT 112P	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	NSP 012-030N-005W
SAN JUAN 30-5 UNIT 113M	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	NSP 011-030N-005W
SAN JUAN 30-5 UNIT 113N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	NSP 011-030N-005W
SAN JUAN 30-5 UNIT 248A	FRUITLAND COAL/PICTURED CLIFFS	New Drill-Commingle	W/2 035-030N-005W
SAN JUAN 30-5 UNIT 270	MESAVERDE/DAKOTA	New Drill-Commingle	MV E/2 029-030N-005W DK S/2 029-030N-005W
SAN JUAN 30-5 UNIT 270N	MESAVERDE/DAKOTA/MANCOS	New Drill-Trimingle	MV W/2 029-030N-005W DK/MC S/2 029-030N-005W
SAN JUAN 30-5 UNIT 24	PICTURED CLIFFS	Recomplete-Commingle	SW/4 016-030N-005W


San Juan 30-5 Unit
2013 Plan of Development

The working interest owners are being furnished a copy of this letter, well status listing and enclosed map. ConocoPhillips, as Unit Operator, will drill any offset wells required to prevent drainage of unitized substances and any other wells deemed necessary by the working interest owners or Unit Operator.

In accordance to Section 10 of the Unit Agreement, please provide your approvals by executing and returning a copy of this letter to the undersigned.

Please contact me at (505) 324-6180 if there are any questions regarding this letter.

Sincerely,



Vanessa Thompson, RPL
Land Supervisor, SE,


VMT/ys

xc: San Juan 30-5 Unit, 3.0 (2013)
San Juan 30-5 Unit Working Interest Owners


**SAN JUAN 30-5 UNIT
2013 PLAN OF DEVELOPMENT APPROVALS**

Bureau of Land Management

Date



New Mexico Oil Conservation Division



Date

New Mexico Commissioner of Public Lands

Date

***WORKING INTEREST OWNERS
SAN JUAN 30-5 UNIT***

NAVATEX ENERGY LP

BARTON RESOURCES LLC

BP AMERICA PRODUCTION COMPANY

BURLINGTON RESOURCES O&G CO LP

CONOCOPHILLIPS COMPANY

DUGAN PRODUCTION CORP

FOUR STAR OIL & GAS COMPANY

JABCO LLP

LANGDON D HARRISON TRUST

MAR OIL & GAS CORPORATION

PHILLIPS NEW MEXICO PARTNERS LP

PHILLIPS SAN JUAN LTD PARTNERSHIP

PROVIDENCE MINERALS LLC

RIO ARIBAGAS LTD

RIO ARRIBA LIMITED PARTNERSHIP

RUTH ZIMMERMAN TRUST


SAN JUAN BASIN PARTNERSHIP

THOMAS P TINNIN

TINMIL A NM LLC

WPX ENERGY INC

R5W



SAN JUAN 30-5 UNIT

T
30
N

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300393066200N02	SAN JUAN 30-5 1N DK NU	RIO ARRIBA	NM					A719865	12001	BASIN::DAKOTA	11	G	10/8/12		10/9/12	10/9/12
300393066200N01	SAN JUAN 30-5 1N DK UT	RIO ARRIBA	NM					A719864	12001	BASIN::DAKOTA	11	G	10/8/12		10/9/12	10/9/12
300393066200N04	SAN JUAN 30-5 1N MC NU	RIO ARRIBA	NM					A718574	12001	BASIN::MANCOS	11	G	10/8/12		10/9/12	10/9/12
300393066200N03	SAN JUAN 30-5 1N MC UT	RIO ARRIBA	NM					A718572	12001	BASIN::MANCOS	11	G	10/8/12		10/9/12	10/9/12
300393066200N06	SAN JUAN 30-5 1N MV NU	RIO ARRIBA	NM					A719869	12001	BLANCO::MESAVERDE	11	G	10/8/12		10/9/12	10/9/12
300393066200N05	SAN JUAN 30-5 1N MV UT	RIO ARRIBA	NM					A719871	12001	BLANCO::MESAVERDE	11	G	10/8/12		10/9/12	10/9/12
300392454300S01	SAN JUAN 30-5 201 FC	RIO ARRIBA	NM	30	N	5	W 19	A746885	12001	BASIN::FRUITLAND COAL	11	G	2/1/90		2/1/90	2/1/90
300392786700S01	SAN JUAN 30-5 201A FC	RIO ARRIBA	NM	30	N	5	W 19	A746885	12001	BASIN::FRUITLAND COAL	11	G	11/20/04		1/27/05	1/27/05
300392467000S01	SAN JUAN 30-5 203 FC	RIO ARRIBA	NM	30	N	5	W 6	A746885	12001	BASIN::FRUITLAND COAL	41	G	7/1/90		7/1/90	7/1/90
300392725300S01	SAN JUAN 30-5 203A FC	RIO ARRIBA	NM	30	N	5	W 6	A746885	12001	BASIN::FRUITLAND COAL	11	G	2/17/03		3/4/03	3/4/03
300392468500S01	SAN JUAN 30-5 204 FC	RIO ARRIBA	NM	30	N	5	W 7	A746885	12001	BASIN::FRUITLAND COAL	11	G	2/1/92		2/1/92	2/1/92
300392463700S01	SAN JUAN 30-5 205 FC	RIO ARRIBA	NM	30	N	5	W 7	A746885	12001	BASIN::FRUITLAND COAL	11	G	9/1/93		9/1/93	9/1/93
300392469100S01	SAN JUAN 30-5 206 FC	RIO ARRIBA	NM	30	N	5	W 18	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/1/91		10/1/91	10/1/91
300392921600S01	SAN JUAN 30-5 206A FC	RIO ARRIBA	NM	30	N	5	W 18	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/27/04		12/9/04	12/9/04
300392479000S01	SAN JUAN 30-5 207 FC	RIO ARRIBA	NM	30	N	5	W 18	A746885	12001	BASIN::FRUITLAND COAL	11	G	9/15/91		1/1/92	1/1/92
300392747300S01	SAN JUAN 30-5 207A FC	RIO ARRIBA	NM	30	N	5	W 18	A746885	12001	BASIN::FRUITLAND COAL	11	G	6/30/04		7/29/04	7/29/04
300392480600S01	SAN JUAN 30-5 208 FC	RIO ARRIBA	NM	30	N	5	W 19	A746885	12001	BASIN::FRUITLAND COAL	11	G	3/1/91		3/1/91	3/1/91
300392785400S01	SAN JUAN 30-5 208A FC	RIO ARRIBA	NM	30	N	5	W 19	A746885	12001	BASIN::FRUITLAND COAL	11	G	11/16/04		1/26/05	1/26/05
300392469200S01	SAN JUAN 30-5 209 FC	RIO ARRIBA	NM	30	N	5	W 30	A746885	12001	BASIN::FRUITLAND COAL	11	G	7/1/90		7/1/90	7/1/90
300392497100S01	SAN JUAN 30-5 210 FC	RIO ARRIBA	NM	30	N	5	W 30	A746885	12001	BASIN::FRUITLAND COAL	11	G	6/1/91		6/1/91	6/1/91
300392786800S01	SAN JUAN 30-5 210A FC	RIO ARRIBA	NM	30	N	5	W 30	A746885	12001	BASIN::FRUITLAND COAL	11	G	11/7/04		3/11/05	3/11/05
300392472000S01	SAN JUAN 30-5 211 FC	RIO ARRIBA	NM	30	N	5	W 31	A746885	12001	BASIN::FRUITLAND COAL	11	G	5/1/91			
300392472100S01	SAN JUAN 30-5 212 FC	RIO ARRIBA	NM	30	N	5	W 31	A746885	12001	BASIN::FRUITLAND COAL	11	G	9/1/90		9/1/90	9/1/90
300392785800S01	SAN JUAN 30-5 212A FC	RIO ARRIBA	NM	30	N	5	W 31	A746885	12001	BASIN::FRUITLAND COAL	11	G	11/12/04		2/2/05	2/2/05
300392725200S01	SAN JUAN 30-5 213A	RIO ARRIBA	NM	30	N	5	W 5	A746885	12001	BASIN::FRUITLAND COAL	11	G	3/11/03		3/19/03	3/19/03
300392651200S01	SAN JUAN 30-5 214	RIO ARRIBA	NM	30	N	5	W 5	A746885	12001	BASIN::FRUITLAND COAL	11	G	1/4/01			
300392777500S01	SAN JUAN 30-5 215A	RIO ARRIBA	NM	30	N	5	W 8	A746885	12001	BASIN::FRUITLAND COAL	11	G	9/10/04			
300392783000S01	SAN JUAN 30-5 216A FC	RIO ARRIBA	NM	30	N	5	W 20	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/29/04		1/3/05	1/3/05
300392531800S01	SAN JUAN 30-5 216R FC	RIO ARRIBA	NM	30	N	5	W 20	A746885	12001	BASIN::FRUITLAND COAL	11	G	1/1/94		1/1/94	1/1/94
300392780900S01	SAN JUAN 30-5 217A FC	RIO ARRIBA	NM	30	N	5	W 21	A746885	12001	BASIN::FRUITLAND COAL	11	G	8/15/04		9/14/04	9/14/04
300392478800S01	SAN JUAN 30-5 218 FC	RIO ARRIBA	NM	30	N	5	W 17	A746885	12001	BASIN::FRUITLAND COAL	11	G	3/1/91		3/1/91	3/1/91
300392776800S01	SAN JUAN 30-5 218A FC	RIO ARRIBA	NM	30	N	5	W 17	A746885	12001	BASIN::FRUITLAND COAL	11	G	8/8/04		11/1/04	11/1/04
300392476800S01	SAN JUAN 30-5 219 FC	RIO ARRIBA	NM	30	N	5	W 16	A746885	12001	BASIN::FRUITLAND COAL	31	S	6/1/91		6/1/91	6/1/91
300392748700S01	SAN JUAN 30-5 219A FC	RIO ARRIBA	NM	30	N	5	W 16	A746885	12001	BASIN::FRUITLAND COAL	11	G	2/8/04		2/25/04	2/25/04
300392664000S01	SAN JUAN 30-5 219R FC	RIO ARRIBA	NM	30	N	5	W 16	A746885	12001	BASIN::FRUITLAND COAL	11	G	2/20/01		2/27/01	2/27/01
300392641800C01	SAN JUAN 30-5 21A DK P&A	RIO ARRIBA	NM	30	N	5	W 24	E A650523	12001	BASIN::DAKOTA	71	G		6/4/09	10/31/00	10/31/00
300392641800C01	SAN JUAN 30-5 21A DK P&A	RIO ARRIBA	NM	30	N	5	W 24	E A650523	12001	BASIN::DAKOTA	71	G		6/4/09	10/31/00	10/31/00
300392641800C01	SAN JUAN 30-5 21A DK P&A	RIO ARRIBA	NM	30	N	5	W 24	E A650523	12001	BASIN::DAKOTA	71	G		6/4/09	10/31/00	10/31/00
300392985700S01	SAN JUAN 30-5 220A FC	RIO ARRIBA	NM	30	N	5	W 8	A746885	12001	BASIN::FRUITLAND COAL	11	G	9/28/06		10/27/06	10/27/06
300392490100S01	SAN JUAN 30-5 223 FC	RIO ARRIBA	NM	30	N	5	W 20	A746885	12001	BASIN::FRUITLAND COAL	11	G	2/1/93		2/1/93	2/1/93
300392781300S01	SAN JUAN 30-5 223A FC	RIO ARRIBA	NM	30	N	5	W 20	A746885	12001	BASIN::FRUITLAND COAL	11	G	8/22/04		10/8/04	10/8/04
300392490200S01	SAN JUAN 30-5 224 FC	RIO ARRIBA	NM	30	N	5	W 17	A746885	12001	BASIN::FRUITLAND COAL	11	G	7/1/91		7/1/91	7/1/91
300392508700S01	SAN JUAN 30-5 225 FC	RIO ARRIBA	NM	30	N	5	W 29	A746885	12001	BASIN::FRUITLAND COAL	11	G	6/1/93		6/1/93	6/1/93
300392496500S01	SAN JUAN 30-5 226 FC	RIO ARRIBA	NM	30	N	5	W 29	A746885	12001	BASIN::FRUITLAND COAL	11	G	7/15/91			
300392921000S01	SAN JUAN 30-5 226A FC	RIO ARRIBA	NM	30	N	5	W 29	A746885	12001	BASIN::FRUITLAND COAL	11	G	11/8/04		1/26/05	1/26/05
300392489200S01	SAN JUAN 30-5 227 FC	RIO ARRIBA	NM	30	N	5	W 28	A746885	12001	BASIN::FRUITLAND COAL	11	G	6/1/91		6/1/91	6/1/91
300392512700S01	SAN JUAN 30-5 228 FC	RIO ARRIBA	NM	30	N	5	W 28	A746885	12001	BASIN::FRUITLAND COAL	11	G	6/1/93		6/1/93	6/1/93
300392497900S01	SAN JUAN 30-5 229 FC	RIO ARRIBA	NM	30	N	5	W 21	A746885	12001	BASIN::FRUITLAND COAL	11	G	6/1/91		6/1/91	6/1/91
300392777300S01	SAN JUAN 30-5 229A FC	RIO ARRIBA	NM	30	N	5	W 21	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/7/04		12/9/04	12/9/04

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300392490300S01	SAN JUAN 30-5 230 FC	RIO ARRIBA	NM	30	N	5	W 32	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/12/91		7/1/92	7/1/92
300392751300S01	SAN JUAN 30-5 230A FC	RIO ARRIBA	NM	30	N	5	W 32	A746885	12001	BASIN::FRUITLAND COAL	72	G	3/28/04	12/12/05	5/4/04	5/4/04
300392489300S01	SAN JUAN 30-5 231 FC	RIO ARRIBA	NM	30	N	5	W 32	A746885	12001	BASIN::FRUITLAND COAL	11	G	6/1/93		6/1/93	6/1/93
300392751400S01	SAN JUAN 30-5 231A FC	RIO ARRIBA	NM	30	N	5	W 32	A746885	12001	BASIN::FRUITLAND COAL	11	G	1/8/04		3/2/04	3/2/04
300392519400S01	SAN JUAN 30-5 232 FC	RIO ARRIBA	NM	30	N	5	W 33	A746885	12001	BASIN::FRUITLAND COAL	11	G	12/1/93		12/1/93	12/1/93
300392519500S01	SAN JUAN 30-5 233 FC	RIO ARRIBA	NM	30	N	5	W 33	A746885	12001	BASIN::FRUITLAND COAL	11	G	6/1/93			
300392517100S01	SAN JUAN 30-5 234 FC	RIO ARRIBA	NM	30	N	5	W 22	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/1/93		10/1/93	10/1/93
300392780600S01	SAN JUAN 30-5 234A FC	RIO ARRIBA	NM	30	N	5	W 22	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/13/04		11/5/04	11/5/04
300392514000S01	SAN JUAN 30-5 235 FC	RIO ARRIBA	NM	30	N	5	W 27	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/1/93		10/1/93	10/1/93
300392507700S01	SAN JUAN 30-5 236 FC	RIO ARRIBA	NM	30	N	5	W 27	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/1/93		10/1/93	10/1/93
300392748800S01	SAN JUAN 30-5 237A FC	RIO ARRIBA	NM	30	N	5	W 16	A746885	12001	BASIN::FRUITLAND COAL	11	G	12/7/03			
300392514100S01	SAN JUAN 30-5 238 FC	RIO ARRIBA	NM	30	N	5	W 34	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/1/93		10/1/93	10/1/93
300392516500S01	SAN JUAN 30-5 239 FC	RIO ARRIBA	NM	30	N	5	W 15	A746885	12001	BASIN::FRUITLAND COAL	11	G	1/1/94		1/1/94	1/1/94
300392923200S01	SAN JUAN 30-5 239A FC	RIO ARRIBA	NM	30	N	5	W 15	A746885	12001	BASIN::FRUITLAND COAL	11	G	11/30/05		12/14/05	12/14/05
300392520200S01	SAN JUAN 30-5 240 FC	RIO ARRIBA	NM	30	N	5	W 22	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/1/93		10/1/93	10/1/93
300392921900S01	SAN JUAN 30-5 240A FC	RIO ARRIBA	NM	30	N	5	W 22	A746885	12001	BASIN::FRUITLAND COAL	11	G			12/9/04	12/9/04
300392520300S01	SAN JUAN 30-5 241 FC	RIO ARRIBA	NM	30	N	5	W 23	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/1/93		10/1/93	10/1/93
300392924400S01	SAN JUAN 30-5 241A FC	RIO ARRIBA	NM	30	N	5	W 23	A746885	12001	BASIN::FRUITLAND COAL	11	G	8/20/06		9/12/06	9/12/06
300392516600S01	SAN JUAN 30-5 242 FC	RIO ARRIBA	NM	30	N	5	W 34	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/1/93		10/1/93	10/1/93
300392780500S01	SAN JUAN 30-5 243A FC	RIO ARRIBA	NM	30	N	5	W 15	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/22/04		12/2/04	12/2/04
300392526500S01	SAN JUAN 30-5 246 FC	RIO ARRIBA	NM	30	N	5	W 26	A746885	12001	BASIN::FRUITLAND COAL	11	G	12/1/93		12/1/93	12/1/93
300392923000S01	SAN JUAN 30-5 249A FC	RIO ARRIBA	NM	30	N	5	W 23	A746885	12001	BASIN::FRUITLAND COAL	99	G	8/31/06		10/5/06	10/5/06
300392598100S01	SAN JUAN 30-5 260 FC	RIO ARRIBA	NM	30	N	5	W 9	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/30/98		11/25/98	
300392725600S01	SAN JUAN 30-5 260A FC	RIO ARRIBA	NM	30	N	5	W 9	A746885	12001	BASIN::FRUITLAND COAL	11	G	4/12/03		4/23/03	4/23/03
300392604900S01	SAN JUAN 30-5 264 FC	RIO ARRIBA	NM	30	N	5	W 9	A746885	12001	BASIN::FRUITLAND COAL	11	G	3/31/99			
300392777200S01	SAN JUAN 30-5 264A FC	RIO ARRIBA	NM	30	N	5	W 9	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/30/04		12/6/04	12/6/04
300392630300S01	SAN JUAN 30-5 265 FC	RIO ARRIBA	NM	30	N	5	W 10	A746885	12001	BASIN::FRUITLAND COAL	11	G	5/9/00			
300392777100S01	SAN JUAN 30-5 265A FC	RIO ARRIBA	NM	30	N	5	W 10	A746885	12001	BASIN::FRUITLAND COAL	11	G	10/6/04		11/1/04	11/1/04
300392630200S01	SAN JUAN 30-5 266 FC	RIO ARRIBA	NM	30	N	5	W 10	A746885	12001	BASIN::FRUITLAND COAL	11	G	3/24/00			
300392725400S01	SAN JUAN 30-5 266A FC	RIO ARRIBA	NM	30	N	5	W 10	A746885	12001	BASIN::FRUITLAND COAL	11	G	3/21/03		3/28/03	3/28/03
300392955200S02	SAN JUAN 30-5 37G DK	RIO ARRIBA	NM	30	N	5	W 8	A728848	12001	BASIN::DAKOTA	11	G	8/30/06		10/4/06	10/4/06
300392955200S01	SAN JUAN 30-5 37G MV	RIO ARRIBA	NM	30	N	5	W 8	A728850	12001	BLANCO::MESAVERDE	11	G	8/30/06		10/4/06	10/4/06
300393070700C01	SAN JUAN 30-5 UNIT 20N DK	RIO ARRIBA	NM	30	N	5	W 8	A650402	12001	BASIN::DAKOTA	11	G	8/31/09		10/29/09	10/29/09
300393070700C02	SAN JUAN 30-5 UNIT 20N MV	RIO ARRIBA	NM	30	N	5	W 8	A650113	12001	BLANCO::MESAVERDE	11	G	8/31/09		10/29/09	10/29/09
300393069500C01	SAN JUAN 30-5 UNIT 96M DK	RIO ARRIBA	NM	30	N	5	W 28	A650283	12001	BASIN::DAKOTA	11	G	9/28/09		9/16/09	9/16/09
300393069500C02	SAN JUAN 30-5 UNIT 96M MV	RIO ARRIBA	NM	30	N	5	W 28	A650113	12001	BLANCO::MESAVERDE	11	G	9/28/09		9/16/09	9/16/09
300393070800C01	SAN JUAN 30-5 UNIT 97M DK	RIO ARRIBA	NM	30	N	5	W 29	A650402	12001	BASIN::DAKOTA	11	G	11/16/09		12/2/09	12/2/09
300393070800C02	SAN JUAN 30-5 UNIT 97M MV	RIO ARRIBA	NM	30	N	5	W 29	A650113	12001	BLANCO::MESAVERDE	11	G	11/16/09		12/2/09	12/2/09
300390779200S01	SAN JUAN 30-5 UNIT NP SPO	RIO ARRIBA	NM	30	N	5	W 20	A722554	12001	BASIN::DAKOTA	99	G	11/19/59			
300390783800S01	SAN JUAN 30-5 UT 10 MV	RIO ARRIBA	NM	30	N	5	W 18	A650113	12001	BLANCO::MESAVERDE	11	G				
300392317500S01	SAN JUAN 30-5 UT 100 DK	RIO ARRIBA	NM	30	N	5	W 34	A650285	12001	BASIN::DAKOTA	11	G				
300392317500S01	SAN JUAN 30-5 UT 100 DK	RIO ARRIBA	NM	30	N	5	W 34	A650285	12001	BASIN::DAKOTA	11	G				
300392317500S01	SAN JUAN 30-5 UT 100 DK	RIO ARRIBA	NM	30	N	5	W 34	A650285	12001	BASIN::DAKOTA	11	G				
300393071000C01	SAN JUAN 30-5 UT 100N DK	RIO ARRIBA	NM	30	N	5	W 34	A650285	12001	BASIN::DAKOTA	11	G	9/22/09		9/9/09	9/9/09
300393071000C02	SAN JUAN 30-5 UT 100N MV	RIO ARRIBA	NM	30	N	5	W 34	A650113	12001	BLANCO::MESAVERDE	11	G	9/22/09		9/9/09	9/9/09
300392314700S01	SAN JUAN 30-5 UT 101 DK	RIO ARRIBA	NM	30	N	5	W 35	A650402	12001	DAKOTA LP	11	G				
300392314700S01	SAN JUAN 30-5 UT 101 DK	RIO ARRIBA	NM	30	N	5	W 35	A650402	12001	DAKOTA LP	11	G				
300392317600C02	SAN JUAN 30-5 UT 102 DK	RIO ARRIBA	NM	30	N	5	W 34	A650286	12001	BASIN::DAKOTA	11	G				
300392317600C02	SAN JUAN 30-5 UT 102 DK	RIO ARRIBA	NM	30	N	5	W 34	A650286	12001	BASIN::DAKOTA	11	G				

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
 41 - SHUT IN 72 - PERM ABANDON WELL
 59 - SOLD PA - PLUG ABANDON
 61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300392317600C02	SAN JUAN 30-5 UT 102 DK	RIO ARRIBA	NM	30	N	5	W 34	K	A650286	12001	BASIN::DAKOTA	11	G			
300392317600C01	SAN JUAN 30-5 UT 102 GA	RIO ARRIBA	NM	30	N	5	W 34	K	A650286	12001	BASIN::GALLUP	11	G			
300392317600C01	SAN JUAN 30-5 UT 102 GA	RIO ARRIBA	NM	30	N	5	W 34	K	A650286	12001	BASIN::GALLUP	11	G			
300392317600C01	SAN JUAN 30-5 UT 102 GA	RIO ARRIBA	NM	30	N	5	W 34	K	A650286	12001	BASIN::GALLUP	11	G			
300392317600C01	SAN JUAN 30-5 UT 102 GA	RIO ARRIBA	NM	30	N	5	W 34	K	A650286	12001	BASIN::GALLUP	11	G			
3003923176	SAN JUAN 30-5 UT 102 GADK	RIO ARRIBA	NM	30	N	5	W 34	K	A650286	12001	BASIN::GALLUP-DAKOTA	99	G	9/21/84		
300392322300S01	SAN JUAN 30-5 UT 103 DK	RIO ARRIBA	NM	30	N	5	W 3	M	A650291	12001	BASIN::DAKOTA	11	G	1/26/85	11/21/97	11/21/97
300392322300S01	SAN JUAN 30-5 UT 103 DK	RIO ARRIBA	NM	30	N	5	W 3	M	A650291	12001	BASIN::DAKOTA	11	G	1/26/85	11/21/97	11/21/97
300392331100C01	SAN JUAN 30-5 UT 104 DK	RIO ARRIBA	NM	30	N	5	W 13	G	A650402	12001	BASIN::DAKOTA	11	G	1/30/84	1/30/84	1/30/84
300392331100C01	SAN JUAN 30-5 UT 104 DK	RIO ARRIBA	NM	30	N	5	W 13	G	A650402	12001	BASIN::DAKOTA	11	G	1/30/84	1/30/84	1/30/84
300392331100C02	SAN JUAN 30-5 UT 104 MV	RIO ARRIBA	NM	30	N	5	W 13	G	A714098	12001	BLANCO::MESAVERDE	11	G	6/10/11	8/5/11	8/5/11
300392641700C01	SAN JUAN 30-5 UT 104E DK	RIO ARRIBA	NM	30	N	5	W 13	J	A650402	12001	BASIN::DAKOTA	11	G	8/23/00	8/23/00	8/23/00
300392641700C02	SAN JUAN 30-5 UT 104E MV	RIO ARRIBA	NM	30	N	5	W 13	J	A714098	12001	BLANCO::MESAVERDE	11	G	10/1/10		10/9/10
300392426600S01	SAN JUAN 30-5 UT 109 MV	RIO ARRIBA	NM	30	N	5	W 14	K	A650113	12001	BLANCO::MESAVERDE	11	G			
300392570600C01	SAN JUAN 30-5 UT 109A DK	RIO ARRIBA	NM	30	N	5	W 14	E	A650402	12001	DAKOTA NQ	11	G		10/28/97	10/28/97
300392570600C01	SAN JUAN 30-5 UT 109A DK	RIO ARRIBA	NM	30	N	5	W 14	E	A650402	12001	DAKOTA NQ	11	G		10/28/97	10/28/97
300392570600C02	SAN JUAN 30-5 UT 109A MV	RIO ARRIBA	NM	30	N	5	W 14	E	A650113	12001	BLANCO::MESAVERDE	11	G		5/14/98	5/14/98
300391820400S01	SAN JUAN 30-5 UT 11 MV	RIO ARRIBA	NM	30	N	5	W 23	L	A650113	12001	BLANCO::MESAVERDE	11	G			
300392528400C01	SAN JUAN 30-5 UT 110 DK	RIO ARRIBA	NM	30	N	5	W 16	A	A650402	12001	DAKOTA NQ	11	G		3/1/94	
300392528400C02	SAN JUAN 30-5 UT 110 MV	RIO ARRIBA	NM	30	N	5	W 16	A	A650113	12001	BLANCO::MESAVERDE	11	G		11/19/02	11/19/02
300393010800C01	SAN JUAN 30-5 UT 110G DK	RIO ARRIBA	NM	30	N	5	W 16	C	A650402	12001	BASIN::DAKOTA	11	G	7/30/07	8/7/07	8/7/07
300393010800C02	SAN JUAN 30-5 UT 110G MV	RIO ARRIBA	NM	30	N	5	W 16	C	A650113	12001	BLANCO::MESAVERDE	11	G	7/30/07	8/7/07	8/7/07
300392565800C01	SAN JUAN 30-5 UT 110M DK	RIO ARRIBA	NM	30	N	5	W 16	E	A650402	12001	DAKOTA NQ	11	G		6/24/97	6/24/97
300392565800C02	SAN JUAN 30-5 UT 110M MV	RIO ARRIBA	NM	30	N	5	W 16	E	A650113	12001	BLANCO::MESAVERDE	11	G		11/26/97	11/26/97
300392615800C01	SAN JUAN 30-5 UT 111 DK	RIO ARRIBA	NM	30	N	5	W 13	N	A650402	12001	DAKOTA NQ	11	G	7/17/99	9/9/99	9/9/99
300392615800C02	SAN JUAN 30-5 UT 111 MV	RIO ARRIBA	NM	30	N	5	W 13	N	A714123	12001	BLANCO::MESAVERDE	11	G	7/17/99		
300393066500C01	SAN JUAN 30-5 UT 111E DK	RIO ARRIBA	NM	30	N	5	W 13	F	A650402	12001	BASIN::DAKOTA	11	G	9/13/10	10/1/10	10/1/10
300393066500C02	SAN JUAN 30-5 UT 111E MV	RIO ARRIBA	NM	30	N	5	W 13	F	A715804	12001	BLANCO::MESAVERDE	11	G	9/13/10	10/1/10	10/1/10
300392615900C01	SAN JUAN 30-5 UT 112 DK	RIO ARRIBA	NM	30	N	5	W 12	O	A650479	12001	DAKOTA NQ	11	G		9/9/99	9/9/99
300392615900C01	SAN JUAN 30-5 UT 112 DK	RIO ARRIBA	NM	30	N	5	W 12	O	A650479	12001	DAKOTA NQ	11	G		9/9/99	9/9/99
300392615900C01	SAN JUAN 30-5 UT 112 DK	RIO ARRIBA	NM	30	N	5	W 12	O	A650479	12001	DAKOTA NQ	11	G		9/9/99	9/9/99
300392615900C02	SAN JUAN 30-5 UT 112 MV	RIO ARRIBA	NM	30	N	5	W 12	O	A650113	12001	BLANCO::MESAVERDE	11	G		6/1/00	6/1/00
300392636600C01	SAN JUAN 30-5 UT 113 DK	RIO ARRIBA	NM	30	N	5	W 11	K	A650402	12001	BASIN::DAKOTA	11	G		7/24/00	7/24/00
300392636600C02	SAN JUAN 30-5 UT 113 MV	RIO ARRIBA	NM	30	N	5	W 11	K	A650113	12001	BLANCO::MESAVERDE	11	G		11/2/00	11/2/00
300390772100S01	SAN JUAN 30-5 UT 12 MV	RIO ARRIBA	NM	30	N	5	W 31	N	A650113	12001	BLANCO::MESAVERDE	11	G			
300392272900D01	SAN JUAN 30-5 UT 12A MV	RIO ARRIBA	NM	30	N	5	W 31	E	A650113	12001	BLANCO::MESAVERDE	11	G	11/6/81	11/6/81	11/6/81
300392272900D02	SAN JUAN 30-5 UT 12A PC	RIO ARRIBA	NM	30	N	5	W 31	E	A650110	12001	GOBERNADOR:PICTURED CLIFF	71	G	11/6/81	7/24/81	
300390785900S01	SAN JUAN 30-5 UT 13 MV	RIO ARRIBA	NM	30	N	5	W 16	B	A650113	12001	BLANCO::MESAVERDE	11	G			
300390774300S01	SAN JUAN 30-5 UT 14 MV	RIO ARRIBA	NM	30	N	5	W 31	B	A650113	12001	BLANCO::MESAVERDE	11	G			
300392219200S01	SAN JUAN 30-5 UT 14A MV	RIO ARRIBA	NM	30	N	5	W 31	O	A650113	12001	BLANCO::MESAVERDE	11	G			
300390781200S01	SAN JUAN 30-5 UT 15 MV	RIO ARRIBA	NM	30	N	5	N 19	H	A650113	12001	BLANCO::MESAVERDE	11	G			
300390775600S01	SAN JUAN 30-5 UT 16 MV	RIO ARRIBA	NM	30	N	5	W 26	N	A650113	12001	BLANCO::MESAVERDE	11	G			
300390791800S01	SAN JUAN 30-5 UT 17 MV	RIO ARRIBA	NM	30	N	5	W 6	H	A650113	12001	BLANCO::MESAVERDE	11	G			
300390784800S01	SAN JUAN 30-5 UT 19 MV	RIO ARRIBA	NM	30	N	5	W 18	G	A650113	12001	BLANCO::MESAVERDE	11	G			
300392454300S01	SAN JUAN 30-5 UT 201 FC	RIO ARRIBA	NM	30	N	5	W 19	N	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		2/9/90	
300392786700S01	SAN JUAN 30-5 UT 201A FC	RIO ARRIBA	NM	30	N	5	W 19	D	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		1/27/05	1/27/05
300392452000S01	SAN JUAN 30-5 UT 202 FC	RIO ARRIBA	NM	30	N	5	W 6	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		3/8/90	
300392452000S01	SAN JUAN 30-5 UT 202 FC	RIO ARRIBA	NM	30	N	5	W 6	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		3/8/90	
300392452000S01	SAN JUAN 30-5 UT 202 FC	RIO ARRIBA	NM	30	N	5	W 6	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		3/8/90	

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300392452000S01	SAN JUAN 30-5 UT 202 FC	RIO ARRIBA	NM	30	N	5	W	6	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		3/8/90
300392776500S01	SAN JUAN 30-5 UT 202A FC	RIO ARRIBA	NM	34	T	5	W	6	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		11/2/04
300392776500S01	SAN JUAN 30-5 UT 202A FC	RIO ARRIBA	NM	34	T	5	W	6	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		11/2/04
300392776500S01	SAN JUAN 30-5 UT 202A FC	RIO ARRIBA	NM	34	T	5	W	6	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		11/2/04
300392467000S01	SAN JUAN 30-5 UT 203 FC	RIO ARRIBA	NM	30	N	5	W	6	L	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		7/28/90
300392725300S01	SAN JUAN 30-5 UT 203A FC	RIO ARRIBA	NM	30	N	5	W	6	C	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		3/4/03
300392468500S01	SAN JUAN 30-5 UT 204 FC	RIO ARRIBA	NM	30	N	5	W	7	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		1/15/92
300392463700S01	SAN JUAN 30-5 UT 205 FC	RIO ARRIBA	NM	30	N	5	W	7	K	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		9/24/93
300392469100S01	SAN JUAN 30-5 UT 206 FC	RIO ARRIBA	NM	30	N	5	W	18	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		10/7/91
300392921600S01	SAN JUAN 30-5 UT 206A FC	RIO ARRIBA	NM	30	N	5	W	18	O	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	12/9/04	12/9/04
300392479000S01	SAN JUAN 30-5 UT 207 FC	RIO ARRIBA	NM	30	N	5	W	18	L	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		1/15/92
300392747300S01	SAN JUAN 30-5 UT 207A FC	RIO ARRIBA	NM	30	N	5	W	18	E	A650363	12001	BASIN CB::FRUITLAND COAL	72	G	10/15/12	7/29/04
300392480600S01	SAN JUAN 30-5 UT 208 FC	RIO ARRIBA	NM	30	N	5	W	19	H	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		3/8/91
300392785400S01	SAN JUAN 30-5 UT 208A FC	RIO ARRIBA	NM	30	N	5	W	19	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		1/26/05
300392469200S01	SAN JUAN 30-5 UT 209 FC	RIO ARRIBA	NM	30	N	5	W	30	A	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		6/27/90
300392921700S01	SAN JUAN 30-5 UT 209A FC	RIO ARRIBA	NM	30	N	5	W	30	O	A650363	12001	BASIN CB::FRUITLAND COAL	72	G		3/11/05
300392604000C01	SAN JUAN 30-5 UT 20A DK	RIO ARRIBA	NM	30	N	5	W	8	P	A650402	12001	DAKOTA NQ	11	G		5/24/99
300392604000C02	SAN JUAN 30-5 UT 20A MV	RIO ARRIBA	NM	30	N	5	W	8	P	A650113	12001	BLANCO::MESAVERDE	11	G		11/10/99
300393059900C01	SAN JUAN 30-5 UT 20M DK	RIO ARRIBA	NM	30	N	5	W	8	G	A650402	12001	BASIN::DAKOTA	11	G	4/16/09	8/25/09
300393059900C02	SAN JUAN 30-5 UT 20M MV	RIO ARRIBA	NM	30	N	5	W	8	G	A650113	12001	BLANCO::MESAVERDE	11	G	4/16/09	8/25/09
300392497100S01	SAN JUAN 30-5 UT 210 FC	RIO ARRIBA	NM	30	N	5	W	30	M	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		5/30/91
300392786800S01	SAN JUAN 30-5 UT 210A FC	RIO ARRIBA	NM	30	N	5	W	30	C	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		3/11/05
300392482600S01	SAN JUAN 30-5 UT 213(POW)	RIO ARRIBA	NM	30	N	5	W	5	B	A650363	12001	BASIN CB::FRUITLAND COAL	PM	G		6/19/91
300392725200S01	SAN JUAN 30-5 UT 213A FC	RIO ARRIBA	NM	30	N	5	W	5	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		3/19/03
300392652300S01	SAN JUAN 30-5 UT 213R FC	RIO ARRIBA	NM	30	N	5	W	5	H	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		2/15/01
300392652300S01	SAN JUAN 30-5 UT 213R FC	RIO ARRIBA	NM	30	N	5	W	5	H	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		2/15/01
300392651200S01	SAN JUAN 30-5 UT 214 FC	RIO ARRIBA	NM	30	N	5	W	5	N	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		1/12/01
300392651200S01	SAN JUAN 30-5 UT 214 FC	RIO ARRIBA	NM	30	N	5	W	5	N	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		1/12/01
300392725100S01	SAN JUAN 30-5 UT 214A FC	RIO ARRIBA	NM	30	N	5	W	5		A746885	12001	BASIN::FRUITLAND COAL	11	G	2/26/03	3/14/03
300392725100S01	SAN JUAN 30-5 UT 214A FC	RIO ARRIBA	NM	30	N	5	W	5	E	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		3/14/03
300392478700S01	SAN JUAN 30-5 UT 215 FC	RIO ARRIBA	NM	30	N	5	W	8	H	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		2/6/91
300392478700S01	SAN JUAN 30-5 UT 215 FC	RIO ARRIBA	NM	30	N	5	W	8	H	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		2/6/91
300392777500S01	SAN JUAN 30-5 UT 215A FC	RIO ARRIBA	NM	30	N	5	W	8	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		11/2/04
300392482800S01	SAN JUAN 30-5 UT 216(POW)	RIO ARRIBA	NM	30	N	5	W	20	M	A650154	12001	BASIN CB::FRUITLAND COAL	PM	G	12/14/90	
300392783000S01	SAN JUAN 30-5 UT 216A FC	RIO ARRIBA	NM	30	N	5	W	20	D	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	10/29/04	1/3/05
300392531800S01	SAN JUAN 30-5 UT 216R FC	RIO ARRIBA	NM	30	N	5	W	20	L	A650363	12001	BASIN::FRUITLAND COAL	11	G	12/15/93	12/29/93
300392484900S01	SAN JUAN 30-5 UT 217 FC	RIO ARRIBA	NM	30	N	5	W	21	L	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		1/19/91
300392780900S01	SAN JUAN 30-5 UT 217A FC	RIO ARRIBA	NM	30	N	5	W	21	F	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		9/14/04
300392478800S01	SAN JUAN 30-5 UT 218 FC	RIO ARRIBA	NM	30	N	5	W	17	A	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		2/20/91
300392776800S01	SAN JUAN 30-5 UT 218A FC	RIO ARRIBA	NM	30	N	5	W	17	O	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		11/1/04
300392476800S01	SAN JUAN 30-5 UT 219	RIO ARRIBA	NM	30	N	5	W	16	L	A650363	12001	BASIN CB::FRUITLAND COAL	PM	G		5/23/91
300392748700S01	SAN JUAN 30-5 UT 219A FC	RIO ARRIBA	NM	30	N	5	W	16	C	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		2/25/04
300392664000S01	SAN JUAN 30-5 UT 219R FC	RIO ARRIBA	NM	30	N	5	W	16	L	A650363	12001	BASIN::FRUITLAND COAL	11	G		2/27/01
300392641800S02	SAN JUAN 30-5 UT 21A MV	RIO ARRIBA	NM	30	N	5	W	24	E	A650113	12001	BLANCO::MESAVERDE	11	G		11/9/01
300393071700S01	SAN JUAN 30-5 UT 21M DK	RIO ARRIBA	NM	30	N	5	W	24	N	A713187	12001	BASIN::DAKOTA	61	G	10/26/09	
300393071700S02	SAN JUAN 30-5 UT 21M MV	RIO ARRIBA	NM	30	N	5	W	24	N	A650113	12001	BLANCO::MESAVERDE	11	G	10/12/09	10/12/09
300390784900S01	SAN JUAN 30-5 UT 22 MV	RIO ARRIBA	NM	30	N	5	W	17	G	A650113	12001	BLANCO::MESAVERDE	11	G		
300392985700S01	SAN JUAN 30-5 UT 220A FC	RIO ARRIBA	NM	30	N	5	W	8		A650363	12001	BASIN CB::FRUITLAND COAL	11	G	9/28/06	10/27/06
300392620000S01	SAN JUAN 30-5 UT 220R FC	RIO ARRIBA	NM	30	N	5	W	8	N	A650363	12001	BASIN::FRUITLAND COAL	11	G		4/21/00

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300392620000S01	SAN JUAN 30-5 UT 220R FC	RIO ARRIBA	NM	30	N	5	W	8	N	A650363	12001	BASIN::FRUITLAND COAL	11	G	4/21/00	4/21/00
300392490100S01	SAN JUAN 30-5 UT 223 FC	RIO ARRIBA	NM	30	N	5	W	20	B	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	1/29/93	
300392781300S01	SAN JUAN 30-5 UT 223A FC	RIO ARRIBA	NM	30	N	5	W	20	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	10/8/04	10/8/04
300392490200S01	SAN JUAN 30-5 UT 224 FC	RIO ARRIBA	NM	30	N	5	W	17	L	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	7/10/91	
300392508700S01	SAN JUAN 30-5 UT 225 FC	RIO ARRIBA	NM	30	N	5	W	29	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	6/1/93	
300392496500S01	SAN JUAN 30-5 UT 226 FC	RIO ARRIBA	NM	30	N	5	W	29	M	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	6/18/91	6/18/91
300392921000S01	SAN JUAN 30-5 UT 226A FC	RIO ARRIBA	NM	30	N	5	W	29	C	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	1/26/05	1/26/05
300392489200S01	SAN JUAN 30-5 UT 227 FC	RIO ARRIBA	NM	30	N	5	W	28	A	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	5/23/91	
300392512700S01	SAN JUAN 30-5 UT 228 FC	RIO ARRIBA	NM	30	N	5	W	28	L	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	6/1/93	
300392497900S01	SAN JUAN 30-5 UT 229 FC	RIO ARRIBA	NM	30	N	5	W	21	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	5/20/91	
300392777300S01	SAN JUAN 30-5 UT 229A FC	RIO ARRIBA	NM	31	T	5	W	21	J	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	12/9/04	12/9/04
300392549700C01	SAN JUAN 30-5 UT 22A DK	RIO ARRIBA	NM	30	N	5	W	17	P	A650402	12001	DAKOTA NQ	11	G	11/3/95	
300392549700C02	SAN JUAN 30-5 UT 22A MV	RIO ARRIBA	NM	30	N	5	W	17	P	A650113	12001	BLANCO::MESAVERDE	11	G	10/30/95	
300393009100C01	SAN JUAN 30-5 UT 22F DK	RIO ARRIBA	NM	30	N	5	W	17	I	A650402	12001	BASIN::DAKOTA	11	G	7/18/07	8/28/07
300393009100C02	SAN JUAN 30-5 UT 22F MV	RIO ARRIBA	NM	30	N	5	W	17	I	A650113	12001	BLANCO::MESAVERDE	11	G	7/18/07	8/28/07
300393059700C01	SAN JUAN 30-5 UT 22M DK	RIO ARRIBA	NM	30	N	5	W	17	B	A650402	12001	BASIN::DAKOTA	11	G	6/17/09	7/7/09
300393059700C02	SAN JUAN 30-5 UT 22M MV	RIO ARRIBA	NM	30	N	5	W	17	B	A650113	12001	BLANCO::MESAVERDE	11	G	6/17/09	7/7/09
300390789100S01	SAN JUAN 30-5 UT 23 MV	RIO ARRIBA	NM	30	N	5	W	7	H	A650113	12001	BLANCO::MESAVERDE	11	G		
300392490300S01	SAN JUAN 30-5 UT 230 FC	RIO ARRIBA	NM	30	N	5	W	32	A	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	7/21/92	
300392751300S01	SAN JUAN 30-5 UT 230A FC	RIO ARRIBA	NM	30	N	5	W	32	I	A650363	12001	BASIN CB::FRUITLAND COAL	72	G	12/12/05	5/4/04
300392751400S01	SAN JUAN 30-5 UT 231A FC	RIO ARRIBA	NM	30	N	5	W	32	E	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	3/2/04	3/2/04
300392519400S01	SAN JUAN 30-5 UT 232 FC	RIO ARRIBA	NM	30	N	5	W	33	A	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	12/13/93	
300392517100S01	SAN JUAN 30-5 UT 234 FC	RIO ARRIBA	NM	30	N	5	W	22	M	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	10/19/93	
300392780600S01	SAN JUAN 30-5 UT 234A FC	RIO ARRIBA	NM	30	N	5	W	22	D	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	11/5/04	11/5/04
300392514000S01	SAN JUAN 30-5 UT 235 FC	RIO ARRIBA	NM	30	N	5	W	27	B	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	10/18/93	
300392507700S01	SAN JUAN 30-5 UT 236 FC	RIO ARRIBA	NM	30	N	5	W	27	K	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	10/18/93	
300392511000S01	SAN JUAN 30-5 UT 237 FC	RIO ARRIBA	NM	30	N	5	W	16	B	A650363	12001	BASIN CB::FRUITLAND COAL	72	G	1/12/07	6/2/93
300392511000S01	SAN JUAN 30-5 UT 237 FC	RIO ARRIBA	NM	30	N	5	W	16	B	A650363	12001	BASIN CB::FRUITLAND COAL	72	G	1/12/07	6/2/93
300392511000S01	SAN JUAN 30-5 UT 237 FC	RIO ARRIBA	NM	30	N	5	W	16	B	A650363	12001	BASIN CB::FRUITLAND COAL	72	G	1/12/07	6/2/93
300392748800S01	SAN JUAN 30-5 UT 237A FC	RIO ARRIBA	NM	30	N	5	W	16	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	12/22/03	12/22/03
300392748800S01	SAN JUAN 30-5 UT 237A FC	RIO ARRIBA	NM	30	N	5	W	16	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	12/22/03	12/22/03
300392748800S01	SAN JUAN 30-5 UT 237A FC	RIO ARRIBA	NM	30	N	5	W	16	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	12/22/03	12/22/03
300392748800S01	SAN JUAN 30-5 UT 237A FC	RIO ARRIBA	NM	30	N	5	W	16	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	12/22/03	12/22/03
300392951000S01	SAN JUAN 30-5 UT 237R FC	RIO ARRIBA	NM	30	N	5	W	16	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	11/10/05	11/10/05
300392951000S01	SAN JUAN 30-5 UT 237R FC	RIO ARRIBA	NM	30	N	5	W	16	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	11/10/05	11/10/05
300392951000S01	SAN JUAN 30-5 UT 237R FC	RIO ARRIBA	NM	30	N	5	W	16	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	11/10/05	11/10/05
300392514100S01	SAN JUAN 30-5 UT 238 FC	RIO ARRIBA	NM	30	N	5	W	34	H	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	10/18/93	
300392516500S01	SAN JUAN 30-5 UT 239 FC	RIO ARRIBA	NM	30	N	5	W	15	M	A650363	12001	BASIN::FRUITLAND COAL	11	G	1/11/94	
300392923200S01	SAN JUAN 30-5 UT 239A FC	RIO ARRIBA	NM	30	N	5	W	15	E	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	11/1/05	12/14/05
300390783600S01	SAN JUAN 30-5 UT 24 MV	RIO ARRIBA	NM	30	N	5	W	16	M	A650113	12001	BLANCO::MESAVERDE	11	G		
300392520200S01	SAN JUAN 30-5 UT 240 FC	RIO ARRIBA	NM	30	N	5	W	22	H	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	10/18/93	
300392921900S01	SAN JUAN 30-5 UT 240A FC	RIO ARRIBA	NM	30	N	5	W	22	P	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	12/9/04	12/9/04
300392520300S01	SAN JUAN 30-5 UT 241 FC	RIO ARRIBA	NM	30	N	5	W	23	L	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	10/19/93	
300392924400S01	SAN JUAN 30-5 UT 241A FC	RIO ARRIBA	NM	30	N	5	W	23	E	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	9/12/06	9/12/06
300392516600S01	SAN JUAN 30-5 UT 242 FC	RIO ARRIBA	NM	30	N	5	W	34	L	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	10/15/93	
300392598400S01	SAN JUAN 30-5 UT 243 FC	RIO ARRIBA	NM	30	N	5	W	15	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	12/23/98	12/23/98
300392780500S01	SAN JUAN 30-5 UT 243A FC	RIO ARRIBA	NM	30	N	5	W	15	O	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	12/2/04	12/2/04
300392526500S01	SAN JUAN 30-5 UT 246 FC	RIO ARRIBA	NM	30	N	5	W	26	L	A650363	12001	BASIN::FRUITLAND COAL	11	G	9/20/93	12/21/93

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300392529700S01	SAN JUAN 30-5 UT 247(POW)	RIO ARRIBA	NM	30	N	5	W	26	G	A650385	12001	BASIN::FRUITLAND COAL	72	S	9/30/93	7/28/08
300392923300S01	SAN JUAN 30-5 UT 247R FC	RIO ARRIBA	NM	30	N	5	W	26	A	A650385	12001	BASIN CB::FRUITLAND COAL	11	G	9/6/07	10/3/07
300392529800S01	SAN JUAN 30-5 UT 248(POW)	RIO ARRIBA	NM	30	N	5	W	35	M	A650386	12001	BASIN::FRUITLAND COAL	72	S	7/31/08	11/18/97
300392529800S01	SAN JUAN 30-5 UT 248(POW)	RIO ARRIBA	NM	30	N	5	W	35	M	A650386	12001	BASIN::FRUITLAND COAL	72	S	7/31/08	11/18/97
300392529800S01	SAN JUAN 30-5 UT 248(POW)	RIO ARRIBA	NM	30	N	5	W	35	M	A650386	12001	BASIN::FRUITLAND COAL	72	S	7/31/08	11/18/97
300392529800S01	SAN JUAN 30-5 UT 248(POW)	RIO ARRIBA	NM	30	N	5	W	35	M	A650386	12001	BASIN::FRUITLAND COAL	72	S	7/31/08	11/18/97
300392597200S01	SAN JUAN 30-5 UT 249 FC	RIO ARRIBA	NM	30	N	5	W	23	A	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		11/4/98
300392597200S01	SAN JUAN 30-5 UT 249 FC	RIO ARRIBA	NM	30	N	5	W	23	A	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		11/4/98
300392923000S01	SAN JUAN 30-5 UT 249A FC	RIO ARRIBA	NM	30	N	5	W	23	J	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	8/31/06	10/5/06
300390783500S01	SAN JUAN 30-5 UT 25 MV	RIO ARRIBA	NM	30	N	5	W	17	M	A650113	12001	BLANCO::MESAVERDE	11	G		
300392553200S01	SAN JUAN 30-5 UT 255 FC	RIO ARRIBA	NM	30	N	5	W	14	M	A650363	12001	BASIN::FRUITLAND COAL	11	G		5/24/96
300392922500S01	SAN JUAN 30-5 UT 255A FC	RIO ARRIBA	NM	30	N	5	W	14		A650363	12001	BASIN CB::FRUITLAND COAL	11	G	6/8/06	7/26/06
300392571800S01	SAN JUAN 30-5 UT 257 FC	RIO ARRIBA	NM	30	N	5	W	11	M	A650363	12001	BASIN::FRUITLAND COAL	11	G		10/17/97
300392922600S01	SAN JUAN 30-5 UT 257A FC	RIO ARRIBA	NM	30	N	5	W	11	F	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	9/18/06	10/25/06
300392569900S01	SAN JUAN 30-5 UT 258 FC	RIO ARRIBA	NM	30	N	5	W	14	G	A650363	12001	BASIN::FRUITLAND COAL	11	G		10/31/97
300392922800S01	SAN JUAN 30-5 UT 258A FC	RIO ARRIBA	NM	30	N	5	W	14		A650363	12001	BASIN CB::FRUITLAND COAL	11	G	6/21/06	8/24/06
300392570500S01	SAN JUAN 30-5 UT 259 FC	RIO ARRIBA	NM	30	N	5	W	13	M	A650363	12001	BASIN::FRUITLAND COAL	11	G		9/7/99
300392570500S01	SAN JUAN 30-5 UT 259 FC	RIO ARRIBA	NM	30	N	5	W	13	M	A650363	12001	BASIN::FRUITLAND COAL	11	G		9/7/99
300392922700S01	SAN JUAN 30-5 UT 259A FC	RIO ARRIBA	NM	30	N	5	W	13	F	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	9/15/06	10/25/06
300392598100S01	SAN JUAN 30-5 UT 260 FC	RIO ARRIBA	NM	30	N	5	W	9	L	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		11/25/98
300392598100S01	SAN JUAN 30-5 UT 260 FC	RIO ARRIBA	NM	30	N	5	W	9	L	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		11/25/98
300392725600S01	SAN JUAN 30-5 UT 260A FC	RIO ARRIBA	NM	30	N	5	W	9	F	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		4/23/03
300392596300S01	SAN JUAN 30-5 UT 261 FC	RIO ARRIBA	NM	30	N	5	W	11	B	A650363	12001	BASIN::FRUITLAND COAL	11	G		9/15/99
300392596300S01	SAN JUAN 30-5 UT 261 FC	RIO ARRIBA	NM	30	N	5	W	11	B	A650363	12001	BASIN::FRUITLAND COAL	11	G		9/15/99
300392922400S01	SAN JUAN 30-5 UT 261A FC	RIO ARRIBA	NM	30	N	5	W	11	J	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	9/15/06	10/25/06
300392595900S01	SAN JUAN 30-5 UT 262 FC	RIO ARRIBA	NM	30	N	5	W	12	K	A650363	12001	BASIN::FRUITLAND COAL	11	G		9/7/99
300392598200S01	SAN JUAN 30-5 UT 263 FC	RIO ARRIBA	NM	30	N	5	W	13	G	A650363	12001	BASIN::FRUITLAND COAL	11	G		11/23/99
300392598200S01	SAN JUAN 30-5 UT 263 FC	RIO ARRIBA	NM	30	N	5	W	13	G	A650363	12001	BASIN::FRUITLAND COAL	11	G		11/23/99
300392922300S01	SAN JUAN 30-5 UT 263A FC	RIO ARRIBA	NM	30	N	5	W	13	J	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	11/17/05	11/17/05
300392604900S01	SAN JUAN 30-5 UT 264 FC	RIO ARRIBA	NM	30	N	5	W	9	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		4/8/99
300392604900S01	SAN JUAN 30-5 UT 264 FC	RIO ARRIBA	NM	30	N	5	W	9	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		4/8/99
300392777200S01	SAN JUAN 30-5 UT 264A FC	RIO ARRIBA	NM	30	N	5	W	9	O	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		12/6/04
300392630300S01	SAN JUAN 30-5 UT 265 FC	RIO ARRIBA	NM	30	N	5	W	10	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		5/16/00
300392630300S01	SAN JUAN 30-5 UT 265 FC	RIO ARRIBA	NM	30	N	5	W	10	G	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		5/16/00
300392777100S01	SAN JUAN 30-5 UT 265A FC	RIO ARRIBA	NM	30	N	5	W	10	O	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		11/1/04
300392630200S01	SAN JUAN 30-5 UT 266 FC	RIO ARRIBA	NM	30	N	5	W	10	M	A650363	12001	BASIN::FRUITLAND COAL	11	G		4/4/00
300392630200S01	SAN JUAN 30-5 UT 266 FC	RIO ARRIBA	NM	30	N	5	W	10	M	A650363	12001	BASIN::FRUITLAND COAL	11	G		4/4/00
300392725400S01	SAN JUAN 30-5 UT 266A FC	RIO ARRIBA	NM	30	N	5	W	10	E	A650363	12001	BASIN CB::FRUITLAND COAL	11	G		3/28/03
300392651400S01	SAN JUAN 30-5 UT 267 FC	RIO ARRIBA	NM	30	N	5	W	24	G	A650363	12001	BASIN::FRUITLAND COAL	11	G		7/24/02
300392651400S01	SAN JUAN 30-5 UT 267 FC	RIO ARRIBA	NM	30	N	5	W	24	G	A650363	12001	BASIN::FRUITLAND COAL	11	G		7/24/02
300392924300C02	SAN JUAN 30-5 UT 267A FC	RIO ARRIBA	NM	30	N	5	W	24	O	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	8/23/06	6/30/08
300392924300C01	SAN JUAN 30-5 UT 267A PC	RIO ARRIBA	NM	30	N	5	W	24	O	A710570	12001	GOBERNADOR:PICTURED CLIFF	11	G	8/23/06	9/25/06
300392924300C01	SAN JUAN 30-5 UT 267A PC	RIO ARRIBA	NM	30	N	5	W	24	O	A710570	12001	GOBERNADOR:PICTURED CLIFF	11	G	8/23/06	9/25/06
300392650800S01	SAN JUAN 30-5 UT 268 FC	RIO ARRIBA	NM	30	N	5	W	24	K	A650363	12001	BASIN::FRUITLAND COAL	11	G		11/1/01
300392650800S01	SAN JUAN 30-5 UT 268 FC	RIO ARRIBA	NM	30	N	5	W	24	K	A650363	12001	BASIN::FRUITLAND COAL	11	G		11/1/01
300392925000S01	SAN JUAN 30-5 UT 268A FC	RIO ARRIBA	NM	30	N	5	W	24	F	A650363	12001	BASIN CB::FRUITLAND COAL	11	G	7/1/06	9/13/06
300392925100S01	SAN JUAN 30-5 UT 269 FC	RIO ARRIBA	NM	30	N	5	W	25	D	A709618	12001	BASIN CB::FRUITLAND COAL	72	G	10/11/07	10/7/07
300390779200C01	SAN JUAN 30-5 UT 27 DK	RIO ARRIBA	NM	30	N	5	W	20	M	A650319	12001	BASIN::DAKOTA	71	G	9/27/59	9/27/59
300390779200C01	SAN JUAN 30-5 UT 27 DK	RIO ARRIBA	NM	30	N	5	W	20	M	A650319	12001	BASIN::DAKOTA	71	G	9/27/59	9/27/59
300390779200S02	SAN JUAN 30-5 UT 27 MV	RIO ARRIBA	NM	30	N	5	W	20	M	A650113	12001	BLANCO::MESAVERDE	11	G	9/27/59	9/27/59

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsrv Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300393012800C01	SAN JUAN 30-5 UT 27F DK	RIO ARRIBA	NM	30	N	5	W	20	C	A650402	12001	BASIN::DAKOTA	11	G	6/17/09	6/8/09
300393012800C02	SAN JUAN 30-5 UT 27F MV	RIO ARRIBA	NM	30	N	5	W	20	C	A650113	12001	BLANCO::MESAVERDE	11	G	6/17/09	6/8/09
300392566900C01	SAN JUAN 30-5 UT 27M DK	RIO ARRIBA	NM	30	N	5	W	20	C	A650402	12001	DAKOTA NQ	11	G		8/5/97
300392566900C01	SAN JUAN 30-5 UT 27M DK	RIO ARRIBA	NM	30	N	5	W	20	C	A650402	12001	DAKOTA NQ	11	G		8/5/97
300392566900C02	SAN JUAN 30-5 UT 27M MV	RIO ARRIBA	NM	30	N	5	W	20	C	A650113	12001	BLANCO::MESAVERDE	11	G		4/14/98
300393087500C01	SAN JUAN 30-5 UT 27N DK	RIO ARRIBA	NM	30	N	5	W	20	L	A650402	12001	BASIN::DAKOTA	11	G	7/30/10	8/20/10
300393087500C02	SAN JUAN 30-5 UT 27N MV	RIO ARRIBA	NM	30	N	5	W	20	L	A650113	12001	BLANCO::MESAVERDE	11	G	7/30/10	8/20/10
300390782000S01	SAN JUAN 30-5 UT 28X MV	RIO ARRIBA	NM	30	N	5	W	23	A	A650113	12001	BLANCO::MESAVERDE	11	G		
300390785100S01	SAN JUAN 30-5 UT 29 MV	RIO ARRIBA	NM	30	N	5	W	14	G	A650113	12001	BLANCO::MESAVERDE	11	G		
300392570700S01	SAN JUAN 30-5 UT 29A DK	RIO ARRIBA	NM	30	N	5	W	14	P	A650402	12001	DAKOTA NQ	11	G	10/28/97	10/28/97
300392570700S01	SAN JUAN 30-5 UT 29A DK	RIO ARRIBA	NM	30	N	5	W	14	P	A650402	12001	DAKOTA NQ	11	G	10/28/97	10/28/97
300392677600C01	SAN JUAN 30-5 UT 29B DK	RIO ARRIBA	NM	30	N	5	W	14	O	A650402	12001	BASIN::DAKOTA	11	G		8/7/03
300392677600C02	SAN JUAN 30-5 UT 29B MV	RIO ARRIBA	NM	30	N	5	W	14	O	A650113	12001	BLANCO::MESAVERDE	11	G		8/7/03
300392677700C01	SAN JUAN 30-5 UT 29M DK	RIO ARRIBA	NM	30	N	5	W	14	H	A650402	12001	BASIN::DAKOTA	11	G		8/21/03
300392677700C02	SAN JUAN 30-5 UT 29M MV	RIO ARRIBA	NM	30	N	5	W	14	H	A650113	12001	BLANCO::MESAVERDE	11	G		8/21/03
300392114800S01	SAN JUAN 30-5 UT 2R MV	RIO ARRIBA	NM	30	N	5	W	29	H	A650113	12001	BLANCO::MESAVERDE	11	G		
300390779900S01	SAN JUAN 30-5 UT 30 MV	RIO ARRIBA	NM	30	N	5	W	21	L	A650113	12001	BLANCO::MESAVERDE	11	G		
300390776100S01	SAN JUAN 30-5 UT 31 MV	RIO ARRIBA	NM	30	N	5	W	27	L	A650113	12001	BLANCO::MESAVERDE	11	G		
300390782200S01	SAN JUAN 30-5 UT 33 MV	RIO ARRIBA	NM	30	N	5	W	20	A	A650113	12001	BLANCO::MESAVERDE	11	G		
300390777800S01	SAN JUAN 30-5 UT 34 MV	RIO ARRIBA	NM	30	N	5	W	27	A	A650113	12001	BLANCO::MESAVERDE	11	G		
300390788400S01	SAN JUAN 30-5 UT 35 MV	RIO ARRIBA	NM	30	N	5	W	7	K	A650113	12001	BLANCO::MESAVERDE	11	G		
300392052400S01	SAN JUAN 30-5 UT 36 MV	RIO ARRIBA	NM	30	N	5	W	30	M	A650113	12001	BLANCO::MESAVERDE	11	G	8/23/72	
300392078200C01	SAN JUAN 30-5 UT 37 DK	RIO ARRIBA	NM	30	N	5	W	8	K	A650402	12001	DAKOTA NQ	11	G		
300392078200C02	SAN JUAN 30-5 UT 37 MV	RIO ARRIBA	NM	30	N	5	W	8	K	A650113	12001	BLANCO::MESAVERDE	11	G		8/12/97
300392955200C01	SAN JUAN 30-5 UT 37G DK	RIO ARRIBA	NM	30	N	5	W	8		A650402	12001	BASIN::DAKOTA	11	G	8/30/06	10/4/06
300392955200C02	SAN JUAN 30-5 UT 37G MV	RIO ARRIBA	NM	30	N	5	W	8		A650113	12001	BLANCO::MESAVERDE	11	G	8/30/06	10/4/06
300392724800C01	SAN JUAN 30-5 UT 37M DK	RIO ARRIBA	NM	30	N	5	W	8	C	A650402	12001	BASIN::DAKOTA	11	G	5/10/06	7/10/06
300392724800C01	SAN JUAN 30-5 UT 37M DK	RIO ARRIBA	NM	30	N	5	W	8	C	A650402	12001	BASIN::DAKOTA	11	G	5/10/06	7/10/06
300392724800C02	SAN JUAN 30-5 UT 37M MV	RIO ARRIBA	NM	30	N	5	W	8	C	A650113	12001	BLANCO::MESAVERDE	11	G	5/10/06	7/10/06
300392215900S01	SAN JUAN 30-5 UT 38 DK	RIO ARRIBA	NM	30	N	5	W	18	G	A650402	12001	DAKOTA LP	11	G		
300392215900S01	SAN JUAN 30-5 UT 38 DK	RIO ARRIBA	NM	30	N	5	W	18	G	A650402	12001	DAKOTA LP	11	G		
300392990600C01	SAN JUAN 30-5 UT 38M DK	RIO ARRIBA	NM	30	N	5	W	18	P	A650402	12001	BASIN::DAKOTA	11	G	11/29/06	12/14/06
300392990600C02	SAN JUAN 30-5 UT 38M MV	RIO ARRIBA	NM	30	N	5	W	18	P	A650113	12001	BLANCO::MESAVERDE	11	G	11/29/06	12/14/06
300393089200C01	SAN JUAN 30-5 UT 38P DK	RIO ARRIBA	NM	30	N	5	W	18	O	A650402	12001	BASIN::DAKOTA	11	G	8/16/10	11/3/10
300393089200C02	SAN JUAN 30-5 UT 38P MV	RIO ARRIBA	NM	30	N	5	W	18	O	A650113	12001	BLANCO::MESAVERDE	11	G	8/16/10	
300392107200C01	SAN JUAN 30-5 UT 39 DK	RIO ARRIBA	NM	30	N	5	W	7	G	A650402	12001	DAKOTA NQ	11	G		
300392107200C01	SAN JUAN 30-5 UT 39 DK	RIO ARRIBA	NM	30	N	5	W	7	G	A650402	12001	DAKOTA NQ	11	G		
300392107200C02	SAN JUAN 30-5 UT 39 MV	RIO ARRIBA	NM	30	N	5	W	7	G	A650113	12001	BLANCO::MESAVERDE	11	G		12/16/02
300390774500S01	SAN JUAN 30-5 UT 4 MV	RIO ARRIBA	NM	30	N	5	W	35	B	A650113	12001	BLANCO::MESAVERDE	11	G		
300392102600S01	SAN JUAN 30-5 UT 40 MV	RIO ARRIBA	NM	30	N	5	W	33	N	A650113	12001	BLANCO::MESAVERDE	11	G		
300392102700S01	SAN JUAN 30-5 UT 41 MV	RIO ARRIBA	NM	30	N	5	W	32	H	A650113	12001	BLANCO::MESAVERDE	11	G		
300392267800S01	SAN JUAN 30-5 UT 41A MV	RIO ARRIBA	NM	30	N	5	W	32	I	A650113	12001	BLANCO::MESAVERDE	11	G		
300392114100S01	SAN JUAN 30-5 UT 43 MV	RIO ARRIBA	NM	30	N	5	W	5	M	A650113	12001	BLANCO::MESAVERDE	11	G		
300392114200S01	SAN JUAN 30-5 UT 44 MV	RIO ARRIBA	NM	30	N	5	W	6	L	A650113	12001	BLANCO::MESAVERDE	11	G		
300392114300S01	SAN JUAN 30-5 UT 45 MV	RIO ARRIBA	NM	30	N	5	W	15	M	A650113	12001	BLANCO::MESAVERDE	11	G		
300392114400S01	SAN JUAN 30-5 UT 46 MV	RIO ARRIBA	NM	30	N	5	W	36	G	A650113	12001	BLANCO::MESAVERDE	11	G		
300392107000S01	SAN JUAN 30-5 UT 47 DK	RIO ARRIBA	NM	30	N	5	W	17	L	A650402	12001	DAKOTA NQ	11	G		7/13/77
300392107000S01	SAN JUAN 30-5 UT 47 DK	RIO ARRIBA	NM	30	N	5	W	17	L	A650402	12001	DAKOTA NQ	11	G		7/13/77

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300393016500C01	SAN JUAN 30-5 UT 47G DK	RIO ARRIBA	NM	30	N	5	W	17	D	A650402	12001	BASIN::DAKOTA	11	G	10/22/07	11/14/07
300393016500C02	SAN JUAN 30-5 UT 47G MV	RIO ARRIBA	NM	30	N	5	W	17	D	A650113	12001	BLANCO::MESAVERDE	11	G	10/22/07	11/14/07
300392567800C01	SAN JUAN 30-5 UT 47M DK	RIO ARRIBA	NM	30	N	5	W	17	F	A650402	12001	DAKOTA NQ	11	G	8/5/97	8/5/97
300392567800C02	SAN JUAN 30-5 UT 47M MV	RIO ARRIBA	NM	30	N	5	W	17	F	A650113	12001	BLANCO::MESAVERDE	11	G	5/8/98	5/8/98
300392181300C01	SAN JUAN 30-5 UT 48 DK	RIO ARRIBA	NM	30	N	5	W	20	B	A650402	12001	DAKOTA LP	11	G		
300392181300C01	SAN JUAN 30-5 UT 48 DK	RIO ARRIBA	NM	30	N	5	W	20	B	A650402	12001	DAKOTA LP	11	G		
300392181300C02	SAN JUAN 30-5 UT 48 MV	RIO ARRIBA	NM	30	N	5	W	20	B	A650113	12001	BLANCO::MESAVERDE	11	G	1/9/03	1/9/03
300392636700C01	SAN JUAN 30-5 UT 48M DK	RIO ARRIBA	NM	30	N	5	W	20	I	A650402	12001	BASIN::DAKOTA	11	G	6/28/00	6/28/00
300392636700C02	SAN JUAN 30-5 UT 48M MV	RIO ARRIBA	NM	30	N	5	W	20	I	A650113	12001	BLANCO::MESAVERDE	11	G	12/14/00	12/14/00
300393082900C01	SAN JUAN 30-5 UT 48N DK	RIO ARRIBA	NM	30	N	5	W	20	P	A650402	12001	BASIN::DAKOTA	11	G	7/6/10	8/11/10
300393082900C02	SAN JUAN 30-5 UT 48N MV	RIO ARRIBA	NM	30	N	5	W	20	P	A650113	12001	BLANCO::MESAVERDE	11	G	7/6/10	8/11/10
300392183000C01	SAN JUAN 30-5 UT 49 DK	RIO ARRIBA	NM	30	N	5	W	9	M	A650402	12001	DAKOTA LP	11	G		
300392183000C01	SAN JUAN 30-5 UT 49 DK	RIO ARRIBA	NM	30	N	5	W	9	M	A650402	12001	DAKOTA LP	11	G		
300392183000C02	SAN JUAN 30-5 UT 49 MV	RIO ARRIBA	NM	30	N	5	W	9	M	A650113	12001	BLANCO::MESAVERDE	11	G	7/25/97	7/25/97
300392680300C01	SAN JUAN 30-5 UT 49M DK	RIO ARRIBA	NM	30	N	5	W	9	D	A650402	12001	BASIN::DAKOTA	11	G	5/6/02	5/6/02
300392680300C02	SAN JUAN 30-5 UT 49M MV	RIO ARRIBA	NM	30	N	5	W	9	D	A650113	12001	BLANCO::MESAVERDE	11	G	12/16/02	12/16/02
300393073200C01	SAN JUAN 30-5 UT 49N DK	RIO ARRIBA	NM	30	N	5	W	9	K	A650402	12001	BASIN::DAKOTA	11	G	8/29/09	10/29/09
300393073200C02	SAN JUAN 30-5 UT 49N MV	RIO ARRIBA	NM	30	N	5	W	9	K	A650113	12001	BLANCO::MESAVERDE	11	G	8/29/09	10/29/09
300393090000C01	SAN JUAN 30-5 UT 49P DK	RIO ARRIBA	NM	30	N	5	W	9	D	A650402	12001	BASIN::DAKOTA	11	G	11/5/10	11/11/10
300393090000C02	SAN JUAN 30-5 UT 49P MV	RIO ARRIBA	NM	30	N	5	W	9	D	A650113	12001	BLANCO::MESAVERDE	11	G	11/5/10	11/11/10
300392257100C01	SAN JUAN 30-5 UT 50 DK	RIO ARRIBA	NM	30	N	5	W	6	M	A650402	12001	DAKOTA LP	11	G		
300392257100C01	SAN JUAN 30-5 UT 50 DK	RIO ARRIBA	NM	30	N	5	W	6	M	A650402	12001	DAKOTA LP	11	G		
300392257100C02	SAN JUAN 30-5 UT 50 MV	RIO ARRIBA	NM	30	N	5	W	6	M	A650113	12001	BLANCO::MESAVERDE	11	G	1/2/03	1/2/03
300393010700C01	SAN JUAN 30-5 UT 50G DK	RIO ARRIBA	NM	30	N	5	W	6	I	A650402	12001	BASIN::DAKOTA	11	G	10/12/07	11/13/07
300393010700C02	SAN JUAN 30-5 UT 50G MV	RIO ARRIBA	NM	30	N	5	W	6	I	A650113	12001	BLANCO::MESAVERDE	11	G	10/12/07	11/13/07
300392708500C01	SAN JUAN 30-5 UT 50M DK	RIO ARRIBA	NM	30	N	5	W	6	P	A650402	12001	BASIN::DAKOTA	11	G	6/5/04	7/7/04
300392708500C01	SAN JUAN 30-5 UT 50M DK	RIO ARRIBA	NM	30	N	5	W	6	P	A650402	12001	BASIN::DAKOTA	11	G	6/5/04	7/7/04
300392708500C02	SAN JUAN 30-5 UT 50M MV	RIO ARRIBA	NM	30	N	5	W	6	P	A650113	12001	BLANCO::MESAVERDE	11	G	6/5/04	7/7/04
300392244700S01	SAN JUAN 30-5 UT 51 DK	RIO ARRIBA	NM	30	N	5	W	21	B	A650402	12001	DAKOTA LP	11	G		
300392244700S01	SAN JUAN 30-5 UT 51 DK	RIO ARRIBA	NM	30	N	5	W	21	B	A650402	12001	DAKOTA LP	11	G		
300392638100C01	SAN JUAN 30-5 UT 51M DK	RIO ARRIBA	NM	30	N	5	W	21	I	A650402	12001	BASIN::DAKOTA	11	G	6/22/00	6/22/00
300392638100C02	SAN JUAN 30-5 UT 51M MV	RIO ARRIBA	NM	30	N	5	W	21	I	A650113	12001	BLANCO::MESAVERDE	11	G	12/7/00	12/7/00
300393092000C01	SAN JUAN 30-5 UT 51N DK	RIO ARRIBA	NM	30	N	5	W	21	N	A650402	12001	BASIN::DAKOTA	11	G	8/13/10	8/30/10
300393092000C02	SAN JUAN 30-5 UT 51N MV	RIO ARRIBA	NM	30	N	5	W	21	N	A650113	12001	BLANCO::MESAVERDE	11	G	8/13/10	8/30/10
300392257400C01	SAN JUAN 30-5 UT 52 DK	RIO ARRIBA	NM	30	N	5	W	15	N	A650402	12001	DAKOTA LP	11	G		
300392257400C01	SAN JUAN 30-5 UT 52 DK	RIO ARRIBA	NM	30	N	5	W	15	N	A650402	12001	DAKOTA LP	11	G		
300392257400C02	SAN JUAN 30-5 UT 52 MV	RIO ARRIBA	NM	30	N	5	W	15	N	A650113	12001	BLANCO::MESAVERDE	11	G	12/19/02	12/19/02
300392567700C01	SAN JUAN 30-5 UT 52M DK	RIO ARRIBA	NM	30	N	5	W	15	I	A650402	12001	BASIN::DAKOTA	99	G	5/22/97	5/22/97
300392567700C01	SAN JUAN 30-5 UT 52M DK	RIO ARRIBA	NM	30	N	5	W	15	I	A650402	12001	DAKOTA NQ	11	G	5/22/97	5/22/97
300392567700C02	SAN JUAN 30-5 UT 52M MV	RIO ARRIBA	NM	30	N	5	W	15	I	A650113	12001	BLANCO::MESAVERDE	11	G	4/23/98	4/23/98
300393064800C01	SAN JUAN 30-5 UT 52N DK	RIO ARRIBA	NM	30	N	5	W	15	O	A650402	12001	BASIN::DAKOTA	11	G	7/9/09	6/19/09
300393064800C02	SAN JUAN 30-5 UT 52N MV	RIO ARRIBA	NM	30	N	5	W	15	O	A650113	12001	BLANCO::MESAVERDE	11	G	7/9/09	6/19/09
300392241200C01	SAN JUAN 30-5 UT 53 DK	RIO ARRIBA	NM	30	N	5	W	16	L	A650402	12001	DAKOTA LP	11	G		
300392241200C01	SAN JUAN 30-5 UT 53 DK	RIO ARRIBA	NM	30	N	5	W	16	L	A650402	12001	DAKOTA LP	11	G		
300392241200C02	SAN JUAN 30-5 UT 53 MV	RIO ARRIBA	NM	30	N	5	W	16	L	A650113	12001	BLANCO::MESAVERDE	11	G	1/13/03	1/13/03
300392515500C01	SAN JUAN 30-5 UT 53E DK	RIO ARRIBA	NM	30	N	5	W	16	I	A650402	12001	DAKOTA NQ	11	G	3/1/94	
300392515500C02	SAN JUAN 30-5 UT 53E MV	RIO ARRIBA	NM	30	N	5	W	16	I	A650113	12001	BLANCO::MESAVERDE	11	G	6/4/97	6/4/97
300393098200C01	SAN JUAN 30-5 UT 53M DK	RIO ARRIBA	NM	30	N	5	W	16	J	A650402	12001	BASIN::DAKOTA	11	G	11/5/10	11/16/10
300393098200C02	SAN JUAN 30-5 UT 53M MV	RIO ARRIBA	NM	30	N	5	W	16	J	A650113	12001	BLANCO::MESAVERDE	11	G	11/5/10	11/16/10

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300392114700S01	SAN JUAN 30-5 UT 54 MV	RIO ARRIBA	NM	30	N	5	W	28	L	A650113	12001	BLANCO::MESAVERDE	11	G		
300392129400S01	SAN JUAN 30-5 UT 56 MV	RIO ARRIBA	NM	30	N	5	W	22	M	A650113	12001	BLANCO::MESAVERDE	11	G		
300392127600S01	SAN JUAN 30-5 UT 57 MV	RIO ARRIBA	NM	30	N	5	W	28	A	A650113	12001	BLANCO::MESAVERDE	11	G		
300392127700S01	SAN JUAN 30-5 UT 58 MV	RIO ARRIBA	NM	30	N	5	W	36	M	A650113	12001	BLANCO::MESAVERDE	11	G		
300392149300S01	SAN JUAN 30-5 UT 60 MV	RIO ARRIBA	NM	30	N	5	W	5	H	A650113	12001	BLANCO::MESAVERDE	11	G		
300392371700S01	SAN JUAN 30-5 UT 61 MV	RIO ARRIBA	NM	30	N	5	W	15	A	A650113	12001	BLANCO::MESAVERDE	11	G		
300392149400S01	SAN JUAN 30-5 UT 62 MV	RIO ARRIBA	NM	30	N	5	W	21	G	A650113	12001	BLANCO::MESAVERDE	11	G	10/25/77	
300392149400S02	SAN JUAN 30-5 UT 62 PC	RIO ARRIBA	NM	30	N	5	W	21	G	A650110	12001	GOBERNADOR:PICTURED CLIFF	11	G		12/7/05
300392149400S02	SAN JUAN 30-5 UT 62 PC	RIO ARRIBA	NM	30	N	5	W	21	G	A650110	12001	GOBERNADOR:PICTURED CLIFF	11	G		12/7/05
300392149400S02	SAN JUAN 30-5 UT 62 PC	RIO ARRIBA	NM	30	N	5	W	21	G	A650110	12001	GOBERNADOR:PICTURED CLIFF	11	G		12/7/05
300392179100S01	SAN JUAN 30-5 UT 63 PC	RIO ARRIBA	NM	30	N	5	W	31	N	A650110	12001	GOBERNADOR:PICTURED CLIFF	11	G		
300392165400S01	SAN JUAN 30-5 UT 68 MV	RIO ARRIBA	NM	30	N	5	W	25	L	A650113	12001	BLANCO::MESAVERDE	11	G		
300390775400S01	SAN JUAN 30-5 UT 7 MV	RIO ARRIBA	NM	30	N	5	W	29	M	A650113	12001	BLANCO::MESAVERDE	11	G	3/19/54	
300392246200C01	SAN JUAN 30-5 UT 70 DK	RIO ARRIBA	NM	30	N	5	W	9	A	A650402	12001	DAKOTA LP	11	G		
300392246200C01	SAN JUAN 30-5 UT 70 DK	RIO ARRIBA	NM	30	N	5	W	9	A	A650402	12001	DAKOTA LP	11	G		
300392246200C02	SAN JUAN 30-5 UT 70 MV	RIO ARRIBA	NM	30	N	5	W	9	A	A650113	12001	BLANCO::MESAVERDE	11	G		11/23/98
300392246200C02	SAN JUAN 30-5 UT 70 MV	RIO ARRIBA	NM	30	N	5	W	9	A	A650113	12001	BLANCO::MESAVERDE	11	G		11/23/98
300392602800C01	SAN JUAN 30-5 UT 70E DK	RIO ARRIBA	NM	30	N	5	W	9	O	A650402	12001	DAKOTA NQ	11	G		5/19/99
300392602800C02	SAN JUAN 30-5 UT 70E MV	RIO ARRIBA	NM	30	N	5	W	9	O	A650113	12001	BLANCO::MESAVERDE	11	G		1/11/00
300393009600C01	SAN JUAN 30-5 UT 70F DK	RIO ARRIBA	NM	30	N	5	W	9	G	A650402	12001	BASIN::DAKOTA	11	G	9/24/07	10/8/07
300393009600C02	SAN JUAN 30-5 UT 70F MV	RIO ARRIBA	NM	30	N	5	W	9	G	A650113	12001	BLANCO::MESAVERDE	11	G	9/24/07	10/8/07
300392247600S01	SAN JUAN 30-5 UT 71 DK	RIO ARRIBA	NM	30	N	5	W	22	M	A650402	12001	DAKOTA LP	11	G		12/16/80
300392247600S01	SAN JUAN 30-5 UT 71 DK	RIO ARRIBA	NM	30	N	5	W	22	M	A650402	12001	DAKOTA LP	11	G		12/16/80
300393036600C01	SAN JUAN 30-5 UT 71F DK	RIO ARRIBA	NM	30	N	5	W	22	C	A650402	12001	BASIN::DAKOTA	11	G	6/3/09	6/2/09
300393036600C02	SAN JUAN 30-5 UT 71F MV	RIO ARRIBA	NM	30	N	5	W	22	C	A650113	12001	BLANCO::MESAVERDE	11	G	6/3/09	6/16/09
300392602900C01	SAN JUAN 30-5 UT 71M DK	RIO ARRIBA	NM	30	N	5	W	22	D	A650402	12001	DAKOTA NQ	11	G		6/3/99
300392602900C02	SAN JUAN 30-5 UT 71M MV	RIO ARRIBA	NM	30	N	5	W	22	D	A650113	12001	BLANCO::MESAVERDE	11	G		12/30/99
300392257300C01	SAN JUAN 30-5 UT 72 DK	RIO ARRIBA	NM	30	N	5	W	10	M	A650402	12001	DAKOTA LP	11	G		4/13/81
300392257300C01	SAN JUAN 30-5 UT 72 DK	RIO ARRIBA	NM	30	N	5	W	10	M	A650402	12001	DAKOTA LP	11	G		4/13/81
300392257300C02	SAN JUAN 30-5 UT 72 MV	RIO ARRIBA	NM	30	N	5	W	10	M	A650113	12001	BLANCO::MESAVERDE	11	G		7/22/97
300392257300C02	SAN JUAN 30-5 UT 72 MV	RIO ARRIBA	NM	30	N	5	W	10	M	A650113	12001	BLANCO::MESAVERDE	11	G		7/22/97
300392567600C01	SAN JUAN 30-5 UT 72E DK	RIO ARRIBA	NM	30	N	5	W	10	O	A650402	12001	DAKOTA NQ	11	G	7/11/97	7/11/97
300392567600C02	SAN JUAN 30-5 UT 72E MV	RIO ARRIBA	NM	30	N	5	W	10	O	A650113	12001	BLANCO::MESAVERDE	11	G	12/14/98	12/14/98
300392567600C02	SAN JUAN 30-5 UT 72E MV	RIO ARRIBA	NM	30	N	5	W	10	O	A650113	12001	BLANCO::MESAVERDE	11	G	12/14/98	12/14/98
300393064400C01	SAN JUAN 30-5 UT 72M DK	RIO ARRIBA	NM	30	N	5	W	10	P	A650402	12001	BASIN::DAKOTA	11	G	7/28/09	7/13/09
300393064400C02	SAN JUAN 30-5 UT 72M MV	RIO ARRIBA	NM	30	N	5	W	10	P	A650113	12001	BLANCO::MESAVERDE	11	G	7/28/09	7/13/09
300392257200C01	SAN JUAN 30-5 UT 73 DK	RIO ARRIBA	NM	30	N	5	W	10	B	A650402	12001	DAKOTA LP	11	G	3/31/81	3/31/81
300392257200C01	SAN JUAN 30-5 UT 73 DK	RIO ARRIBA	NM	30	N	5	W	10	B	A650402	12001	DAKOTA LP	11	G	3/31/81	3/31/81
300392257200C02	SAN JUAN 30-5 UT 73 MV	RIO ARRIBA	NM	30	N	5	W	10	B	A650113	12001	BLANCO::MESAVERDE	11	G	11/17/98	11/17/98
300392257200C02	SAN JUAN 30-5 UT 73 MV	RIO ARRIBA	NM	30	N	5	W	10	B	A650113	12001	BLANCO::MESAVERDE	11	G	11/17/98	11/25/98
300393011400C01	SAN JUAN 30-5 UT 73G DK	RIO ARRIBA	NM	30	N	5	W	10	F	A650402	12001	BASIN::DAKOTA	11	G	9/13/07	10/22/07
300393011400C02	SAN JUAN 30-5 UT 73G MV	RIO ARRIBA	NM	30	N	5	W	10	F	A650113	12001	BLANCO::MESAVERDE	11	G	9/13/07	10/22/07
300392680100C01	SAN JUAN 30-5 UT 73M DK	RIO ARRIBA	NM	30	N	5	W	10	D	A650402	12001	BASIN::DAKOTA	11	G		5/9/02
300392680100C02	SAN JUAN 30-5 UT 73M MV	RIO ARRIBA	NM	30	N	5	W	10	D	A650113	12001	BLANCO::MESAVERDE	11	G		12/23/02
300393037400C01	SAN JUAN 30-5 UT 73N DK	RIO ARRIBA	NM	30	N	5	W	10	G	A650402	12001	BASIN::DAKOTA	11	G	5/5/09	7/7/09
300393037400C02	SAN JUAN 30-5 UT 73N MV	RIO ARRIBA	NM	30	N	5	W	10	G	A650113	12001	BLANCO::MESAVERDE	11	G	5/5/09	7/7/09
300392275400C01	SAN JUAN 30-5 UT 74 MV	RIO ARRIBA	NM	30	N	5	W	34	K	A650113	12001	BLANCO::MESAVERDE	11	G		
300392275400C02	SAN JUAN 30-5 UT 74 PC	RIO ARRIBA	NM	30	N	5	W	34	K	A650110	12001	GOBERNADOR:PICTURED CLIFF	11	G		
300392270800S01	SAN JUAN 30-5 UT 75 DK	RIO ARRIBA	NM	30	N	5	W	21	L	A650402	12001	DAKOTA LP	11	G		

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300392270800S01	SAN JUAN 30-5 UT 75 DK	RIO ARRIBA	NM	30	N	5	W 21	L	A650402	12001	DAKOTA LP	11	G			
300393012500C01	SAN JUAN 30-5 UT 75F DK	RIO ARRIBA	NM	30	N	5	W 21	C	A650402	12001	BASIN::DAKOTA	11	G	11/12/07	11/26/07	11/26/07
300393012500C02	SAN JUAN 30-5 UT 75F MV	RIO ARRIBA	NM	30	N	5	W 21	C	A650113	12001	BLANCO::MESAVERDE	11	G	11/12/07	11/26/07	11/26/07
300392565900C01	SAN JUAN 30-5 UT 75M DK	RIO ARRIBA	NM	30	N	5	W 21	E	A650402	12001	DAKOTA NQ	11	G		6/23/97	6/23/97
300392565900C02	SAN JUAN 30-5 UT 75M MV	RIO ARRIBA	NM	30	N	5	W 21	E	A650113	12001	BLANCO::MESAVERDE	11	G		4/15/98	4/15/98
300393064300C01	SAN JUAN 30-5 UT 75N DK	RIO ARRIBA	NM	30	N	5	W 21	N	A650402	12001	BASIN::DAKOTA	11	G	8/13/09	8/3/09	8/3/09
300393064300C02	SAN JUAN 30-5 UT 75N MV	RIO ARRIBA	NM	30	N	5	W 21	N	A650113	12001	BLANCO::MESAVERDE	11	G	8/13/09	8/3/09	8/3/09
300392272700S01	SAN JUAN 30-5 UT 76 DK	RIO ARRIBA	NM	30	N	5	W 15	A	A650402	12001	DAKOTA LP	11	G			
300392272700S01	SAN JUAN 30-5 UT 76 DK	RIO ARRIBA	NM	30	N	5	W 15	A	A650402	12001	DAKOTA LP	11	G			
300392551100C01	SAN JUAN 30-5 UT 76M DK	RIO ARRIBA	NM	30	N	5	W 15	F	A650402	12001	DAKOTA NQ	11	G		10/30/95	10/30/95
300392551100C02	SAN JUAN 30-5 UT 76M MV	RIO ARRIBA	NM	30	N	5	W 15	F	A650113	12001	BLANCO::MESAVERDE	11	G		10/30/95	
300393089900C01	SAN JUAN 30-5 UT 76N DK	RIO ARRIBA	NM	30	N	5	W 16	A	A650402	12001	BASIN::DAKOTA	11	G	10/25/10	11/9/10	11/9/10
300393089900C02	SAN JUAN 30-5 UT 76N MV	RIO ARRIBA	NM	30	N	5	W 16	A	A650113	12001	BLANCO::MESAVERDE	11	G	10/25/10	11/9/10	11/9/10
300392267900S01	SAN JUAN 30-5 UT 77 DK	RIO ARRIBA	NM	30	N	5	W 36	G	A650402	12001	DAKOTA LP	11	G			
300392267900S01	SAN JUAN 30-5 UT 77 DK	RIO ARRIBA	NM	30	N	5	W 36	G	A650402	12001	DAKOTA LP	11	G			
300393018300S01	SAN JUAN 30-5 UT 77M DK	RIO ARRIBA	NM	30	N	5	W 36	O	A650402	12001	BASIN::DAKOTA	71	G	10/16/07	10/12/07	
300393018300S02	SAN JUAN 30-5 UT 77M MV	RIO ARRIBA	NM	30	N	5	W 36	O	A650113	12001	BLANCO::MESAVERDE	11	G	10/16/07	11/14/07	11/14/07
300392270700C01	SAN JUAN 30-5 UT 78 DK	RIO ARRIBA	NM	30	N	5	W 7	L	A650402	12001	DAKOTA LP	11	G			
300392270700C01	SAN JUAN 30-5 UT 78 DK	RIO ARRIBA	NM	30	N	5	W 7	L	A650402	12001	DAKOTA LP	11	G			
300392270700C02	SAN JUAN 30-5 UT 78 MV	RIO ARRIBA	NM	30	N	5	W 7	L	A650113	12001	BLANCO::MESAVERDE	11	G		12/9/02	12/9/02
300392703300C01	SAN JUAN 30-5 UT 78M DK	RIO ARRIBA	NM	30	N	5	W 7	I	A650402	12001	BASIN::DAKOTA	11	G		7/8/04	7/8/04
300392703300C01	SAN JUAN 30-5 UT 78M DK	RIO ARRIBA	NM	30	N	5	W 7	I	A650402	12001	BASIN::DAKOTA	11	G		7/8/04	7/8/04
300392703300C02	SAN JUAN 30-5 UT 78M MV	RIO ARRIBA	NM	30	N	5	W 7	I	A650113	12001	BLANCO::MESAVERDE	11	G		7/8/04	7/8/04
300393025500C01	SAN JUAN 30-5 UT 78N DK	RIO ARRIBA	NM	30	N	5	W 7	O	A650402	12001	BASIN::DAKOTA	11	G	6/30/08	7/16/08	7/16/08
300393025500C02	SAN JUAN 30-5 UT 78N MV	RIO ARRIBA	NM	30	N	5	W 7	O	A650113	12001	BLANCO::MESAVERDE	11	G	6/30/08	7/16/08	7/16/08
300392270500C01	SAN JUAN 30-5 UT 79 DK	RIO ARRIBA	NM	30	N	5	W 5	B	A650402	12001	DAKOTA LP	11	G			
300392270500C01	SAN JUAN 30-5 UT 79 DK	RIO ARRIBA	NM	30	N	5	W 5	B	A650402	12001	DAKOTA LP	11	G			
300392270500C02	SAN JUAN 30-5 UT 79 MV	RIO ARRIBA	NM	30	N	5	W 5	B	A650113	12001	BLANCO::MESAVERDE	11	G		12/31/02	12/31/02
300393022400C01	SAN JUAN 30-5 UT 79M DK	RIO ARRIBA	NM	30	N	5	W 5	C	A650402	12001	BASIN::DAKOTA	11	G	9/4/07	10/2/07	10/2/07
300393022400C02	SAN JUAN 30-5 UT 79M MV	RIO ARRIBA	NM	30	N	5	W 5	C	A650113	12001	BLANCO::MESAVERDE	11	G	9/4/07	10/2/07	10/2/07
300392270600C01	SAN JUAN 30-5 UT 80 DK	RIO ARRIBA	NM	30	N	5	W 6	A	A650402	12001	DAKOTA LP	11	G			
300392270600C01	SAN JUAN 30-5 UT 80 DK	RIO ARRIBA	NM	30	N	5	W 6	A	A650402	12001	DAKOTA LP	11	G			
300392270600C02	SAN JUAN 30-5 UT 80 MV	RIO ARRIBA	NM	30	N	5	W 6	A	A650113	12001	BLANCO::MESAVERDE	11	G		1/15/03	1/15/03
300393011300C01	SAN JUAN 30-5 UT 80G DK	RIO ARRIBA	NM	30	N	5	W 6	C	A650402	12001	BASIN::DAKOTA	11	G	10/2/07	10/24/07	10/24/07
300393011300C02	SAN JUAN 30-5 UT 80G MV	RIO ARRIBA	NM	30	N	5	W 6	C	A650113	12001	BLANCO::MESAVERDE	11	G	10/2/07	10/24/07	10/24/07
300392656100C01	SAN JUAN 30-5 UT 80M DK	RIO ARRIBA	NM	30	N	5	W 6	F	A650402	12001	BASIN::DAKOTA	11	G		3/19/02	3/19/02
300392656100C02	SAN JUAN 30-5 UT 80M MV	RIO ARRIBA	NM	30	N	5	W 6	F	A650113	12001	BLANCO::MESAVERDE	11	G		12/9/02	12/9/02
300392270900S01	SAN JUAN 30-5 UT 81 DK	RIO ARRIBA	NM	30	N	5	W 27	L	A650276	12001	BASIN::DAKOTA	11	G			
300392270900S01	SAN JUAN 30-5 UT 81 DK	RIO ARRIBA	NM	30	N	5	W 27	L	A650276	12001	BASIN::DAKOTA	11	G			
300392270900S01	SAN JUAN 30-5 UT 81 DK	RIO ARRIBA	NM	30	N	5	W 27	L	A650276	12001	BASIN::DAKOTA	11	G			
300393076500C01	SAN JUAN 30-5 UT 81N DK	RIO ARRIBA	NM	30	N	5	W 27	F	A650276	12001	BASIN::DAKOTA	11	G	12/11/09	12/11/09	1/7/10
300393076500C02	SAN JUAN 30-5 UT 81N MV	RIO ARRIBA	NM	30	N	5	W 27	F	A650113	12001	BLANCO::MESAVERDE	11	G	12/11/09	12/11/09	1/7/10
300393080000C01	SAN JUAN 30-5 UT 81P DK	RIO ARRIBA	NM	30	N	5	W 27	F	A714392	12001	BASIN::DAKOTA	11	G	1/20/10	1/20/10	1/20/10
300393080000C02	SAN JUAN 30-5 UT 81P MV	RIO ARRIBA	NM	30	N	5	W 27	F	A650113	12001	BLANCO::MESAVERDE	11	G	1/20/10	1/20/10	1/20/10
300392275500S01	SAN JUAN 30-5 UT 82 DK TA	RIO ARRIBA	NM	30	N	5	W 25	D	A650275	12001	BASIN::DAKOTA	61	G			
300392275500S01	SAN JUAN 30-5 UT 82 DK TA	RIO ARRIBA	NM	30	N	5	W 25	D	A650275	12001	BASIN::DAKOTA	61	G			
300392275500S01	SAN JUAN 30-5 UT 82 DK TA	RIO ARRIBA	NM	30	N	5	W 25	D	A650275	12001	BASIN::DAKOTA	61	G			
300392275500S02	SAN JUAN 30-5 UT 82 MV	RIO ARRIBA	NM	30	N	5	W 25	D	A650113	12001	BLANCO::MESAVERDE	11	G		6/16/04	6/16/04
300392272800S01	SAN JUAN 30-5 UT 83 DK	RIO ARRIBA	NM	30	N	5	W 23	L	A650402	12001	DAKOTA LP	11	G			

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300392272800S01	SAN JUAN 30-5 UT 83 DK	RIO ARRIBA	NM	30	N	5	W 23	L	A650402	12001	DAKOTA LP	11	G			
300392616200C01	SAN JUAN 30-5 UT 83M DK	RIO ARRIBA	NM	30	N	5	W 23	C	A650402	12001	BASIN::DAKOTA	11	G		11/9/99	11/9/99
300392616200C02	SAN JUAN 30-5 UT 83M MV	RIO ARRIBA	NM	30	N	5	W 23	C	A650113	12001	BLANCO::MESAVERDE	11	G		6/6/00	6/6/00
300392301900C01	SAN JUAN 30-5 UT 84 MV	RIO ARRIBA	NM	30	N	5	W 33	J	A650113	12001	BLANCO::MESAVERDE	11	G	10/8/82	10/8/82	10/8/82
300392301900C02	SAN JUAN 30-5 UT 84 PC	RIO ARRIBA	NM	30	N	5	W 33	J	A650110	12001	GOBERNADOR:PICTURED CLIFF	11	G	10/9/82	10/9/82	10/9/82
300392312900S01	SAN JUAN 30-5 UT 85 DK	RIO ARRIBA	NM	30	N	5	W 36	M	A650278	12001	BASIN::DAKOTA	72	G	9/20/83	7/22/11	
300393072000C01	SAN JUAN 30-5 UT 85M DK	RIO ARRIBA	NM	30	N	5	W 36	F	A713912	12001	BASIN::DAKOTA	11	G	7/24/09	6/1/10	6/1/10
300393072000C02	SAN JUAN 30-5 UT 85M MV	RIO ARRIBA	NM	30	N	5	W 36	F	A650113	12001	BLANCO::MESAVERDE	11	G	7/24/09	6/1/10	6/1/10
300393076000C01	SAN JUAN 30-5 UT 85N DK	RIO ARRIBA	NM	30	N	5	W 36	F	A714194	12001	BASIN::DAKOTA	11	G	10/15/09	5/17/10	5/17/10
300393076000C02	SAN JUAN 30-5 UT 85N MV	RIO ARRIBA	NM	30	N	5	W 36	F	A650113	12001	BLANCO::MESAVERDE	11	G	10/15/09	5/17/10	5/17/10
300392314800S01	SAN JUAN 30-5 UT 86 DK	RIO ARRIBA	NM	30	N	5	W 35	M	A650402	12001	DAKOTA LP	11	G			
300392314800S01	SAN JUAN 30-5 UT 86 DK	RIO ARRIBA	NM	30	N	5	W 35	M	A650402	12001	DAKOTA LP	11	G			
300392315700S01	SAN JUAN 30-5 UT 87 DK	RIO ARRIBA	NM	30	N	5	W 5	M	A650402	12001	DAKOTA LP	11	G			
300392315700S01	SAN JUAN 30-5 UT 87 DK	RIO ARRIBA	NM	30	N	5	W 5	M	A650402	12001	DAKOTA LP	11	G			
300392680400C01	SAN JUAN 30-5 UT 87M DK	RIO ARRIBA	NM	30	N	5	W 5	I	A650402	12001	BASIN::DAKOTA	11	G		5/17/02	5/17/02
300392680400C02	SAN JUAN 30-5 UT 87M MV	RIO ARRIBA	NM	30	N	5	W 5	I	A650113	12001	BLANCO::MESAVERDE	11	G		1/6/03	1/6/03
300392317700C01	SAN JUAN 30-5 UT 88 DK	RIO ARRIBA	NM	30	N	5	W 18	L	A650402	12001	DAKOTA LP	11	G			
300392317700C01	SAN JUAN 30-5 UT 88 DK	RIO ARRIBA	NM	30	N	5	W 18	L	A650402	12001	DAKOTA LP	11	G			
300392317700C02	SAN JUAN 30-5 UT 88 MV	RIO ARRIBA	NM	30	N	5	W 18	L	A650113	12001	BLANCO::MESAVERDE	11	G		12/11/02	12/11/02
300392708700C01	SAN JUAN 30-5 UT 88M DK	RIO ARRIBA	NM	30	N	5	W 18	E	A650402	12001	BASIN::DAKOTA	11	G		7/28/04	7/28/04
300392708700C01	SAN JUAN 30-5 UT 88M DK	RIO ARRIBA	NM	30	N	5	W 18	E	A650402	12001	BASIN::DAKOTA	11	G		7/28/04	7/28/04
300392708700C02	SAN JUAN 30-5 UT 88M MV	RIO ARRIBA	NM	30	N	5	W 18	E	A650113	12001	BLANCO::MESAVERDE	11	G		7/28/04	7/28/04
300393025200C01	SAN JUAN 30-5 UT 88N DK	RIO ARRIBA	NM	30	N	5	W 18	C	A650402	12001	BASIN::DAKOTA	11	G	10/30/07	10/30/07	11/20/07
300393025200C02	SAN JUAN 30-5 UT 88N MV	RIO ARRIBA	NM	30	N	5	W 18	C	A650113	12001	BLANCO::MESAVERDE	11	G	10/30/07	10/30/07	11/20/07
300392317800S01	SAN JUAN 30-5 UT 89 DK	RIO ARRIBA	NM	30	N	5	W 19	H	A650402	12001	DAKOTA LP	11	G			
300392317800S01	SAN JUAN 30-5 UT 89 DK	RIO ARRIBA	NM	30	N	5	W 19	H	A650402	12001	DAKOTA LP	11	G			
300393054100C01	SAN JUAN 30-5 UT 89M DK	RIO ARRIBA	NM	30	N	5	W 19	J	A650402	12001	BASIN::DAKOTA	11	G	9/9/09	9/1/09	9/1/09
300393054100C02	SAN JUAN 30-5 UT 89M MV	RIO ARRIBA	NM	30	N	5	W 19	J	A650113	12001	BLANCO::MESAVERDE	11	G	9/9/09	9/1/09	9/1/09
300393069700C01	SAN JUAN 30-5 UT 89N DK	RIO ARRIBA	NM	30	N	5	W 18	O	A650402	12001	BASIN::DAKOTA	11	G	8/28/09	8/18/09	8/18/09
300393069700C01	SAN JUAN 30-5 UT 89N DK	RIO ARRIBA	NM	30	N	5	W 18	O	A650402	12001	BASIN::DAKOTA	11	G	8/28/09	8/18/09	8/18/09
300393069700C02	SAN JUAN 30-5 UT 89N MV	RIO ARRIBA	NM	30	N	5	W 18	O	A650113	12001	BLANCO::MESAVERDE	11	G	8/28/09	8/18/09	8/18/09
300390771700S01	SAN JUAN 30-5 UT 9 MV	RIO ARRIBA	NM	30	N	5	W 32	M	A650113	12001	BLANCO::MESAVERDE	11	G			
300392317300C01	SAN JUAN 30-5 UT 90 DK	RIO ARRIBA	NM	30	N	5	W 22	H	A650402	12001	DAKOTA LP	11	G			
300392317300C01	SAN JUAN 30-5 UT 90 DK	RIO ARRIBA	NM	30	N	5	W 22	H	A650402	12001	DAKOTA LP	11	G			
300392317300C02	SAN JUAN 30-5 UT 90 MV	RIO ARRIBA	NM	30	N	5	W 22	H	A650113	12001	BLANCO::MESAVERDE	11	G		7/18/97	7/18/97
300392708600C01	SAN JUAN 30-5 UT 90M DK	RIO ARRIBA	NM	30	N	5	W 22	I	A650402	12001	BASIN::DAKOTA	11	G		7/19/04	7/19/04
300392708600C01	SAN JUAN 30-5 UT 90M DK	RIO ARRIBA	NM	30	N	5	W 22	I	A650402	12001	BASIN::DAKOTA	11	G		7/19/04	7/19/04
300392708600C02	SAN JUAN 30-5 UT 90M MV	RIO ARRIBA	NM	30	N	5	W 22	I	A650113	12001	BLANCO::MESAVERDE	11	G		7/19/04	7/19/04
300393086900C01	SAN JUAN 30-5 UT 90N DK	RIO ARRIBA	NM	30	N	5	W 22	C	A650402	12001	BASIN::DAKOTA	11	G	9/24/10	10/15/10	10/15/10
300393086900C02	SAN JUAN 30-5 UT 90N MV	RIO ARRIBA	NM	30	N	5	W 22	C	A650113	12001	BLANCO::MESAVERDE	11	G	9/24/10	10/15/10	10/15/10
300393092100C01	SAN JUAN 30-5 UT 90P DK	RIO ARRIBA	NM	30	N	5	W 22	P	A650402	12001	BASIN::DAKOTA	11	G	11/12/10	11/12/10	
300393092100C02	SAN JUAN 30-5 UT 90P MV	RIO ARRIBA	NM	30	N	5	W 22	P	A650113	12001	BLANCO::MESAVERDE	11	G	11/12/10	11/12/10	
300392316800C02	SAN JUAN 30-5 UT 91 DK	RIO ARRIBA	NM	30	N	5	W 25	L	A650279	12001	BASIN::DAKOTA	11	G		10/17/83	10/17/83
300392316800C02	SAN JUAN 30-5 UT 91 DK	RIO ARRIBA	NM	30	N	5	W 25	L	A650279	12001	BASIN::DAKOTA	11	G		10/17/83	10/17/83
300392316800C02	SAN JUAN 30-5 UT 91 DK	RIO ARRIBA	NM	30	N	5	W 25	L	A650279	12001	BASIN::DAKOTA	11	G		10/17/83	10/17/83
300392316800C01	SAN JUAN 30-5 UT 91 GA	RIO ARRIBA	NM	30	N	5	W 25	L	A650279	12001	BASIN::GALLUP	11	G		10/17/83	10/17/83
300392316800C01	SAN JUAN 30-5 UT 91 GA	RIO ARRIBA	NM	30	N	5	W 25	L	A650279	12001	BASIN::GALLUP	11	G		10/17/83	10/17/83
300392316800C01	SAN JUAN 30-5 UT 91 GA	RIO ARRIBA	NM	30	N	5	W 25	L	A650279	12001	BASIN::GALLUP	11	G		10/17/83	10/17/83
300392316800C01	SAN JUAN 30-5 UT 91 GA	RIO ARRIBA	NM	30	N	5	W 25	L	A650279	12001	BASIN::GALLUP	11	G		10/17/83	10/17/83

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-5 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
3003923168	SAN JUAN 30-5 UT 91 GA DK	RIO ARRIBA	NM	30	N	5	W 25	L	A650279	12001	BASIN::GALLUP-DAKOTA	99	G	10/17/83	10/17/83	10/17/83
300392314500S01	SAN JUAN 30-5 UT 92 DK	RIO ARRIBA	NM	30	N	5	W 26	K	A650402	12001	DAKOTA LP	11	G			
300392314500S01	SAN JUAN 30-5 UT 92 DK	RIO ARRIBA	NM	30	N	5	W 26	K	A650402	12001	DAKOTA LP	11	G			
300393110200C01	SAN JUAN 30-5 UT 92M DK	RIO ARRIBA	NM	30	N	5	W 26	G	A650402	12001	BASIN::DAKOTA	11	G	8/9/12	8/10/12	8/10/12
300393110200C02	SAN JUAN 30-5 UT 92M MC	RIO ARRIBA	NM	30	N	5	W 26	G	A718889	12001	BASIN::MANCOS	11	G	8/9/12	8/10/12	8/10/12
300393110200C03	SAN JUAN 30-5 UT 92M MV	RIO ARRIBA	NM	30	N	5	W 26	G	A650113	12001	BLANCO::MESAVERDE	11	G	8/9/12	8/10/12	8/10/12
300393060400C01	SAN JUAN 30-5 UT 92P DK	RIO ARRIBA	NM	30	N	5	W 26	M	A650402	12001	BASIN::DAKOTA	11	G	3/16/09	6/23/09	6/23/09
300393060400C01	SAN JUAN 30-5 UT 92P DK	RIO ARRIBA	NM	30	N	5	W 26	M	A650402	12001	BASIN::DAKOTA	11	G	3/16/09	6/23/09	6/23/09
300393060400C02	SAN JUAN 30-5 UT 92P MV	RIO ARRIBA	NM	30	N	5	W 26	M	A650113	12001	BLANCO::MESAVERDE	11	G	3/16/09	6/23/09	6/23/09
300392314400S01	SAN JUAN 30-5 UT 93 DK TA	RIO ARRIBA	NM	30	N	5	W 26	A	A650402	12001	DAKOTA LP	61	G			
300392314400S01	SAN JUAN 30-5 UT 93 DK TA	RIO ARRIBA	NM	30	N	5	W 26	A	A650402	12001	DAKOTA LP	61	G			
300392314400S02	SAN JUAN 30-5 UT 93 MV	RIO ARRIBA	NM	30	N	5	W 26	A	A650113	12001	BLANCO::MESAVERDE	11	G		11/9/04	
300392314600S01	SAN JUAN 30-5 UT 94 DK	RIO ARRIBA	NM	30	N	5	W 27	B	A650402	12001	DAKOTA LP	11	G	12/14/83		
300392314600S01	SAN JUAN 30-5 UT 94 DK	RIO ARRIBA	NM	30	N	5	W 27	B	A650402	12001	DAKOTA LP	11	G	12/14/83		
300393075100C01	SAN JUAN 30-5 UT 94M DK	RIO ARRIBA	NM	30	N	5	W 27	B	A650402	12001	BASIN::DAKOTA	11	G	10/27/09	10/15/09	10/15/09
300393075100C02	SAN JUAN 30-5 UT 94M MV	RIO ARRIBA	NM	30	N	5	W 27	B	A650113	12001	BLANCO::MESAVERDE	11	G	10/27/09	10/15/09	10/15/09
300393101700C01	SAN JUAN 30-5 UT 94N DK	RIO ARRIBA	NM	30	N	5	W 34	B	A650402	12001	BASIN::DAKOTA	11	G	8/31/11	10/12/11	10/12/11
300393101700C02	SAN JUAN 30-5 UT 94N MV	RIO ARRIBA	NM	30	N	5	W 34	B	A650113	12001	BLANCO::MESAVERDE	11	G	8/31/11	10/12/11	10/12/11
300393079600C01	SAN JUAN 30-5 UT 94P DK	RIO ARRIBA	NM	30	N	5	W 27	I	A650402	12001	BASIN::DAKOTA	11	G	11/20/09	11/20/09	2/25/10
300393079600C02	SAN JUAN 30-5 UT 94P MV	RIO ARRIBA	NM	30	N	5	W 27	I	A650113	12001	BLANCO::MESAVERDE	11	G	11/20/09	11/20/09	2/25/10
300392312800S01	SAN JUAN 30-5 UT 95 DK	RIO ARRIBA	NM	30	N	5	W 28	H	A650402	12001	DAKOTA LP	11	G			
300392312800S01	SAN JUAN 30-5 UT 95 DK	RIO ARRIBA	NM	30	N	5	W 28	H	A650402	12001	DAKOTA LP	11	G			
300393021700C01	SAN JUAN 30-5 UT 95F DK	RIO ARRIBA	NM	30	N	5	W 28	B	A650402	12001	BASIN::DAKOTA	11	G	8/9/07	9/5/07	9/5/07
300393021700C02	SAN JUAN 30-5 UT 95F MV	RIO ARRIBA	NM	30	N	5	W 28	B	A650113	12001	BLANCO::MESAVERDE	11	G	8/9/07	9/5/07	9/5/07
300392317900S01	SAN JUAN 30-5 UT 96 DK	RIO ARRIBA	NM	30	N	5	W 28	L	A650283	12001	BASIN::DAKOTA	11	G			
300392317900S01	SAN JUAN 30-5 UT 96 DK	RIO ARRIBA	NM	30	N	5	W 28	L	A650283	12001	BASIN::DAKOTA	11	G			
300392317900S01	SAN JUAN 30-5 UT 96 DK	RIO ARRIBA	NM	30	N	5	W 28	L	A650283	12001	BASIN::DAKOTA	11	G			
300393063000C01	SAN JUAN 30-5 UT 96N DK	RIO ARRIBA	NM	30	N	5	W 28	E	A650283	12001	BASIN::DAKOTA	11	G	10/12/09	9/30/09	9/30/09
300393063000C02	SAN JUAN 30-5 UT 96N MV	RIO ARRIBA	NM	30	N	5	W 28	E	A650113	12001	BLANCO::MESAVERDE	11	G	10/12/09	9/30/09	9/30/09
300392318000S01	SAN JUAN 30-5 UT 97 DK	RIO ARRIBA	NM	30	N	5	W 29	H	A650402	12001	DAKOTA NQ	11	G			
300392318000S01	SAN JUAN 30-5 UT 97 DK	RIO ARRIBA	NM	30	N	5	W 29	H	A650402	12001	DAKOTA NQ	11	G			
300392271000S01	SAN JUAN 30-5 UT 9A MV	RIO ARRIBA	NM	30	N	5	W 32	E	A650113	12001	BLANCO::MESAVERDE	11	G			
300393089500C01	SAN JUAN 30-5 UT 9B DK	RIO ARRIBA	NM	30	N	5	W 32	E	A714455	12001	BASIN::DAKOTA	11	G	8/25/11	9/16/11	9/16/11
300393089500C02	SAN JUAN 30-5 UT 9B MV	RIO ARRIBA	NM	30	N	5	W 32	E	A650113	12001	BLANCO::MESAVERDE	11	G	8/24/11	9/16/11	9/16/11
300393066200C01	SAN JUAN 30-5 UT CM 1N DK	RIO ARRIBA	NM	30	N	5	W 4	O	A719864	12001	BASIN::DAKOTA	11	G	10/8/12	10/9/12	10/9/12
300393066200C02	SAN JUAN 30-5 UT CM 1N MC	RIO ARRIBA	NM	30	N	5	W 4	O	A718572	12001	BASIN::MANCOS	11	G	10/8/12	10/9/12	10/9/12
300393066200C03	SAN JUAN 30-5 UT CM 1N MV	RIO ARRIBA	NM	30	N	5	W 4	O	A719871	12001	BLANCO::MESAVERDE	11	G	10/8/12	10/9/12	10/9/12

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN