


OXY - Diamond 34 State #1 SWD

Temperature Gradient Comparison



OXY - SWD Log vs. Devon offset baseline Log




Oil Conservation Division
Case No. 12
Exhibit No. 1

OXY - Diamond 34 State #1 SWD

Temperature Gradient Comparison (zoom)



OXY - SWD Log vs. Devon offset baseline Log




OXY - Diamond 34 State #1 SWD

Multiple Passes



OXY - Diamond 34 State 1 SWD Temperature Logs




OXY - Diamond 34 State #1 SWD

Multiple Passes with Normal Gradient




OXY - Diamond 34 State 1 SWD Temperature Logs



North Thistle 34 State Com 1H

Potential Fluid Migration Paths






Option 1

- Low cement top
- Intermediate casing leak
- Uncontained hydraulic frac treatment(s)
- Higher than permitted injection pressures

Option 2

- Poorly plugged well
- Failed cement plugs with time

NYSE: DVN



OXY Slide 14 Comparison to Thistle Unit 6 Fiber Optic Temp Gradient

DEVON
THISTLE UNIT
6
30025347670000

