

Wednesday, February 13, 2008

**Monument #2:**

Know new information concerning the actual setting depth of the stage collar. I have checked with all the service companies and BP Amoco Farmington office with no success.

Several different scenarios have been run using different slurry volumes as well as different percentages for open-hole excess.

With the wells Coleman has drilled and completed in the area and the stage collar set into the Mancos fifty to one hundred feet and using the stage volumes that were reported, we feel comfortable that the cement volumes were more than adequate to get cement well above the top of the Mesa Verde formation and should have been enough to get cement to surface.