28-Aug-08

Well Inspection History

API Number: 30-015-20088-00-00

Well Name & No.: RESLER YATES STATE

Operator: SANDLOTT ENERGY (JACKIE BREWER DB District: ARTESIA

County Name: EDDY

Field: RESLER YATES STATE

Legal: S: 32 T: 18S R: 28E

Well Type: OIL (PRODUCING)

Insp. Dt. Insp. Type

Insp. Purpose

Insp. No.

RmdyRqDt

Insp. By

Viol. SNC Failed Codes

7/16/2007 Routine/Periodic

Normal Routine Activity

iMLB07197424

Partial well sign laying on ground. Power switch is off. Contamination at well head area and West of pumping unit, as noted in 2006

inspection, has had no change. Several patches on metal flowline.

7/5/2006 File and Compliance Review Normal Routine Activity

iPCH0618638

No electrical power hooked to motor on pumping unit. Broken well sign on ground, contamination around wellhead and csg. Contamination at

flow line West side of location

8/30/2005 Routine/Periodic

Normal Routine Activity

iMLB05242509

211

No Pumping Unit or production equipment. No compliant well sign. Contaminated area along flowline on West side of location.

8/20/2004 Routine/Periodic

Normal Routine Activity

iGEG0423339

209

No Pumping Unit. Last reported production April 2003. Area contaminated. No well sign.

10/19/1999 Routine/Periodic

Status Check

iELG0003120

207

A-OK. All Equipment and Location in Good Shape.

Total Inspections Performed: 5

Jackie Brewer D/B/A Sandlott Energy De Novo Case 14074 OCD Exhibit No. 10