

2 1 0 1

14. Blair & Price's C.F.E. Fed. No. 1, Unit N, Section 1, T23S, R37E.
Plugged and abandoned well. Considered a potential problem well for the future, if waterflood is extended into north half of Section 2. P&A procedure considered adequate for present, since waterflow is not indicated to extend this far east. Recommend action be deferred until waterflood is extended into adjacent area, or problem area is extended into vicinity of the wellbore.

15. Gulf's Fred C. King No. 1, Unit E, Section 5, T23S, R37E.
Plugged and abandoned well. Well considered adequately plugged in lower intervals; but possibly inadequately plugged in upper 1500' section. Recommend monitoring of bradenhead pressures on surrounding wells; and re-plugging if problems develop. No pressure or waterflows indicated on surrounding wells on bradenhead pressure check.

02/28/60