

**Brooks, David K., EMNRD**

---

**From:** Brooks, David K., EMNRD  
**Sent:** Tuesday, January 11, 2011 11:43 AM  
**To:** 'jamesbruc@aol.com'  
**Cc:** Jones, William V., EMNRD  
**Subject:** Case No. 14552; Application of BOPCO for Approval of a Pilot Waterflood, etc

Dear Jim

There is a concern in this case about the PLU #153, one of the wells in the area of review. The well data concerning this well indicates that the 10 ¾ casing is cemented at 3578 feet, and the 7 5/8 casing is cemented at 11,450, w/ TOC at 8193, indicating that the annulus behind the 7 5/8 casing is open across the proposed injection interval and clear up to the surface. In the absence of additional data, we would be disposed to require remedial work to seal off the injection zone in this well.

Please advise if there is additional information indicating that this well does not present a problem as the information in the C-108s suggests.

Sincerely  
David