

TEXACO EXPLORATION AND PRODUCTION INC.

C. W. ROBERTS NO. 4 660' FSL 660' FWL SEC. 17, T25N, R3W RIO ARRIBA CO., NEW MEXICO



LIST OF EXHIBITS


- A. Land Map Location of Well/Lease
- B. Well Location and Acreage Dedication Plat (Form C-102)
- C. Offset Operator Plat
- D. List of Offset Operators
- E. Return Receipt of Notice to Offset Operators
- F. Waiver Letters From Offset Operators
- G. Gallup Structure Map
- H. Gallup Isopach Map (Upper and Lower Zones)
- I. Gallup Isopach Map (Upper Perforated Zone)
- J. Cross Section (West East)
- K. Well Schematic Current Completion
- L. Well Schematic Proposed Completion
- M. Proposed Drilling Procedure





Ĩ -

P.O. Box 1980, Hobbs, NM 88241-1980 DISTRICT II P.O. Box Drawer DD, Artesia, NM 88211-0719 DISTRICT III 1000 Bia Brazos Bd. Attec. NM 87410	Ite of New MexicoForm C-102Ind Natural Resources DepartmentRevised February 10,199Instructions on backInstructions on backSubmit to Appropriate District Offic
DISTRICT IV Santa Fe,	O. Box 2088 State Lease - 4 Copies lew Mexico 87504-2088 Fee Lease - 3 Copie
API Number 2 Pool Code 3003905965 39189	LINDRITH GALLUP-DAKOTA, WEST
⁴ Property Code 11208	Property Name ⁶ Well No. W ROBERTS 4
OCITID ITUINDEL	Operator Name ⁹ Elevation ACTION & PRODUCTION, INC. 7193' DF
¹⁰ Sur	ce Location
Ul or lot no. Section Township Range Lot.ldn Feet Fill M 17 25N 3W 6	
	n If Different From Surface
UI or lot no. Section Township Range Lot.Idn Feet F	n The North/South Line Feet From The East/West Line County
¹² Dedicated Acre ¹³ Joint or Infill ¹⁴ Consolidation Code	¹⁵ Order No.
SEC. 16 SEC. 17 SEC. 17 PROPOSED BUTTOM HOLD LOCATION 66000	17 OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief Dawwa Himati Signature Signature Printed Name Rachen Himati Rachen Himati Position Senton Englater Date 6/2/95 18 18 SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief. Date Surveyed Signature & Seal of Professional Surveyor
0 330 660 990 1320 1650 1980 2310 2640 2000	Certificate No.



AHachment II

OFFSET OPERATORS C.W. ROBERTS #4 WEST LINDRITH GALLUP/DAKOTA

- -- =-

Elliott Oil Co. P.O. Box 1355 Roswell, NM 88202

Little, Curtis J., Oil & Gas Box 1258 2346 E. 20th St. Farmington, NM 87499 2

Attachment III side? SENDER: I also wish to receive the · Complete items 1 and/or 2 for additional services. · Complete items 3, and 4e & b. following services (for an extra いるのにないななななない。日本の **FBVBISB** Service · Print your name and address on the reverse of this form so that we can fee): return this card to you. 1. Addressee's Address · Attach this form to the front of the mailpiece, or on the back if space does not permit. Receipt ţ . Write "Return Receipt Requested" on the mailpiece below the article number. 2. C Restricted Delivery The Return Receipt will show to whom the article was delivered and the date ADDRESS completed on Consult postmaster for fee. delivered. 3. Article Addressed to: 4a. Article Number Return Z. 175 050 4b. Service Type LITTLE, CURTIS J., OIL & GAS Registered Insured using P.O.BOX 1258 Certified 2346 E. 20TH ST. Return Receipt for Express Mail Merchandise FARMINGTON, NM 87499 E 7. Date of Delivery 2 5 ίς Γ нş RETURN Addressee's Address (Only if requested 5. Signature (Addressee and fee is paid) ĕ 6. Signature (Agent) 1. S. S. S. S. 1 a. Your PS Form 3811, December 1991 -352-714 +U.S. GPO: 1993 DOMESTIC RETURN RECEIPT Ide? SENDER: I also wish to receive the · Complete items 1 and/or 2 for additional following services (for an extra · Complete items 3, and 4e & b. 244 ø form so that we can · Print your name and address on the rev and the second secon fee): Servi ŝŝ return this card to you. 1. Addressee's Address にない · Attach this form to the front of the mail; or on the back if space é does not permit. ----ţ . Write "Return Receipt Requested" on the mailpiece below the article number 2. C Restricted Delivery . The Return Receipt will show to whom the article was delivered and the date Consult postmaster for fee. 50 delivered. Ĥ 4a. Article Number دور دور مراجع 3. Article Addressed to: completed 4b. Service Type ELLIOTT OIL CO. Registered Insured using ٤., Certified PO BOX 1355 ADDRESS Ķ\$ ROSWELL, NM 88202 Return Receipt for Express Mail 協力が Merchandise 7. Date of Delivery 5-30-ŶĹ ě RETURN Addressee's Address (Only if requested 8. 5. Signature (Addressee) 51 × and fee is paid) r - - 7 المرتبع بالمنا العجاك ا 6. Signature (Agent) ÷. • -U **s** your Л 3810 PS DOMESTIC **RETURN RECEIP** Ŕ Fórm December 1991 #U.S. GPO: 1993--352-714 ź 5


EXHIBIT "E"



"stace Excloration and Production Inc.

Little, Curtis J., Oil & Gas Box 1258 2346 E. 20th St. Farmington, NM 87499

RE: Horizontal Re-Entry C.W. Roberts No. 4 Surf Loc: 660' FSL, 660' FWL, Unit M Sec. 17-T25N-R3W Río Arriba County, New Mexico 3300 N S... 37 Formington 11M \$7401



May 25, 1995

Gentlemen:

~ .

As offset operator to the spacing unit for the referenced well, you are being notified of our application with the New Mexico Oil Conservation Division (NMOCD) to drill a short radius horizontal lateral reentry into the Gallup formation. We plan to mill out a section of casing, sidetrack, drill and complete a single 2500' short radius horizontal section (100' radius, 57 degrees/100' build) into the upper portion of the Gallup formation. The kick off point will be at approximately 6900' and the targeted total vertical depth of the horizontal lateral section is 7160'. Attached are wellbore diagrams for the current and proposed completions. The horizontal leg will be in a eastward direction, as shown on the attached location map. We expect to recover additional Gallup reserves in the adjacent undeveloped W. Lindrith Gallup Dakota 160 acre spacing unit (SE quarter of section 17, T25N-R3W). These reserves would normally be recovered by an additional vertical well. Both spacing units are included in the Texaco Exploration and Producing Inc. operated C.W. Roberts lease.

If you have no objection to the above application please sign the waiver at the bottom of this letter and return it to this address. To expedite this procedure a facsimile signed copy would be greatly appreciated. Please fax to 505-325-5398. If you do have an objection, it must be filed with the NMOCD in writing within twenty (20) days of the date this notice was received. Your attention to this matter is greatly appreciated.

If you have any questions concerning this matter please contact Mr. Mark R. Reinhold at 505-325-4397 ext. 19.

Sincerely.

Riched Hundi GONTAT

Ted A. Tipton Operating Unit Manager MRR/s

Attachments		
cc: file		
WAIVER APPROVAL:		\sim
COMPANY: Contraction of Company:	BY: Julina	+ fore
DATE: 6-5-95		

EVHIRIT "C"



Texaco Exploration and Production Inc.

3300 N Butler Farmington NM 87401 May 25, 1995

Elliott Oll Co. P.O. Box 1355 Roswell, NM \$\$202

.. .

Horizontal Re-Entry RE:

C.W. Roberts No. 4 Surf Loc: 660' FSL, 660' FWL, Unit M Sec. 17-T25N-R3W Rio Arriba County, New Mexico

Gentlemen:

As offset operator to the spacing unit for the referenced well, you are being notified of our application with the New Mexico Oil Conservation Division (NMOCD) to drill a short radius horizontal lateral reentry into the Gallup formation. We plan to mill out a section of casing, sidetrack, drill and complete a single 2500' short radius horizontal section (100' radius, 57 degrees/100' build) into the upper portion of the Gallup formation. The kick off point will be at approximately 6900' and the targeted total vertical depth of the horizontal lateral section is 7160'. Attached are wellbore diagrams for the current and proposed completions. The horizontal leg will be in a eastward direction, as shown on the attached location map. We expect to recover additional Gallup reserves in the adjacent undeveloped W. Lindrith Gallup Dakota 160 acre spacing unit (SE quarter of section 17, T25N-R3W). These reserves would normally be recovered by an additional vertical well. Both spacing units are included in the Texaco Exploration and Producing Inc. operated C.W. Roberts lease.

If you have no objection to the above application please sign the waiver at the bottom of this letter and return it to this address. To expedite this procedure a facsimile signed copy would be greatly appreciated. Please fax to 505-325-5398. If you do have an objection, it must be filed with the NMOCD in writing within twenty (20) days of the date this notice was received. Your attention to this matter is greatly appreciated.

If you have any questions concerning this matter please contact Mr. Mark R. Reinhold at 505-325-4397 ext. 19.


Sincerely. chad Hindi & TAT

Ted A. Tipton Operating Unit Managor MRR/s

Attachments cc: file

WAIVER APPROVAL:		- A King-
COMPANY:_	Ellist Dil Co.	BY: Trall Matter
DATE:	5/31/85	

EXHIBIT "F"



Î

1

Γ

-


-

Π

ſ

EXHIBIT "G"

EXHIBIT "H"








EXHIBIT "I"

ĥ P Î Î P Π



AHachment IV-A

×. •



PBTD - 3879' TD - 8220'

BDP 2700#, MAX TP 3500# SD 2200#, IR 23 3 BPM

_....

Attachment IV-B




A.4

C.W. ROBERTS No. 4

6/26/95

PROPOSED SIDETRACK COMPLETION



Attachment I

C. W. ROBERTS #4 HORIZONTAL SINGLE LATERAL REENTRY

The subject well is a producing well. It is to be reentered and a single horizontal lateral is to be drilled in the Gallup formation. The existing perforations in the Pictured Cliff and Mesa Verde formations will be squeeze cemented and a 40' section is to be milled in the casing. A short radius horizontal lateral will be drilled in the west direction approximately 2500' long. The well will be acidized using coiled tubing, if necessary, and then production tested.

WELL PREPARATION:

· ...

- 1) MIRUSU. Nipple up 3M BOPE.
- 2) Kill well with produced water.
- 3) TOH and lay down production tubing.
- 4) TIH with 4-3/4" bit on 2-7/8" work string and clean out to PBTD. TOH.

SQUEEZE EXISTING PERFORATIONS:

- 5) TIH with cement retainer on tubing and set above Pictured Cliff perfs (3680'-3700') at 3650'.
- 6) Space out tubing in neutral position and test tubing to 3000 psi. Rig up squeeze manifold. Establish rate into perforations (2 BPM), note pump in pressure. Pressure up annulus to 1000 psi, monitor casing during job.
- 7) Cement squeeze with 150 sx Class "G" with 0.2% D156 and 0.2% D65 to obtain a fluid loss of 200-300 cc/30 min. (determine by lab testing) followed by 100 sx Class "G" neat, mixed at 15.8 ppg. Minimum pump time 150 minutes at 175°F.
 - a) Spot cement to end of tubing.
 - b) Sting into retainer.
 - c) When cement reaches perforations, slow rate to 1/2 BPM
 - d) Maximum squeeze pressure 3000 psi.
 - e) Displace cement to retainer.
- 8) Pull out of retainer, reverse out cement and check for flow. Pull tubing to 2000' and shutin for 24 hours. TOH with tubing.

EXHIBIT "M"

C. W. Roberts No. 4 Horizontal Reentry Rio Arriba County, New Mexico Drilling & Completion Procedure

÷.,•

- 9) Trip in hole with 4-3/4" bit, drill collars and tubing and drill out retainer and cement to 3700'. Circulate hole clean. Shut in backside and test casing to 500 psi.
- 10) Drill out cement retainers (3879' & 4480') and cement plugs (4000' & 4580') and test to 500 psi. Drill out CIBP at 5325'. Repeat steps 5 9 for squeezing Mesa Verde perfs at 5352'-73 and 5555'-65'. Drill out cement retainer at 6875' and cement to 6940'

MILL 5 1/2" CASING:

11) Circulate hole with mud for milling. TOH with tubing and bit.

MUD: Starch Volume: (6800' * .0238 bbl/ft = 162 bbls + 200 bbls for pit = 362 bbls) Weight: 8.5 - 8.7 Funnel Visc.: 75-80

- 12) If casing collar log is not available in Area, Run GR-CCL to determine position of collars. (Window may be moved +/- 10 to avoid milling a casing collar).
- 13) TIH with mill for 5 1/2" casing on 2 7/8" workstring. Mill 40' section of casing from +/-6890' 6930'. While milling, run paper sweeps in the mud to ensure the hole is clean. Place ditch magnets in return lines to catch metal cuttings. Any time a trip is made, make sure the hole is clean and the blades are retracted.
- 14) TOH with mill.

SPOT KICK OFF PLUG:

- 15) TIH with diverter tool and +/- 400' 2 3/8" (2 1/16" if available) on 2 7/8" work string to PBTD 6940' Circulate Starch mud out of hole. Pull up hole so diverter tool is across milled section and wash section. TIH to PBTD.
- Spot 50 sx Class "G" mixed at 17.5 PPG from 6700' to +/- 6940' (200' above window).
 Batch mix cement. Pull out of cement plug slow to approximately 4000'. Do not reverse circulate. Shut in for 24 hours minimum. TOH with tubing.

C. W. Roberts No. 4 Horizontal Reentry Rio Arriba County, New Mexico Drilling & Completion Procedure

- 17) TIH with 4 3/4" bit and dress off cement to the KOP at 6900'. TOH with 4 3/4" bit. Cement must drill 1.5-2 min/ft with 10 pts and 50 RPM to insure the plug is hard enough for kickoff.
- 18) Circulate hole clean.

DRILL CURVE SECTION (WEST DIRECTION):

19) Displace hole with starch mud. TOH with bit.

MUD:	Starch
Volume:	(6800' * .0238 bbl/ft + 200 bbls for pit + 2500' * .0219 bbl/ft) (162 bbls + 200 bbls + 55 bbls = 417 bbls)
Weight:	8.7
Funel Visc.:	35-40

20) Pick up kick-off motor and test on surface. TIH with kick-off BHA s follows:

4 3/4" bit.
Kick-off motor (with 2.5-3.0° bent sub)
Float/ orientation sub.
1 jt 2 7/8" flexible monel collars.
Enough P-110 tubing to reach from KOP to end of planned horizontal wellbore.
Drill collars
2 7/8", Grade G, AOH DP. to surface.

- 21) TIH to KOP (6900'). Run GYRO and Orient motor to west direction. Break circulation and establish off bottom pressure at operating flow rates. Planned build rate is 57°/100' with a radius of 100'.
- 22) Slowly lower motor to bottom, adjusting toolface as necessary to compensate for reactive torque. Drill approximately 20' of build section with kick-off motor. TOH with kick-off motor and lay down. Pick up build motor (3 restricted articulations to maintain build rates below 70°/100') and TIH. Continue drilling curve while maintaining proper toolface orientation. Drill curve section to target depth of 7000 TVD for start of horizontal.

C. W. Roberts No. 4 Horizontal Reentry Rio Arriba County, New Mexico Drilling & Completion Procedure

23) Circulate hole clean. TOH with curve motor.

DRILL HORIZONTAL LATERAL (WEST DIRECTION):

- 24) TIH with lateral motor BHA. (Same as step 22 but motor has lower build rate.)
- 25) Drill the horizontal lateral (2500') adjusting tool face as needed to the target. The end of the horizontal target depth is 7030' TVD. There is a window around the target line which the well path is to stay within. (see attached well plan for well path and hardlines). While drilling the lateral section, run sweeps of 5 bbls. water, 3 bbls prehydrated gel (90+ viscosity), and 1 gallon polymer.
- 26) At TD circulate hole clean with mud. TOH. Release directional equipment.

COMPLETION:

- 27) TIH with muleshoe, 6 jts P-110 tbg and 5-1/2" casing on 2 7/8" tubing. Space out so P-110 tubing is across curve section and packer is in the casing. Set the packer.
- 28) Rig up coiled tubing unit. TIH with "PERFCLEAN" jetting sub on 1 1/2" coiled tubing to TD. Circulate mud out of hole
- 29) Wash 1st lateral open hole with 25,000 gallons 15% NEFE. Rate 2 BPM. POH with coiled tubing while acidizing so entire open hole is stimulated.
- 30) Displace acid to the end of the tubing. SI for 15 min.
- 31) Flow well until dead. TOH with coiled tubing.
- 32) TOH with workstring. TIH with production equipment and test well as needed.

EXHIBIT "M"