


POGO PRODUCING COMPANY
RED TANK PILOT PRESSURE MAINTENANCE PROJECT



Cross-flow will not occur in the offset wells with the flowing
bottom-hole pressure less than reservoir pressure.

NEW MEXICO
OIL CONSERVATION DIVISION

EXHIBIT

14

CASE NO. _____