

Vintage Drilling L.L.C.  
P.O. Box 158  
Loco Hills, N.M. 88255  
505 746-1669

✓

February 1, 2001

Mr. Tim Gum  
Oil Conservation Division  
811 South First Street  
Artesia, N.M. 88210



RE: Inactive Non-Compliance Wells

Mr. Gum,

On the attached inactive wells list:

Harbold Federal #1 Is not our well

N 26-17-27

Carper-Levers #2 Is back on production

Davis Federal #3 & #12 Both have been pulled and ready to be put back on production.  
Should have a unit set on both the week of Feb. 5<sup>th</sup>. 2001.

E Hi Lonesome Federal #006 & 029 Will be back in production by the end of February 2001.

High Lonesome Penrose Unit #001, 003, 004, 005, & 006,

#003 Is back in production

#004,001,006,005 will be put back on in that order.

We will put the #004 on by the end of March 2001.

We will evaluate it for 30 days. If it is worth producing we will go on to the next well, if it is not we will move all the equipment to the next well and plug it. We will then evaluate that well for 30 days, until all four wells have either been put back into production or plugged.

We trust this will answer your inquiry sufficiently, however, if you have any further questions, please contact me again.

Sincerely,

Sonny Hope

RECEIVED	
OCD	
201	
12811	

VINTAGEINACT111600.XIS

API #	Type	Last Production/ Injection	Well Name and Number	ULSTR	FNS	FEW
30-015-00591	0	09-1986	HARBOLD FEDERAL #001	N-26-17S-27E	330S	2310W
30-015-01705	0	08-1994	CARPER LEVERS #002	M-34-17S-28E	330S	330W
30-015-02692	0	03-1998	E HI LONESOME FEDERAL #006	D-13-16S-29E	660N	660W
30-015-02718	0	06-1993	HIGH LONESOME PENROSE UNIT #001	I-15-16S-29E	1980S	860E
30-015-02720	0	12-1992	HIGH LONESOME PENROSE UNIT #006	B-15-16S-29E	990N	2310E
30-015-02721	1	11-1998	HIGH LONESOME PENROSE UNIT #005	J-15-16S-29E	2310S	2310E
30-015-02727	0	06-1991	DAVIS FEDERAL #003	D-15-16S-29E	660N	660W
30-015-02729	0	03-1996	HIGH LONESOME PENROSE UNIT #003	A-15-16S-29E	990N	660E
30-015-02731	0	12-1992	HIGH LONESOME PENROSE UNIT #004	P-15-16S-29E	990S	660E
30-015-05906	0	10-1991	DAVIS FEDERAL #012	D-15-16S-29E	1310N	1310W
30-015-21502	0	11-1998	E HI LONESOME FEDERAL #029	D-13-16S-29E	825N	1295W

111-21194

RECEIVED  
OCD - ARTESIA

1/11/01  
SONNY —  
THE LETTER OF 12/26/00,  
REQUESTED A WORK PLAN  
FOR ALL WELLS ON LIST.

THANKS  
THU



nt

RE: Inactive Non-compliance Wells

Mr. Gum:

On the attached list of inactive wells, the Harbold Federal is not our well.

The Carper-Levers #2 we are in the process of trying to get a pulling unit to put this well back on and this should happen in the next week or two.

The remainder of the wells on this list are Federal Wells covered by a Federal Plugging bond and we are working with the BLM at this time with a plan to get all of them back on in the near future.

We trust this will answer this inquiry sufficiently, however, if you have any further questions, please contact me again.

Sincerely,

A handwritten signature in cursive script that reads 'Sonny Hope'.

Sonny Hope