

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-03734
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E9335-5
7. Lease Name or Unit Agreement Name: STATE "T"
8. Well No. 1
9. Pool name or Wildcat Townsend Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other	
2. Name of Operator Pronghorn Management Corporation	
3. Address of Operator P. O. Box 1772 Hobbs, NM 88241	
4. Well Location Unit Letter: M 2970 feet from the South line and 330 feet from the West line Section 6 Township 16S Range 36E NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3965' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐


COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set CIBP @ 10,100'. Cap w/ 35' cement.
2. Circulate hole with mud laden fluid.
3. Nipple up to 5 1/2" casing. Stretch, cut and pull 5459' casing.
4. Spot cement plug 50' in and out of stub. WOC and tag 5407'.
5. Spot 100 cement plug @ Int. csg. shoe. WOC and tag @ 4675'.
6. Spot 100' cement plug @ Top of Salt. WOC & tag @ 1925'.
7. Spot 100' cement plug @ 13 3/8" shoe. WOC & tag @ 245'.
8. Spot 10 sx. surface plug.
9. Erect dry hole marker. Clean location.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G. A. Baber TITLE Partner DATE 12/11/02

Type or print name G. A. Baber Telephone No. 505-393-9176

(This space for State use) ☐ ORIGINAL SIGNED BY GARY W. WINK
APPROVED BY GARY W. WINK OC FIELD REPRESENTATIVE II/STAFF MANAGER
Conditions of approval, if any: JAN 03 2003

Pronghorn Exhibit 2
Case No. 12905

Submit 3 Copies
Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

TRISTRICT I
O. Box 1980, Hobbs, NM 88240

TRISTRICT II
O. Drawer DD, Artesia, NM 88210

TRISTRICT III
300 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-03736
1. Indicate Type of Lease STATE ☒ FEB ☐
6. State Oil & Gas Lease No. E 9335-S
7. Lease Name or Unit Agreement Name STATE " T "
8. Well No. 3
9. Pool name or Wildcat TOWNSEND PERMO UPPER PENN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER TA
Name of Operator BABER WELL SERVICING CO.
Address of Operator P.O. BOX 1772 Hobbs NM 88240
Well Location Unit Letter N : 3300 Feet From The SOUTH Line and 1551 Feet From The WEST Line Section 6 Township 16-8 Range 36-E NMMPM LEA County
10. Elevation (Show whether DP, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RUN TUBING TO 9518' AND SPOT W/25 SKS AND WOC.
2. TAGGED PLUG AT 9400'
3. LOAD HOLE W/MUD
4. CUT AND LAID DOWN 4992' OF 5½ CASING
5. SPOT 25 SKS CEMENT PLUG AT 6500'
6. SPOT 140 SKS CEMENT PLUG AT 5½ STUB 5050' AND WOC
7. TAGGED PLUG AT 4927' SPOT W/60SKS CEMENT AND WOC
8. TAGGED PLUG AT 4670' SPOT W/45 SKS CEMENT AND WOC
9. TAGGED PLUG AT 4618'
10. SPOT 30 SKS CEMENT PLUG AT 2039'
11. SPOT 15 SKS CEMENT AT SURF AND SET UP P&A MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado TITLE P&A SUPERVISOR DATE 8-14-91
TYPE OR PRINT NAME RAYMOND MALDONADO TELEPHONE NO. (505) 397-35

(This space for State Use)

APPROVED BY Billy E. Freeman TITLE COMPLIANCE OFFICER DATE JAN 03 2003

CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-03737
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E 9335-5

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	7. Lease Name or Unit Agreement Name: STATE T
2. Name of Operator Pronghorn Mgt. Corp.	8. Well No. 4
3. Address of Operator P. O. Box 1772 Hobbs, NM 88241	9. Pool name or Wildcat Townsend Permo Upper Penn
4. Well Location Unit Letter <u>K</u> : <u>4620</u> feet from the <u>South</u> line and <u>1885</u> feet from the <u>West</u> line Section <u>6</u> Township <u>16S</u> Range <u>36E</u> NMPM Lea County	
10. Elevation (Show whether DR, RKE, RT, GR, etc.) 3958'	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:


- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Circulate hole with mud laden fluid. POOH with tubing.
2. Nipple up to 5 1/2" casing. Stretch, cut and pull 5501' casing.
3. Spot cement plug 50' in and out of stub. WOC - tag @ 5450'.
4. Spot 100' cement plug @ intermediate casing shoe. WOC - tag @ 4699'
5. Spot 100' cement plug @ top of salt. WOC and tag @ 1920'.
6. Nipple up to 8 5/8" casing. Stretch, cut, and pull 503' casing.
7. Spot cement plug 50' in and out of stub. WOC - Tag @ 450'.
8. Spot 100' cement plug @ 13 3/8" shoe. WOC tag @ 325'.
9. Spot 10 sx surface plug. Erect dry hole marker. Clean location.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Guy A. Baber TITLE PARTNER DATE 12/11/02
Type or print name Guy A. Baber Telephone No. 505-393-9176
(This space for State use)

APPROVED BY GARY W. WINTLE ORIGINAL SIGNED BY GARY W. WINTLE DATE JAN 03 2003
Conditions of approval, if any: OC FIELD REPRESENTATIVE II/STAFF MANAGER