



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
 OIL CONSERVATION DIVISION
 AZTEC DISTRICT OFFICE

BRUCE KING
 GOVERNOR

LARRY KEHOE
 SECRETARY

1000 RIO BRAZOS ROAD
 AZTEC, NEW MEXICO 87410
 (505) 334-8178

November 24, 1980

6735

Mr. H. D. Hollingsworth
 Dome Petroleum Corporation
 501 Airport Drive
 Farmington, New Mexico 87401

Re: Dome Petroleum Corporation
 Santa Fe 20 #2
 F-20-21N-8W

NOV 26 1980
 DISTRICT SUPERVISOR
 SANTA FE

Dear Holly:

On November 20, 1980, Mr. Gholson and I made an inspection of the above well and lease. We found the operations in violation of several provisions of Order R-6220:


1. There was no gauge or leak detection device installed on the well annulus. The two valves on the annulus were frozen shut and could not be opened.
2. The injection system was operating at approximately 1500 psi in violation of the 1155 psi limitation.

Other problems we found on inspection were as follows:

1. Lack of warning signs about poisonous gas.
2. An oil spill at the #3 well which will require notification as per Rule 116.

You are hereby directed to take immediate action to correct the violations. Please make arrangements with this office to inspect the well and lease after the violations are corrected.

If you have any questions, please contact this office.

Yours truly,

 Frank T. Chavez
 District Supervisor

xc: Reading File
 UIC File
 Mr. Ernest Padilla, General Counsel

FTC:no