		-	ا د	ן ט	Field indr Efroks			
		į	U R S	み R T	Name Mike Willliams Date 5-15-84	Miles <u>236</u>	_District	
	1	i T	٦	Ē R	Time of Departure 8:00 am Time of Return	3 : 30 pm	_Car No7595	
	7 7 10 N	Y		H O U R S	In the space below indicate the purpose of the trip performed, listing wells or leases visited and any signature	and the duties	<u>-</u>	
H	O E	G	3	2	Wells Shut-in, Pit full of water. Oil battery. Water line from Penroc Oil C England Fed battery. Operator notifie	ells H-30-6-26 & N-29-6-26 Deanie Lou Fed #1 & 2. Wells Shut-in. Pit full of water. Oil around battery. Water line from Penroc Oil Co. to England Fed battery. Operator notified to clean up mess & to quit taking Penroc water.		
	0	6	2		l Well C-32-6-26 Deanie Lou, Ring #1. Well rock over casing.	TA'd with		
1	0	6	2		l Well M-29-6-26 Charles W. Harle. Elliott Well TA'd with water running out of c			
					BEFORE EXAMINE OIL CONSERVATION OCO EXHIBIT IN CASE NO	NOS		
					Mileage UIC UIC RFA Other 236 Other Other	RFA	7 1/2	
YPE INSPECTION PERFORMED - Housekeeping - Flugging - Flugging Cleanup - Well Test - Hepair/Horkover - Waterflow - Hishap or Spill - Water Contamination - Other				н	INSPECTION CLASSIFICATION		SPECIFIC WELL	
			ing Crest	leani kova:	injection and production wells, water llows or pre tests, surface injection equipment, plugging, etc. R = inspections relating to Reclamation Fund Activity	ry I = Injec saure C = Combi)	ction tion ned prod. inj. ations ground Storage al Operation ity or location ng	