EXPLORATION AND PRODUCTION GROUP

May 11, 1987

1. AZ ; 1 ·

de

RE:

State 1-2 Well No. 1
East Lusk-Bone Springs Pool
Lea County, New Mexico

Oil Conservation Division
P. O. Box 2088
Santa Fe, New Mexico 87504-2088

ATTN: William J. LeMay, Director

Gentlemen:

Phillips Petroleum Company respectfully requests administrative approval for an exception to Rule No. 2 of the East Lusk-Bone Springs Pool Rules to allow a non-standard proration unit consisting of 120 acres. Pool Rules require 160 acres. Rule 3 allows administrative approval.

We had previously made this request (our letter of November 26, 1986 attached), but withdrew this request due to the protest of Los Siete Exploration, Inc. and Murphy Operating Corporation (letter attached). We now make this request again due to the subject well being placed in the East Lusk-Bone Springs Pool (see letter from Hobbs OCD Office attached). Also, attached is a copy of Form C-101, C-103, C-104, and copies of certified mail receipts to offset operators.

Your early attention to this request is appreciated.

Sincerely,

Larry M. Sanders, Supervisor Regulation and Proration

715- 367-1488

LMS:JLD:1sw REG/PRO4/exception2

Attachments

cc:

Oil Conservation Division

P. O. Box 1980

Hobbs, New Mexico 88240



EXPLORATION AND PRODUCTION GROUP

November 26, 1986

RE: State 1-2

Lease No. L-G888

East Lusk-Bone Springs Field Lea County, New Mexico

Carr and

Oil Conservation Division P. O. Box 2088 Santa Fe, New Mexico 87504-2088

Attn: R. L. Stamets, Director

Gentlemen:

Phillips Petroleum Company respectfully requests administrative approval for exception to Rule No. 2 of the East Lusk-Bone Springs Field Rules to allow a non-standard proration unit consisting of 120 acres. Field rules require 160 acres. Rule 3 allows administrative approval.

Previous completions in the Wolfcamp and Morrow formations have been uneconomical to produce. A successful completion in the Bone Springs will keep this well from being abandoned.

Attached for your information are copies of forms C-101, C-103, and copies of certified mail receipts to offset operators. See attached list.

Your early attention to this request is appreciated.

Yours very truly,

Larry M. Sanders

Regulation and Proration Supervisor

LMS/JLD/sdb REG4.1/east

Attachment

cc: Oil Conservation Division

P. O. Box 1980

Hobbs, New Mexico 88240

Sol West III P. O. Box 10120 El Paso, Texas 79992

J. M. Huber Corp. 2000 West Loop South Houston, Texas 77027

Chevron USA, Inc. P. 0. Box 670 Hobbs, New Mexico 88240

Tenneco Oil Co. Box 2511 Houston, Texas 77001

Shell Oil Co. Box 2463 Houston, Texas 77001

Petroleum Development Corp. 9720-B Candelaria Rd., N.E. Albuquerque, New Mexico 87112

Sun Exploration & Prod. Co. Box 2880 Dallas, Texas 75221

Superior Oil Co. Box 1521 Houston, Texas 77251

Davoil Inc. P. O. Box 12507 Ft. Worth, Texas 76116

	MENT OIL (	CONSERVATION	ON DIVISION		Form C-101	
or cortex accesses					Revised 10-1-78	
DISTRIBUTION	SANIA FE, NEW MEXICO 87501				SA. Indicate Type of Lease	
SANTA FE FILE	-{				BTATE	X
U.S.G.S.					S. Siale Oil L-G	6 Gas Lease No.
OF AAT OR	<u> </u>				111111	
APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK						
is. Type of Work					7. Unit Agre	rement Name
DRILL		DEEPEN	PLUG I	BACK X		
b. Type of Well		-			8. Form or L	
OIL XX GAS WELL	OTHER		SINGLE XX MUL	TIPLE 20NE	State	
•					9. Well No.	1
Phillips Petroleum C	Ompany				10 Field -	nd Pool, or Wildeat
4001 Penbrook St., O	dessa. Texas	79762	•			isk-Bone Springs
	E Loca		North		mm	
UNIT LETTER		ATED FI	LET FROM THE North	LINE		
AND 660 FEET FROM THE	West	E OF SEC. 2	NP. 19-S RGE. 32-	E NUPL		
	innennii:		millim	TITTI	12, County	mHHH:
					Lea	
				(11/1//	77777	
				9A. Formation		20. Retary or C.T.
		1111111111	10150	Bone Sp	<del></del>	
3691 GR, 3712 RKB	etc.) 21A. Kind	6 Status Plug. Bond 2	IB. Drilling Contractor		1	. Date Work will start
JOJI GIG, JIIZ IQQD		į.			Upon A	ໄກກຽດນາ i
21					1	PPIOVAL
23.	#)	RRROSSO CASING AND	CEMENT PROGRAM		1	pprovar
	<del></del>	· · · · · · · · · · · · · · · · · · ·	,	Tevere of		
SIZE OF HOLE SI	ZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH		CEMENT	EST. TOP
SIZE OF HOLE SI	<del></del>	· · · · · · · · · · · · · · · · · · ·	SETTING DEPTH	450 sk	CEMENT	EST. TOP Surface
SIZE OF HOLE SI	ZE OF CASING	WEIGHT PER FOOT 48# & 54#	SETTING DEPTH	450 sk 612 sk	CEMENT "C" H DV @ 3	EST. TOP Surface 300'; 2nd stage
SIZE OF HOLE SI	ZE OF CASING	WEIGHT PER FOOT 48# & 54#	SETTING DEPTH	450 sk 612 sk 1260 sk	CEMENT "C" H DV @ 3	EST. TOP Surface 300'; 2nd stage 0 sk "C"-surface
SIZE OF HOLE SI 17-1/2 " 11" 7-7/8"	ZE OF CASING 13-3/4" 8-5/8" 5-1/2"	WEIGHT PER FOOT 48# & 54# 32#	SETTING DEPTH 444' 5040'	450 sk 612 sk	CEMENT "C" H DV @ 3	EST. TOP Surface 300'; 2nd stage 0 sk "C"-surface 11845 (Temp.
SIZE OF HOLE SI 17-1/2 " 11" 7-7/8"  Present status: Lus	ZE OF CASING 13-3/4" 8-5/8" 5-1/2" k Wolfcamp, Ea	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD	SETTING DEPTH 444' 5040' 13670' 12950';	450 sk 612 sk 1260 sk 1600 sk	CEMENT "C" H DV @ 3	EST. TOP Surface 300'; 2nd stage 0 sk "C"-surface
SIZE OF HOLE SI 17-1/2 " 11" 7-7/8"  Present status: Lusi	ZE OF CASING 13-3/4" 8-5/8" 5-1/2" k Wolfcamp, Eat test 9/5/86:	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11	SETTING DEPTH 444' 5040' 13670' 12950'; MCFGPD, 11 BWPI	450 sk 612 sk 1260 sk 1600 sk	CEMENT "C" H DV @ 3 LW + 10	EST. TOP Surface 300'; 2nd stage 0 sk "C"-surface 11845 (Temp. Survey)
SIZE OF HOLE SI 17-1/2 " 11" 7-7/8"  Present status: Lusi Las Proposed Procedure:	ZE OF CASING 13-3/4" 8-5/8" 5-1/2" k Wolfcamp, Eat test 9/5/86: Pull rods & p	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP.	SETTING DEPTH 444' 5040' 13670' 12950'; MCFGPD, 11 BWPI	450 sk 612 sk 1260 sk 1600 sk	CEMENT "C" H DV @ 3 LW + 10 "H"	EST. TOP Surface 300'; 2nd stage 0 sk "C"-surface 11845 (Temp. Survey)
SIZE OF HOLE SI 17-1/2 " 11" 7-7/8"  Present status: Lusi Las Proposed Procedure: w/dump bailer & du	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top	SETTING DEPTH 444' 5040' 13670' 12950'; MCFGPD, 11 BWPI COOH w/tbg. MI	450 sk 612 sk 1260 sk 1600 sk	CEMENT "C" H DV @ 3 LW + 10 "H"	EST. TOP Surface 300'; 2nd stage 0 sk "C"-surface 11845 (Temp. Survey)
SIZE OF HOLE SI 17-1/2 " 11" 7-7/8"  Present status: Lus Las Proposed Procedure: w/dump bailer & du Load hole w/240 bb	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class 1s. 2% KC1 wti	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top T. Pressure tes	SETTING DEPTH  444'  5040'  13670'  12950';  MCFGPD, 11 BWPI COOH w/tbg. MI of CIBP @ 1295	450 sk 612 sk 1260 sk 1600 sk	CEMENT "C" H DV @ 3 LW + 10 "H"  celine un	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp.  Survey)  it. GIH  10350'.
SIZE OF HOLE SI 17-1/2 " 11" 7-7/8"  Present status: Lus Las Proposed Procedure: w/dump bailer & du Load hole w/240 bb 50 bbls. 10% acetic	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86; Pull rods & pmp 5 sk Class 1s. 2% KCl wtre acid from 10	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top T. Pressure tes 0200' to 8000'.	SETTING DEPTH 444' 5040' 13670' 12950'; MCFGPD, 11 BWPI COOH w/tbg. MI o of CIBP @ 1295 st bridge plug & COOH w/tbg. GI	450 sk 612 sk 1260 sk 1600 sk & RU wir 60'. Set	CEMENT "C" H DV @ 3 LW + 10 "H"  Teline un CIBP @ 500 psi	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp.  Survey)  sit. GIH  10350'.  Spot
SIZE OF HOLE SI 17-1/2 "  11"  7-7/8"  Present status: Lus Las Proposed Procedure: w/dump bailer & du Load hole w/240 bb 50 bbls. 10% acetic Bone Spring format	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class 1s. 2% KCl wtrocacid from 10 ion as follows	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top T. Pressure tes 0200' to 8000'.	SETTING DEPTH 444' 5040' 13670' 12950'; MCFGPD, 11 BWPI COOH w/tbg. MI o of CIBP @ 1295 st bridge plug & COOH w/tbg. GI	450 sk 612 sk 1260 sk 1600 sk & RU wir 60'. Set	CEMENT "C" H DV @ 3 LW + 10 "H"  Teline un CIBP @ 500 psi	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp.  Survey)  sit. GIH  10350'.  Spot
SIZE OF HOLE SI  17-1/2 "  11"  7-7/8"  Present status: Lusi Las  Proposed Procedure: w/dump bailer & du Load hole w/240 bb 50 bbls. 10% acetic Bone Spring format phasing, top to bt Zone 1 8145	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class ls. 2% KCl wtrocacid from 10 ion as follows m.: -8161' 16'	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top T. Pressure tes 200' to 8000'. S using deep per	SETTING DEPTH 444' 5040' 13670' 12950'; MCFGPD, 11 BWPI COOH w/tbg. MI o of CIBP @ 1295 st bridge plug & COOH w/tbg. GI	450 sk 612 sk 1260 sk 1600 sk 6 RU wir 60'. Set c csg. to H w/4" c harges, 2	H DV @ 3 LW + 10 "H" eline un CIBP @ 500 psi asing gu SPF, spi	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp.  Survey)  sit. GIH  10350'.  Spot
SIZE OF HOLE SI 17-1/2 "  11"  7-7/8"  Present status: Lusi Las Proposed Procedure: w/dump bailer & du Load hole w/240 bb 50 bbls. 10% acetic Bone Spring format phasing, top to bt Zone 1 8145' Zone 2 8664'	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class ls. 2% KCl wtr c acid from 10 ion as follows m.: -8161' 16' -8672' 8'	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top r. Pressure tes 0200' to 8000'. s using deep per  32 holes 16 holes	SETTING DEPTH  444'  5040'  13670'  12950';  MCFGPD, 11 BWPF COOH w/tbg. MI o of CIBP @ 1295 st bridge plug & COOH w/tbg. GI netrating DML ch	450 sk 612 sk 1260 sk 1600 sk 8 RU wir 60'. Set csg. to H w/4" c harges, 2	CEMENT "C" H DV @ 3 LW + 10 "H"  eline un CIBP @ 500 psi asing gu SPF, spi les les	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp. Survey)  sit. GIH  10350' Spot m & perforate ral shot
SIZE OF HOLE SI  17-1/2 "  11"  7-7/8"  Present status: Lus Las Proposed Procedure:    w/dump bailer & du    Load hole w/240 bb    50 bbls. 10% acetic Bone Spring format    phasing, top to bt         Zone 1 8145 2         Zone 2 8664 2  9206 1	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class 1s. 2% KC1 wtr c acid from 10 ion as follows m.: -8161' 16' -8672' 8' -9210' 4'	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top r. Pressure tes 0200' to 8000'. s using deep per  32 holes 16 holes 8 holes	SETTING DEPTH  444'  5040'  13670'  12950';  MCFGPD, 11 BWPI COOH w/tbg. MI o of CIBP @ 1295 st bridge plug & COOH w/tbg. GI netrating DML ch	450 sk 612 sk 1260 sk 1600 sk 6 RU wir 60'. Set 6 csg. to 6 csg. to 6 arges, 2	CEMENT "C" H DV @ 3 LW + 10 "H"  eline un CIBP @ 500 psi asing gu SPF, spi les les	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp. Survey)  it. GIH  10350' Spot in & perforate ral shot
SIZE OF HOLE SI 17-1/2 "  11"  7-7/8"  Present status: Lus Las Proposed Procedure: w/dump bailer & du Load hole w/240 bb 50 bbls. 10% acetic Bone Spring format phasing, top to bt Zone 1 8145; Zone 2 8664; 9206; Zone 3 9214;	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class 1s. 2% KCl wtrocacid from 10 ion as follows m.:  -8161' 16' -8672' 8' -9210' 4' -9220' 6'	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top r. Pressure tes 0200' to 8000'. s using deep per  32 holes 16 holes 8 holes 12 holes	SETTING DEPTH  444'  5040'  13670'  12950';  MCFGPD, 11 BWPI COOH w/tbg. MI o of CIBP @ 1295 st bridge plug & COOH w/tbg. GI netrating DML ch	450 sk 612 sk 1260 sk 1600 sk 6 RU wir 60'. Set csg. to H w/4" c harges, 2	CEMENT "C" H DV @ 3 LW + 10 "H"  reline un CIBP @ 500 psi asing gu SPF, spi les les	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp. Survey)  sit. GIH  10350' Spot m & perforate ral shot
SIZE OF HOLE SI  17-1/2 "  11"  7-7/8"  Present status: Lus Las Proposed Procedure: w/dump bailer & du Load hole w/240 bb 50 bbls. 10% acetic Bone Spring format phasing, top to bts Zone 1 8145' Zone 2 8664' 9206' Zone 3 9214' 9239'	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class 1s. 2% KCl wtrocacid from 10 ion as follows m.: -8161' 16' -8672' 8' -9210' 4' -9220' 6' -9251' 12'	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top c. Pressure tes 2200' to 8000'. s using deep per  32 holes 16 holes 8 holes 12 holes 24 holes	SETTING DEPTH  444'  5040'  13670'  12950';  MCFGPD, 11 BWPI COOH w/tbg. MI o of CIBP @ 1295 st bridge plug & COOH w/tbg. GI netrating DML ch 3646'-8656' 10 3680'-8690' 10	450 sk 612 sk 1260 sk 1600 sk 6 RU wir 60'. Set 6 csg. to 120 ho 120 ho 120 ho	CEMENT "C" H DV @ 3 LW + 10 "H"  celine un CIBP @ 500 psi asing gu SPF, spi les les T les	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp. Survey)  it. GIH  10350' Spot in & perforate ral shot
SIZE OF HOLE SI  17-1/2 "  11"  7-7/8"  Present status: Lusi Las Proposed Procedure:    w/dump bailer & du    Load hole w/240 bb    50 bbls. 10% aceti    Bone Spring format    phasing, top to bt         Zone 1 8145;         Zone 2 8664;         9206;         Zone 3 9214;         9239;         Zone 4 10060;	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eattest 9/5/86: Pull rods & pmp 5 sk Class ls. 2% KCl wtrocacid from 10 ion as follows m.: -8161' 16' -8672' 8' -9210' 4' -9220' 6' -9251' 12' -10064' 4'	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top C. Pressure tes 200' to 8000'. S using deep per  32 holes 16 holes 8 holes 12 holes 24 holes 8 holes	SETTING DEPTH  444'  5040'  13670'  12950';  MCFGPD, 11 BWPI COOH w/tbg. MI o of CIBP @ 1295 st bridge plug & COOH w/tbg. GI netrating DML ch 3646'-8656' 10 3680'-8690' 10 9224'-9234' 10	450 sk 612 sk 1260 sk 1600 sk 1600 sk 6 RU wir 60'. Set 6 csg. to 120 ho 120 ho 120 ho 120 ho 120 ho	CEMENT "C" H DV @ 3 LW + 10 "H"  celine un CIBP @ 500 psi asing gu SPF, spi les les tes	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp. Survey)  it. GIH  10350' Spot in & perforate ral shot
SIZE OF HOLE SI  17-1/2 "  11"  7-7/8"  Present status: Lus  Las  Proposed Procedure:  w/dump bailer & du  Load hole w/240 bb  50 bbls. 10% acetic  Bone Spring format  phasing, top to bt:  Zone 1 8145'  Zone 2 8664'  9206'  Zone 3 9214'  9239'  Zone 4 10060'  NABOVE PRACE DESCRIBE PROPO	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class 1s. 2% KCl wtrocacid from 10 ion as follows m.: -8161' 16' -8672' 8' -9210' 4' -9220' 6' -9251' 12' -10064' 4'	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top c. Pressure tes 2200' to 8000'. s using deep per  32 holes 16 holes 8 holes 12 holes 24 holes 8 holes 8 holes	SETTING DEPTH  444'  5040'  13670'  12950';  MCFGPD, 11 BWPI COOH w/tbg. MI o of CIBP @ 1295 st bridge plug & COOH w/tbg. GI netrating DML ch 3646'-8656' 10 3680'-8690' 10 9224'-9234' 10	450 sk 612 sk 1260 sk 1600 sk 1600 sk 6 RU wir 60'. Set 6 csg. to 120 ho 120 ho 120 ho 120 ho 120 ho	CEMENT "C" H DV @ 3 LW + 10 "H"  celine un CIBP @ 500 psi asing gu SPF, spi les les tes	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp. Survey)  it. GIH  10350' Spot in & perforate ral shot  otal of 94' & 188 holes
SIZE OF HOLE SI  17-1/2 "  11"  7-7/8"  Present status: Lus  Las  Proposed Procedure:  w/dump bailer & du  Load hole w/240 bb  50 bbls. 10% acetic  Bone Spring format  phasing, top to bt:  Zone 1 8145'  Zone 2 8664'  9206'  Zone 3 9214'  9239'  Zone 4 10060'  NABOVE PRACE DESCRIBE PROPO	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class 1s. 2% KCl wtrocacid from 10 ion as follows m.: -8161' 16' -8672' 8' -9210' 4' -9220' 6' -9251' 12' -10064' 4'	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top C. Pressure tes 200' to 8000'. S using deep per  32 holes 16 holes 8 holes 12 holes 24 holes 8 holes	SETTING DEPTH  444'  5040'  13670'  12950';  MCFGPD, 11 BWPI COOH w/tbg. MI o of CIBP @ 1295 st bridge plug & COOH w/tbg. GI netrating DML ch 3646'-8656' 10 3680'-8690' 10 9224'-9234' 10	450 sk 612 sk 1260 sk 1600 sk 1600 sk 6 RU wir 60'. Set 6 csg. to 120 ho 120 ho 120 ho 120 ho 120 ho	CEMENT "C" H DV @ 3 LW + 10 "H"  celine un CIBP @ 500 psi asing gu SPF, spi les les tes	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp. Survey)  it. GIH  10350' Spot in & perforate ral shot  otal of 94' & 188 holes
SIZE OF HOLE SI  17-1/2 "  11"  7-7/8"  Present status: Lus  Las  Proposed Procedure:  w/dump bailer & du  Load hole w/240 bb  50 bbls. 10% acetic  Bone Spring format  phasing, top to bt:  Zone 1 8145'  Zone 2 8664'  9206'  Zone 3 9214'  9239'  Zone 4 10060'  NABOVE PRACE DESCRIBE PROPO	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class 1s. 2% KCl wtrocacid from 10 ion as follows m.: -8161' 16' -8672' 8' -9210' 4' -9220' 6' -9251' 12' -10064' 4'	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top T. Pressure tes 0200' to 8000'. s using deep per  32 holes 16 holes 8 holes 12 holes 24 holes 8 holes 12 holes 13 holes 14 holes 8 holes 15 holes 16 holes 17 holes 18 holes 18 holes 19 holes 19 holes 10 holes 11 holes 12 holes 13 holes 14 holes 15 holes 16 holes 17 holes 18 holes	12950'; 12950'; MCFGPD, 11 BWPI COOH w/tbg. MI of CIBP @ 1295 st bridge plug & COOH w/tbg. GI netrating DML ch 3646'-8656' 10 3680'-8690' 10 3224'-9234' 10 10100'-10114' 14	450 sk 612 sk 1260 sk 1600 sk 6 RU wir 60'. Set c csg. to H w/4" c harges, 2 0' 20 ho 0' 20 ho	CEMENT "C" H DV @ 3 LW + 10 "H"  celine un CIBP @ 500 psi asing gu SPF, spi les les tes les	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp. Survey)  Att. GIH  10350'.  Spot  a perforate  ral shot  otal of 94'  & 188 holes  (over)
SIZE OF HOLE SI  17-1/2 "  11"  7-7/8"  Present status: Lus  Las  Proposed Procedure:  w/dump bailer & du  Load hole w/240 bb  50 bbls. 10% acetic  Bone Spring format  phasing, top to bt:  Zone 1 8145'  Zone 2 8664'  9206'  Zone 3 9214'  9239'  Zone 4 10060'  NABOVE PRACE DESCRIBE PROPO	ZE OF CASING  13-3/4"  8-5/8"  5-1/2"  k Wolfcamp, Eat test 9/5/86: Pull rods & pmp 5 sk Class 1s. 2% KCl wtrocacid from 10 ion as follows m.: -8161' 16' -8672' 8' -9210' 4' -9220' 6' -9251' 12' -10064' 4'	WEIGHT PER FOOT  48# & 54#  32#  17#  ast field; PBTD: 3.8 BOPD, 11  Dump. NU BOP. "H" cmt. on top T. Pressure tes 0200' to 8000'. s using deep per  32 holes 16 holes 8 holes 12 holes 24 holes 8 holes 12 holes 13 holes 14 holes 8 holes 15 holes 16 holes 17 holes 18 holes 18 holes 19 holes 19 holes 10 holes 11 holes 12 holes 13 holes 14 holes 15 holes 16 holes 17 holes 18 holes	SETTING DEPTH  444'  5040'  13670'  12950';  MCFGPD, 11 BWPI COOH w/tbg. MI o of CIBP @ 1295 st bridge plug & COOH w/tbg. GI netrating DML ch 3646'-8656' 10 3680'-8690' 10 9224'-9234' 10	450 sk 612 sk 1260 sk 1600 sk 6 RU wir 60'. Set c csg. to H w/4" c harges, 2 0' 20 ho 0' 20 ho	CEMENT "C" H DV @ 3 LW + 10 "H"  celine un CIBP @ 500 psi asing gu SPF, spi les les tes	EST. TOP  Surface  300'; 2nd stage  0 sk "C"-surface  11845 (Temp. Survey)  Att. GIH  10350'.  Spot  a perforate  ral shot  otal of 94'  & 188 holes  (over)

## PROCEDURE Contd.:

GIH w/RBP & RTTS-type packer on 2-7/8" tbg. Set RBP @ ±10200' & set packer @ ±9950'. Swab well to clean up perforations. Acidize Zone 4 Bone Spring perforations w/2700 gals. 15% NEFE HCl acid containing fines suspension agent & clay stabilizer. Flush acid to perforations w/61 bbls. 2% KCl water. Swab test well.

Unseat packer, unseat RBP. Reset RBP @ ±9350', set packer @ ±9320' & test RBP to 1000 psi. Unseat packer & reset @ ±9100'. Swab test well to clean up perforations. Acidize Zone 3 Bone Spring perforations w/3200 gals. 15% NEFE HCl acid containing fines suspension agent & clay stabilizer. Flush acid to perforations with 56 bbls. 2% KCl wtr. Swab test well. Unseat packer, unseat RBP. Reset RBP @±8800', set packer @ 8770' & test RBP to 1000 psi. Unseat packer & reset @ 8500'. Swab test well to clean up perforations. Acidize Zone 2 Bone Spring perforations w/2800 gals. 15% NEFE HCl acid containing fines suspension agent & clay stabilizer. Flush acid to perforations w/54 bbls. 2% KCl wtr. Swab test well.

Unseat packer, unseat RBP. Reset RBP @±8250', Set packer @ 8220' & test RBP to 1000 psi. Unseat packer & reset @ ±8000'. Swab test well to clean up perforations. Acidize Zone 1 Bone Spring perforations w/2400 gals. 15% NEFE HC1 acid containing fines suspension agent and clay stabilizer. Flush acid to perforations w/50 bbls. 2% KCl wtr. Swab test well.

Maximum treating rate 4 BPM @ 4000 psi maximum surface pressure. Maintain 500 psi on tbg.-csg. annulus while acidizing.

Unseat packer, unseat RBP. COOH w/tbg., packer, & bridge plug. GIH w/10000' 2-7/8" production tbg. GIH w/1-1/16" pump on rod string. (188 4700' 5/8" rods, 81 2025' 3/4" rods, 72 1800' 7/8" rods, 64 1600' 1" rods).

Hang well on. Run unit @ 10 SPM & 120" stroke.

All distances must be from the outer boundaries of the Section Operator Legae Well No. Phillips Petroleum Company State 1-2 1 Township Unit Letter Section Range County Ε 19-S 32-E Lea Actual Foctage Location of Well: 1980 North 660 teet from the line and West Ground Level Elev. Producing Formation Dedicated Acreage: 3681 GR Bone Springs East Lusk - Bone Springs 120 Acres 1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below, 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty). 3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling. etc? If answer is "yes," type of consolidation \_ Yes □No If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.). No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Commission. CERTIFICATION D C В Α I hereby certify that the information contained herein is true and complete to the W.J. Muelle F G Н Eng. Supervisor, Reservoir 660' Phillips Petroleum Co. Date 11/25/86 K J Ι I hernby certify that the well location notes of actual surveys made by me ar er my supervision, and that the same true and correct to the best of my knowledge and belief. P 10-31-82 Date Surveyed John W. West Registered Professional Engineer and/or Land Surveyor Certificate No. John West #676 Patrick A. Romero #6663

1980 2310





**EXPLORATION AND PRODUCTION GROUP** 

January 5, 1987

State 1-2 Well No. 1 Lease No. L-G888 East Lusk-Bone Springs Field Lea County, New Mexico

Oil Conservation Division
P. O. Box 2088
Santa Fe, New Mexico 87504-2088

ATTN: Michael Stogner

Gentlemen:

Phillips Petroleum Company has requested administrative approval, our letter dated November 26, 1986, for an exception to Rule 2 of the East Lusk-Bone Springs Field Rules to allow a non-standard proration unit consisting of 120 acres instead of the required 160 acres. At this time, Phillips respectfully requests this application be withdrawn and returned to the letterhead address to my attention.

By copy of this letter to the Hobbs District Office, our application to plug back is also being withdrawn, and will be re-submitted at a later date. If this request has been set for hearing, we request it be dismissed.

Sincerely.

Larry M. Sanders, Supervisor Regulation and Proration

LMS:1sw REG/state

cc: Oil Conservation Division P. O. Box 1980

Hobbs, New Mexico 88240

Offset Operators