



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Wyoming State Office Reservoir Management Group
2987 Prospector Drive
Casper, Wyoming 82604-2968



In Reply Refer To:
3186
(3186.1)
Poker Lake Unit
NMNM71016X

OCT 03 2017

R-153

Mr. Law Armstrong
BOPCO, L.P.
810 Houston Street
Fort Worth, Texas 76102-6203

Re: Paying Well Determination
Poker Lake No. 49
SW $\frac{1}{4}$ NW $\frac{1}{4}$, Sec. 17, T.24S., R.30E.
Poker Lake Unit
Eddy County, New Mexico

Dear Mr. Armstrong:

We have determined that under existing conditions the Poker Lake No. 49 well is **not** capable of producing unitized substances from the Delaware Formation in unit paying quantities. The well was completed in the Delaware Formation on October 7, 2003. Production from the Delaware Formation shall be handled and reported on a lease basis retroactive to the date of first production (October 14, 2003). The well is located on Lease No. NMNM02860.

If you have any questions, please call the undersigned at (307) 261-7685.

Sincerely,

/s/ J. David Chase

J. David Chase
Chief, Reservoir Management Group

cc: NMSO, James Glover
CFO, Chris Walls
ONRR, Glen Reese
New Mexico State Land Office, Anchor Holm
New Mexico Oil Conservation Division, William Jones