



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Wyoming State Office Reservoir Management Group
2987 Prospector Drive
Casper, Wyoming 82604-2968



In Reply Refer To:
3186
(3186.1)
Poker Lake Unit
NMNM71016X

OCT 03 2017

R-153

Mr. Law Armstrong
BOPCO, L.P.
810 Houston Street
Fort Worth, Texas 76102-6203

Re: Paying Well Determination
Poker Lake Unit CVX BS No. 25H
SHL: NW $\frac{1}{4}$ NW $\frac{1}{4}$, Sec. 23, T.25S., R.30E. (NMCL063873A)
BHL: SW $\frac{1}{4}$ NW $\frac{1}{4}$, Sec. 26, T.25S., R.30E. (NMCL063875A)
Poker Lake Unit
Eddy County, New Mexico

Dear Mr. Armstrong:

We have determined that under existing conditions the Poker Lake Unit CVX BS No. 25H well is **not** capable of producing unitized substances from the Bone Spring Formation in unit paying quantities. The well was completed in the Bone Spring Formation on June 4, 2014. Since the well was determined to be a nonpaying unit well, a drilling and spacing unit must be established for the well so that a communitization agreement can be approved by the Carlsbad Field Office.

If you have any questions, please call the undersigned at (307) 261-7685.

Sincerely,

/s/ J. David Chase

J. David Chase
Chief, Reservoir Management Group