Form 3160-5 (June 2015)

NMOCD Rec'd: 10/01/2020 **UNITED STATES** DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM02953

SUNDRY NOTICES AND REPORTS ON WELLS

BUREAU OF LAND MANAGEMENT

De material de	indirects AND REI O	-/-:// (-LLO		141011410102000	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. 891000558X	
Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. JAMES RANCH UNIT DI 1A ENNIS 115H	
Name of Operator					9. API Well No. 30-015-45611-00-X1	
3a. Address 6401 HOLIDAY HILL ROAD E MIDLAND, TX 79707	. (include area code 0-4374			xploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State		
Sec 21 T22S R30E SENW 1608FNL 2605FEL 32.380890 N Lat, 103.886826 W Lon					EDDY COUNTY, NM	
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	ΓE NATURE C	F NOTICE,	REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent ■	☐ Acidize	□ Dee	□ Deepen		ion (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclamation		■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recomplete		☐ Other
☐ Final Abandonment Notice	☐ Change Plans	Plug	☑ Plug and Abandon ☐ T		porarily Abandon	
	☐ Convert to Injection	Plug	☐ Plug Back ☐ Water I		Pisposal	
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fix XTO Permian Operating, LLC conjuncture with a drill and ab Drilled to 550? and lost 100% 1. Tag CIBP @ 466'. 2. Circulate 14.8ppg cmt fr/46: 3. Cut off WH. Install dry hole 4. Skid Rig. Attachments: Current WBD Proposed (PA) WBD	rk will be performed or provide loperations. If the operation resonationment Notices must be filinal inspection. respectfully submits the fandon. Plug and abandor returns. Unable to heal loof to surf. WOC 4 hours. marker.	the Bond No. or sults in a multipled only after all following plughment is requesses.	a file with BLM/BL completion or recrequirements, inclu & abandon proested due to los	A. Required sub- ompletion in a r ding reclamation cedure in st returns.	psequent reports must be a new interval, a Form 3166 n, have been completed as	filed within 30 days 0-4 must be filed once
	For XTO PERMI nmitted to AFMSS for proc	AN OPERATII	IG LLC, sent to BORAH HAM on	the Carlsbad 09/30/2020 (20	DDMH0189SE)	
Name(Printed/Typed) KELLY KA	אויטט		Title REGU	LATURT CU	ORDINATOR	
Signature (Electronic S	Submission)		Date 09/30/2	2020		
this space for federal or state office use						
_Approved By_CHRISTOPHER WALLS			TitlePETROLE	EUM ENGINE	EER	Date 09/30/2020
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carlsbad			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Revisions to Operator-Submitted EC Data for Sundry Notice #532224

Operator Submitted BLM Revised (AFMSS)

ABD NOI Sundry Type: NOI

NMNM06808 Lease: NMNM02953

Agreement: NMNM70965X 891000558X (NMNM70965X)

XTO PERMIAN OPERATING LLC 6401 HOLIDAY HILL ROAD BLDG 5 MIDLAND, TX 79707 Ph: 432.683 2277 Operator: XTO PERMIAN OPERATING, LLC

6401 HOLIDAY HILL RD BLDG 5 MIDLAND, TX 79707 Ph: 432-620-4374

KELLY KARDOS Admin Contact:

KELLY KARDOS REGULATORY COORDINATOR REGULATORY COORDINATOR E-Mail: kelly_kardos@xtoenergy.com E-Mail: kelly_kardos@xtoenergy.com

Ph: 432-620-4374 Ph: 432-620-4374

Tech Contact:

KELLY KARDOS REGULATORY COORDINATOR KELLY KARDOS REGULATORY COORDINATOR E-Mail: kelly_kardos@xtoenergy.com E-Mail: kelly_kardos@xtoenergy.com

Ph: 432-620-4374 Ph: 432-620-4374

Location:

NM EDDY State: NM County: **EDDY** Field/Pool: LOS MEDANOS WOLFCAMP **WILDCAT**

JAMES RANCH UNIT DI 1A ENNIS 115H Well/Facility:

JAMES RANCH UNIT DI 1A ENNIS 115H Sec 21 T22S R30E SENW 1608FNL 2605FEL Sec 21 T22S R30E Mer NMP SENW 1608FNL 2605FEL

32.380890 N Lat, 103.886826 W Lon

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.


Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:

From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted

Current WBD







P&A'd WBD



