



NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

DEC 14 1953

WELL RECORD

Mail to District Office, Oil Conservation Commission, to which Form C-101 was sent not later than twenty days after completion of well. Follow instructions in Rules and Regulations of the Commission. Submit in QUINTUPLICATE.

AREA 640 ACRES
LOCATE WELL CORRECTLY

Humble Oil & Refining Company
(Company or Operator)

Santa Fe Pacific Ry. Company
(Lease)

Well No. 1, in SE 1/4 of SE 1/4, of Sec. 18, T. 6-N, R. 1-W, NMPM.

West Los Lunas W/C Pool, Valencia County.

Well is 660 feet from South line and 660 feet from East line

of Section 18. If State Land the Oil and Gas Lease No. is _____

Drilling Commenced 1-29-53, 19____. Drilling was Completed 11-11-53, 19____.

Name of Drilling Contractor Durham Drilling Company, Inc.

Address Midland, Texas

Elevation above sea level at Top of Tubing Head 5092 DF. The information given is to be kept confidential until _____, 19____.

OIL SANDS OR ZONES

No. 1, from None to _____ No. 4, from _____ to _____

No. 2, from _____ to _____ No. 5, from _____ to _____

No. 3, from _____ to _____ No. 6, from _____ to _____

IMPORTANT WATER SANDS

Include data on rate of water inflow and elevation to which water rose in hole.

No. 1, from None to _____ feet.

No. 2, from _____ to _____ feet.

No. 3, from _____ to _____ feet.

No. 4, from _____ to _____ feet.

CASING RECORD

SIZE	WEIGHT PER FOOT	NEW OR USED	AMOUNT	KIND OF SHOE	CUT AND PULLED FROM	PERFORATIONS	PURPOSE
13-3/8	54.5	New	534.66	Howco			
9-5/8	40 & 36	New	5807.00	Howco			
7-5/8	26.4 & 29.7	New & Used	10,966.50	Howco			
(7-5/8)	26.4 & 29.7		5115.00		Cut casing at 5128' and patched on)		

MUDDING AND CEMENTING RECORD

SIZE OF HOLE	SIZE OF CASING	WHERE SET	NO. SACKS OF CEMENT	METHOD USED	MUD GRAVITY	AMOUNT OF MUD USED
17-1/2	13-3/8	552.19	700	Halliburton	9.5	
12-1/4	9-5/8	5820.00	2500	Halliburton	10.3	
8-3/4	7-5/8	10980.00	500	Halliburton	11.1	
(Patch-on 7-5/8)	5128.50					Cut casing at 5128' and patched-on with Bowen casing bowl

RECORD OF PRODUCTION AND STIMULATION

(Record the Process used, No. of Qts. or Gals. used, interval treated or shot.)

None

Result of Production Stimulation _____

Depth Cleaned Out _____