

**C-141**

**10/11/2004**

AP-113

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

*Holly Energy Partners*

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Navajo Pipeline	Contact <input type="checkbox"/> Johnny Lackey
Address 311 West Quay, Artesia, NM 88210	Telephone No. <input type="checkbox"/> 505-748-8942
Facility Name Hobbs Tank Farm	Facility Type <input type="checkbox"/> Crude Oil Storage
Surface Owner	Mineral Owner
Lease No. <input type="checkbox"/> N/A	

### LOCATION OF RELEASE

32.6517 103.1421

Unit Letter	Section NE 1/4 Sec 22	Township 19S	Range 38E	Feet from the	North/South Line	Feet from the	East/West Line	County Lca
-------------	-----------------------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

### NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release	Volume Recovered <input type="checkbox"/>
Source of Release Pipeline leak	Date and Hour of Occurrence 7/22/04, unknown	Date and Hour of Discovery 7/22/04, 2:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink	
By Whom? <input type="checkbox"/> Johnny Lackey, Holly Energy Partners	Date and Hour <input type="checkbox"/> 7/22/04, 4:45pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The 6" unloading line from the truck unloading rack to Tank 5201 developed a leak inside the tank retaining dike. The line was blocked in at the tank, line depressured and a clamp was installed at the leak. Leak was a result of external corrosion.

Describe Area Affected and Cleanup Action Taken.\*

An area approximately 4 feet wide and 20 feet long and 18 feet deep was stained with crude oil. There was no free liquid. Stained soil will be dug out and disposed of at permitted disposal site and fresh dirt placed in the excavated area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature:

*Johnny Lackey*

Approved by ☐ District Supervisor:

Printed Name: Johnny Lackey

Title: Safety/Environmental Supervisor

Approval Date:

Expiration Date:

Date: 10/11/04

Phone: 505-748-8942

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary