

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Form C-141
Revised August 8, 2011
By **OCD; Dr. Oberding at 9:04 am, Feb 26, 2015**
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Frontier Field Services, LLC	Contact John Prentiss	
Address 65 Mercado Street, Suite 250, Durango, CO 81301	Telephone No. 575-676-3528	
Facility Name Anderson Ranch Discharge Line - #1	Facility Type Condensate transport line	
Surface Owner Frontier Field Services, LLC	Mineral Owner	API No. N/A

LOCATION OF RELEASE

Unit Letter	Section 14	Township 16	Range 32	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	-------------------	--------------------	-----------------	---------------	------------------	---------------	----------------	-------------------

Latitude **32.936766 N** Longitude **-103.734009 W**

NATURE OF RELEASE

Type of Release Historic LOPC of condensate from buried pipeline	Volume of Release Estimated 20bbl subsurface	Volume Recovered: ~2bbl recovered from surface. Excavation underway.
Source of Release Historic pinhole leak discovered in buried heavy condensate pipeline	Date and Hour of Occurrence Historic	Date and Hour of Discovery 1/30/15
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomáš Oberding - NMOCD	
By Whom? Greg Busch - EHS Technician III	Date and Hour 1/30/15 @ 16:08	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*



On 1/30/2015 Frontier Field Services discovered a historic release along the Anderson Ranch Pipeline. Frontier estimated the release to exceed 5bbl and made prompt notifications to NMOCD.

On 2/2/2015 Frontier recovered ~2bbl free liquid from the surface with a hydrovac truck. All free liquid recovered was disposed of at an OCD approved facility. Excavation commenced to delineate and remove contaminated soils and to restore integrity of the pipeline.

Describe Area Affected and Cleanup Action Taken.*

Once excavation has uncovered the pipeline, problem areas will be identified and repaired. Excavation will continue until TPH, BTEX, and Benzene are below the levels outlined in "NMOCD Guidelines for Remediation of Leaks, Spills, and Releases". Impacted soils will be transported to an OCD approved facility for disposal and the area will be backfilled with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Greg Busch		Approved by Environmental Specialist 	
Title: EHS Technician III		Approval Date: 02/26/2015	Expiration Date: 04/26/2015
E-mail Address: gbusch@akaenergy.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/24/15	Phone: 970-764-6651	Site samples required. Delineate and remediate as per NMOCD guides.	1RP-3543 221115

* Attach Additional Sheets If Necessary

nTO1505734888

pTO1505735227