

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation	Contact Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name Hawk B-3 # 9	Facility Type: Oil Well

Surface Owner Farmer Raymond	Mineral Owner BLM	API # 30-025-06501
------------------------------	-------------------	--------------------

### LOCATION OF RELEASE

Unit Letter R	Section 3	Township 21S	Range 37E	Feet from the 1650'	North/South Line FSL	Feet from the 1650'	East/West Line FEL	County Lea
------------------	--------------	-----------------	--------------	------------------------	-------------------------	------------------------	-----------------------	---------------

Latitude N32.50517 Longitude W103.14773

### NATURE OF RELEASE

Type of Release: oil and produced water	Volume of Release 26 barrels of oil and 54 barrels of water	Volume Recovered 25 barrels of oil and 50 barrels of water
Source of Release: Flow line	Date and Hour of Occurrence 2/16/2015	Date and Hour of Discovery 2/16/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Dr. Oberding (NMOCD)	
By Whom? Bruce Baker	Date and Hour 2/17/2015 via email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RECEIVED**

By OCD; Dr. Oberding at 3:04 pm, Mar 23, 2015

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The flow line ruptured. The well was shut in and a vacuum truck was dispatched to pick-up standing fluid.

Describe Area Affected and Cleanup Action Taken.\*  
The entire release was contained inside a 20'X 20'X3' bell hole in the pasture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bruce Baker	Approved by <del>Environmental Specialist:</del> <i>[Signature]</i> PLO	
Title: Environmental Technician	Approval Date: 03/23/2015	Expiration Date: 06/23/2015
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval: Site samples required. Delineate and remediate as per NMOCD guides.	Attached <input type="checkbox"/> IRP-3572 873
Date: 3/23/2015 Phone: (432) 631-6982		

\* Attach Additional Sheets If Necessary

nTO1508254498

pTO1508254870