

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	XTO Energy	Contact	John Robinson
Address	P.O. Box 700 Eunice N.M. 88231	Telephone No.	575-441-5199
Facility Name	Wantz Federal	Facility Type	Battery

Surface Owner	Mineral Owner	BLM	API No.	30-025-29372
---------------	---------------	-----	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
R	1	21 S	37E	1650'	South	1980'	East	LEA

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	13.8 bbls oil	Volume Recovered	5 bbls oil
Source of Release	Hole in oil tank	Date and Hour of Occurrence	11-9-15 1:00 am 04/10/15	Date and Hour of Discovery	11-9-15 8:00 am 04/10/15
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Sol Hughes with BLM and Mark Whitaker with OCD		
By Whom?	John Robinson	Date and Hour	11-9-15 10:30am	04/10/2015	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD; Dr. Oberding at 10:55 am, Apr 13, 2015



Describe Cause of Problem and Remedial Action Taken.*

Hole in bottom of oil tank. We cleaned up all the oil we could with a vacuum truck and plan to dig out the rest of the contaminated soil.

Describe Area Affected and Cleanup Action Taken.*

The spill was contained in the burm area around the tanks. We will clean up all contamination possible and replace with clean backfill

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: John Robinson		Hydrologist Approved by Environmental Specialist 	
Title: Maintenance Foreman		Approval Date: 04/13/2015 Expiration Date: 07/13/2015	
E-mail Address: john_robinson@xtoenergy.com		Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	
Date: 11-10-15 Phone: 575-441-5199		Attached <input type="checkbox"/> 1RP3605 5380	

* Attach Additional Sheets If Necessary

Provide photographic documentation of
remediation.

nTO1510339826

pTO1510339928