District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM1930950727
District RP	1RP-5779
Facility ID	fCOH0815142265
Application ID	pRM1930950218

## **Release Notification**

## **Responsible Party**

Responsible Party ConocoPhillips Company				OGRID 217817			
Contact Name Gustavo Fejervary				Contact Telephone 432/210-7037			
Contact email g.fejervary@cop.com					Incident # (assigned by OCD)		
Contact mail			V 7000 Andrev	ws, TX	79714		
			Location	of R	elease Sc	nurce	
20	00000		Location				
Latitude 32	80360		(NAD 83 in de	ecimal des	Longitude _ rees to 5 decim	-103.77100	
G'. M				1			
Site Name M	Site Name MCA-2C Injection Header				Site Type Injection Header		
Date Release	Discovered	10/2/19			API# (if applicable)		
Unit Letter	Section	Township	Range		Coun	ity	1
J	28	17S	R32E	Lea			-
						justification for the	volumes provided below)
Crude Oil		Volume Released (bbls) 12.3			Volume Recovered (bbls) 1		
✓ Produced Water		Volume Released (bbls) 110.7				Volume Recovered (bbls) 7	
			tion of total dissol water >10,000 mg		ids (TDS)	Yes N	0
Condensa					Volume Recovered (bbls)		
Natural G	Natural Gas Volume Released (Mcf)				Volume Recovered (Mcf)		
Other (describe) Volume/Weight Released (provide units)				Volume/Weight Recovered (provide units)			
Cause of Rel	<sup>ease</sup> Gaske	et on the Heado	er leaked on th	ne flanç	ge valve.	1	

## State of New Mexico Oil Conservation Division

Incident ID	NRM1930950727
District RP	1RP-5779
Facility ID	fCOH0815142265
Application ID	pRM1930950218

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release?						
19.15.29.7(A) NMAC?	it was more than 25 bbls.						
☑ Yes ☐ No	((40'X50X2")+(450'X7'X3")+(118'X100'X4"))X13.57%= 123BBLS						
	13.57%= SOIL SATURATION AFTER 0.5" RAIN IN LAST 24 HRS						
If VES, was immediate no	fVES, was immediate notice given to the OCD? By whom? To whom? When and by what making (nhane, ame: 1, -4-)?						
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?							
It was given on 10/3/19 to district 1 email address and Bradford Billings							
Initial Response							
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury							
✓ The source of the rele	ease has been stopped.						
☑ The impacted area ha	s been secured to protect human health and the environment.						
Released materials ha							
✓ All free liquids and recoverable materials have been removed and managed appropriately.							
If all the actions described above have <u>not</u> been undertaken, explain why:							
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.							
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.							
Printed Name: Gu	stavo Fejervary Environmental Coordinator						
Signature: Date: 10/11/19							
g.feiervarv@	g feiervar/@cop.com 422/240 7027						
email:	Telephone: 432/210-7037						
OCD Only							
Received by: Ramona M	Marcus Date: 11/5/2019						