1R - 18

# REPORTS

DATE:

6/15/1995





## ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

# HORRS DISTRICT OFFICE

OIL CONSERVATION DIVISION \$5 JUNE 16 AM 8 52

### NMOCD Inter-Correspondence

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88241-1980 (505) 393-6161

JR DIVISION

To:

Bill Olson-NMOCD Hydrogeologist Santa Fe

From:

Wayne Price-Environmental Engineer District I

Date:

June 15, 1995

Reference:

Mobil Pipe Line Leak sec 26-Ts 17s-R34e 1 mi. w of Buckeye, NM

Subject:

Corrective Action Plan

Comments:

Dear Bill,

Jerry Sexton has requested that the NMOCD Environmental Bureau handle the corrective action plan for the above mentioned site.

This spill occurred in March of this year. As of to date, we have not received anything from Mobil. When you visited the site on 3/16/95 it was my understanding that Mobil was going to submit a plan of action for both the contaminated soil that has been removed from the ground, and what's remaining in the ground.

Please find enclosed for your reference my field notes. I have also enclosed a copy of Mr. David C. Ince mailing address. It is my understanding he is Mobil's contact on this project.

My last visit to the site was 3/21/95, they have covered the hole, but the dirt pile remains in the east side of the small buffalo wallow.

Please let me know your comments on this project, and if we can assist you any way.

Sincerely yours

Wayne Price-Environmental Engineer

Jerry Sexton-District I Supervisor

attachments-yes



ECT KARFH SHAMA

### STATE OF NEW MEXICO NMOCD District I

### INTER-OFFICE MEMO

To file: Mobil US M&R (Pipeline)

Date:

May 12, 1995

Time:

2:15 pm

Telephone call: \_\_\_\_ Meeting: \_\_\_ Other: \_X\_\_\_

Site Visits

Person called or attending:

see below

REFERENCE: Mobil Pipeline Leak (MPL)-see attached spill

report.

Subject: Field reports

Comments:

- 1. 3/9/95 2:55pm MPL notified NMOCD (B. Prichard) of leak.
- 2. 3/13/95 MPL notified NMOCD correction on spill quantity from 400 bbls. to 700 bbls. per David Ince.
- 3. 3/13/95 3:00pm Wayne Price NMOCD visited site.
  MPL personnel; Jack Murrey, Robert Eckols Mid-Tex Const.
  Hole dug out 16' deep below line leak, contaminated soil on plastic. Bottom hole TPH 4480 ppm, dirt pile 8.8% TPH per contractor. MPL 4" crude line located in sec 26, t17s, R34e just west (140) steps from Marathon well #5 located in (sw/4 sw/4 sec 25, t17s, R34 e). Line is located on the east side of a buffalo wallow. Leaked occurred where MPL 4" crude line crosses over the top of GPM's 12" A8 line.

MPL contractor requested a copy of Leak and spill guidelines. Gave them a set of guidelines.

- 4. 3/15/95 7:15 am telephone call (Price & Ince) progress report and set up meeting at site.
- 5. 3/15/95 approx. 11:00 am site visit. Personnel; Wayne Price NMOCD; MPL personnel David Day, Robert Echols. Hole 25 ' deep, bottom of hole shows signs of gross contamination. Took soil sample from bottom hole strong hydrocarbon smell, cream colored, bottom hole TPH 35,000 ppm, BTEX (PID) >2500 ppm. Took pictures.
- 6. 3/16/95 9:00 am site visit Wayne Price, Bill OLSON NMOCD; MPL personal David Day, David Ince, Terry Lowe, Robert Eckols (MPL contractor). Hole is approx. 30' deep. Bottom of hole sample taken from most recent dirt pile read 2.8 % TPH, BTEX >2500 ppm (PID).

Discussed procedures on clean-up with MPL. Mobil will bring in clean caliche to fill in hole. They will submit a work plan to address the remaining contaminates in the hole and the dirt pile. They will sample the dirt pile to determine if it is hazardous waste.

Gave MPL NM State Engr. office telephone #.

Called NMSE, depth of ground water in nearby windmill is 117'. Also depth of ground water at buckeye is approximately 90-110'.

- 7. 3/21/95 8:45 am took pictures.
- 8. 3/21/95 9:00 am MPL David Ince, Wayne Price NMOCD, Eric Nelson and Leon Anderson NM State Land office; on site.

MPL and NMSLO discussed different land use issues concerning the area. This is NM State Land. They also discussed where caliche could be purchased.

Wayne Price NMOCD Environmental Engineer-District I

Jerry Sexton-District I Supervisor cc: Bill Olson-Hydrogeologist NMOCD Santa Fe office

attached- pictures, sketch of area.

51

Final Revision

# Pevision NEW MEXICO OIL CONSERVATION COMMISSION

### NOTIFICATION OF FIRE, BREAKS, SPILLS, LEAKS. AND BLOWOUTS

	NAME OF MOBIL US M &R				ADDRESS				
OPERATOR				BOX 670 SEMINOLE, TEX. 79360					
REPORT	FIRE	BREAK	SPILL	LEAK	BLOWOUT		OTHER*		
OF				XX		·			
TYPE OF	DRLG	PROD	TANK	PIPE	GASO	OIL	OTHER*		
FACILITY	WELL	WELL	BTTY	LINE XX	PLNT	RFY		·	
NAME OF									
FACILITY VACCUM G	ATHERING S'	YSTEM							
LOCATION OF FACILITY	(QUARTER/Q	UARTER			SEC.	TWP.	RGE.	COUN	
SECTION OR FOOTAGE	DESCRIPTION	۷)			2	6 T17S	R34E	LEA	
DISTANCE AND DIRECTI	ON FROM NE	AREST							
TOWN OR PROMINENT L	ANDMARK	1 MILE WE	ST OF BUCKE	YE STORE		·			
DATE AND HOUR UNKNOWN				DATE AND H 3-9-95 @ 9:00 AM					
OF OCCURENCE				OF DISCOVERY					
WAS IMMEDIATE	YES	NO	NOT RE-	IF YES,					
NOTICE GIVEN?	xxxx		QUIRED	то wном	BONNIE				
BY				DATE	3-9-95				
WHOM D.C.INCE			-	AND HOUF	3:45 P. M.				
TYPE OF			QUANITY		VOLUME R	E-			
FLUID LOST CRUDE OIL			OF LOSS	9	00 COVERED		0		
DID ANY FLUIDS REACH	YES	NO	QUANITY						
A WATERCOURSE? IF YES, DESCRIBE FULL	γ••	xx							
DESCRIBE CAUSE OF PEXTERNAL CORROSION ON PLASTIC FOR TESTI	ROBLEM AND I LEAK, LINE NG AND REM	REMEDIAL A HAS BEEN R EDIATION	EPAIRED , OIL		RT HAS BEEN	BROUGHT	TO THE SURI	FACE AND F	
IF YES, DESCRIBE FULL  DESCRIBE CAUSE OF P  EXTERNAL CORROSION	ROBLEM AND I LEAK, LINE NG AND REMI TED AND CLE	REMEDIAL A HAS BEEN R EDIATION	EPAIRED , OIL		RT HAS BEEN	BROUGHT	TO THE SURI	FACE AND F	
DESCRIBE CAUSE OF P EXTERNAL CORROSION ON PLASTIC FOR TESTI DESCRIBE AREA AFFEC	ROBLEM AND I LEAK, LINE NG AND REM	REMEDIAL A HAS BEEN R EDIATION	EPAIRED , OIL	L STAINED DIF			TO THE SURI	FACE AND F	
DESCRIBE CAUSE OF P EXTERNAL CORROSION ON PLASTIC FOR TESTI DESCRIBE AREA AFFECT	ROBLEM AND I LEAK, LINE NG AND REMI TED AND CLE	REMEDIAL A HAS BEEN R EDIATION	EPAIRED , OIL				TO THE SURI	FACE AND F	
DESCRIBE CAUSE OF P EXTERNAL CORROSION ON PLASTIC FOR TESTI DESCRIBE AREA AFFEC	ROBLEM AND I LEAK, LINE NG AND REMI TED AND CLE FARMING	REMEDIAL A HAS BEEN R EDIATION EANUP ACTIC	EPAIRED , OIL	STAINED DIF	URBAN	OTHER*	TO THE SURI	FACE AND F	
DESCRIBE CAUSE OF P EXTERNAL CORROSION ON PLASTIC FOR TESTI  DESCRIBE AREA AFFECT  DESCRIPTION OF AREA SURFACE CONDITIONS DESCRIBE GENERAL CO CLAM, DRY, AND WA	FARMING SANDY  DNDITIONS PIRM THE INFORM	REMEDIAL A HAS BEEN R EDIATION  EANUP ACTIO  SANDY LOAM REVAILING (1	GRAZING CLAY CEMPERATUR	X ROCKY X E, PRECIPITA	URBAN WET FION, ETC.)**	OTHER*	TO THE SURI	FACE AND S	
DESCRIBE CAUSE OF P EXTERNAL CORROSION ON PLASTIC FOR TESTI  DESCRIBE AREA AFFECT  DESCRIPTION OF AREA SURFACE CONDITIONS DESCRIBE GENERAL CO CLAM, DRY, AND WA	FARMING SANDY  DNDITIONS PIRM THE INFORM	REMEDIAL A HAS BEEN R EDIATION  EANUP ACTIO  SANDY LOAM REVAILING (1	GRAZING CLAY CEMPERATUR	X ROCKY X E, PRECIPITA	URBAN WET FION, ETC.)**	OTHER*	TO THE SUR	FACE AND F	

MOBIL LEAK # 315-95-15

Mobil To INVESTIGATE
FOR GROUND WATER CONTINUE

- NETWON: WILL SUBDICE

1) AN LUS!



# DAVID C. INCE CONSTRUCTION TECHNICAN

MOBIL PIPE LINE CO. P.O. Box 670 Seminole, Texas 79360 (915) 758-2346 Fax (915) 686-1464 Mobile: (915) 758-7588 Home: (915) 758-8183

In Case Of Leak Or Other Pipeline Emergency-Call Collect (915) 684-8381