# 1R - 4-76

## GENERAL CORRESPONDENCE

YEAR(S): 2007

#### Hansen, Edward J., EMNRD

From:

Price, Wayne, EMNRD

Sent:

Monday, November 27, 2006 4:53 PM

To:

Hansen, Edward J., EMNRD

Subject:

FW: Rice Operating Co submittal - ICP for EME C16(1)

Attachments: 3259287626-C-16\_1\_ ICP 11-24-06 lpg.pdf

Please handle, ED call then and see if they have an OCD case #, if not then we need to assign one.

From: L. Peter Galusky, Jr. P.E. [mailto:lpg@texerra.com]

Sent: Friday, November 24, 2006 2:16 PM

To: Price, Wayne, EMNRD

Cc: Kristin Pope

**Subject:** Rice Operating Co submittal - ICP for EME C16(1)

Wayne,

Please find attached, in .pdf format, and Investigation and Characterization Plan for EME C16(1). I will follow this with a hard copy in the mail.

We would like to get right on this, to drill the second week of December. Therefore, we would greatly appreciate your timely approval of this ICP.

Please do not hesitate to call me if you have any questions or need additional information.

Many thanks.

Sincerely,

Pete Galusky

L. Peter Galusky, Jr. P.E. Principal Environmental Engineer Texerra Energy Square 505 N. Big Spring, Suite 404 Midland, Texas 79701

E-mail: lpg@texerra.com Web: www.texerra.com

Office Telephone/Fax: 877-534-9001

#### L. Peter Galusky, Jr. Ph.D., P.G.

Texerra

November 24th, 2006

Mr. Wayne Price

New Mexico Energy, Minerals, & Natural Resources Oil Conservation Division, Environmental Bureau 1220 S. St. Francis Drive Santa Fe, New Mexico 87504

RE: Investigation and Characterization Plan
C-16(1) Leak EME Salt Water Disposal System
UL-C, Sec 16 T22S R37E

Sent via E-mail and U.S. Mail w/ Return Receipt

#### Mr. Price:

RICE Operating Company (ROC) has retained L. Peter Galusky, Jr. Ph.D. to address potential environmental concerns at the above-referenced site. ROC is the service provider (agent) for the EME SWD System and has no ownership of any portion of the pipeline, well, or facility. The System is owned by a consortium of oil producers, System Partners, who provide all operating capital on a percentage ownership/usage basis. Environmental projects of this magnitude require System Partner AFE approval, and work begins as funds are received. In general, project funding is not forthcoming until NMOCD approves the work plan. Therefore, your timely review of this submission would be greatly appreciated.

For all such environmental projects, ROC will choose a path forward that:

- protects public health,
- provides the greatest net environmental benefit,
- complies with NMOCD Rules, and
- is supported by good science.

Each site shall generally have three submissions, as described below:

- 1. An <u>Investigation and Characterization Plan</u> (ICP) is proposed for data gathering and site characterization and assessment.
- 2. Upon evaluating the data and results from the ICP, a recommended remedy will be submitted in a <u>Corrective Action Plan</u> (CAP) if this is warranted.
- 3. Finally, after implementing the remedy, a <u>Closure Report</u> with final documentation will be submitted.

#### Texerra

#### **Background and Previous Work**

Rice Operating Company (ROC) discovered an accidental discharge of produced water at the referenced location on October 12, 2005 (see attached road map). The source of the release was an asbestos-cement pipeline failure, releasing an estimated 35 bbls of produced water. The 4-inch diameter pipeline was replaced with a 4-foot segment of PVC pipe, thus minimizing the threat of future releases and compounded impact.

The surface area affected by this release was approximately 3,700 sq ft (less than 1/10<sup>th</sup> of an acre). Regional groundwater information indicates that the depth to groundwater is approximately 17 to 20 ft below ground surface at this location.

Soil sampling was undertaken by ROC on October 25<sup>th</sup>, 2005. The initial sampling and impact delineation encompassed the area of the release. Samples were taken from the surface to a depth of 3 to 4 feet, using a hand auger, and analyzed for chlorides and organics using field titration and a portable PID, respectively. A subset of samples was sent to a commercial laboratory for verification of field results. A second round of soil sampling was undertaken using a backhoe on November 18<sup>th</sup>, 2005, where soils were sampled to depths of 12 to 14 ft at locations indicated during the previous investigation. Soils were analyzed for chlorides and organics as noted previously.

As part of the emergency response procedure, approximately 120 cu yds of chloride-contaminated soil material from the upper 6 inches of the affected area was removed. This material was taken to the Sundance Disposal facility in Eunice, NM in February, 2006. The site was regraded to original contours, using clean soil material as backfill.

The following scope of work is proposed to provide definitive and sufficient information for the development of a Corrective Action Plan and/or Closure Request.

#### **Proposed Work Elements**

- 1. Summarize information and data collected by ROC to date.
- 2. Summarize additional, publicly available regional and local hydrological information.
- 3. Complete the vertical and lateral delineation of soil chloride concentrations, and prepare three-dimensional graphics to illustrate the horizontal and vertical extent of contamination.
- 4. If warranted, install monitor wells sufficient to determine up-gradient, zone-of-release and down-gradient groundwater chloride concentrations. [All monitoring wells will be constructed (with the annular space sealed with a cement/bentonite mix) per NM Dept. Environment standards].
- 5. Evaluate the risk of groundwater impact in light of the information obtained.

If the evaluation demonstrates that residual constituents pose no threat to ground water quality, then only a surface restoration plan will be proposed to OCD. If, as a result of this work, it is believed that this produced water leak does pose a present or future risk

#### **Texerra**

of impacting groundwater quality, then a corrective action plan (CAP) will be developed and proposed to OCD.

It should be noted that since this release is approximately 400 feet west of a subsequent release (C-16-2) on the same pipeline, that the field investigation will be conducted in conjunction with that for C-16-2, to optimize the locations of any monitor wells which may be installed.

I appreciate the opportunity to work with you and your staff on this project. Please call either myself, at the number below, or Kristin Farris Pope (ROC) at 505-393-9174, if you have any questions or wish to discuss these matters.

Thank you for your consideration.

Sincerely,

L. Peter (**Pete**) Galusky, Jr. Ph.D., P.G. *Principal* 

**Texerra** 

505 N. Big Spring, Suite 404 Midland, Texas 70701

Tel: 432-634-9257


E-mail: <a href="mailto:lpg@texerra.com">lpg@texerra.com</a>
Web site: <a href="mailto:www.texerra.com">www.texerra.com</a>

cc: CDH, KFP, file

attachments: site location map, C-141

32 34.675, -103 15.626 - Google Maps

Page 1 of 1



#### **Directions:**

- Starting in Monument at the intersection of Hwys 8 and 322, travel south on Hwy 8 for 2.9 miles.
- Turn east on dirt road, going through a cattle guard.

  Take east (left) fork. Take 2<sup>nd</sup> lease road past drilling location, turning south for 500 ft.
- Release location is on west side of road.

#### **GPS** Coordinates:

Lat: 32 deg 34.674 minutes Long: -103 deg 15.626 minutes District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

### State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Attached

#### **Release Notification and Corrective Action OPERATOR** Initial Report Final Report Name of Company: Rice Operating Company Contact: Address: 122 West Taylor Telephone No.: 505-393-9174 Facility Name: EME Facility Type: SWD Gathering line Surface Owner: STATE leased to SW Mineral Owner: Lease No.: Cattle Co. LOCATION OF RELEASE Unit Letter Feet from the North/South Line Feet from the County Section Township Range East/West Line C 16 20S 37E **Latitude:** 32\*34.675N **Longitude:** 103\*15.626W NATURE OF RELEASE Type of Release: Produced water Volume of Release: 35 bbls Volume Recovered: 0 Date and Hour of Discovery: Source of Release: Pipeline Date and Hour of Occurrence: 10/12/05 10/12/05 4:30 pm If YES, To Whom? Paul Sheeley Was Immediate Notice Given? By Whom? Jennifer Johnson Date and Hour: 10/13/05 left message at 2:45 pm Was a Watercourse Reached? If YES, Volume Impacting the Watercourse: ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.\* Describe Cause of Problem and Remedial Action Taken.\* 4" AC Pipeline cracked, replaced with 4" PVC Pipeline Describe Area Affected and Cleanup Action Taken.\* Approximately 3728 sq feet affected. Delineation results and work plan to follow. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. **OIL CONSERVATION DIVISION** Signature: Approved by District Supervisor: Printed Name: Jennifer Johnson Environmental and Field Technician **Expiration Date:** Approval Date:

Conditions of Approval:

Phone: 505-393-9174

E-mail Address: jjriceswd@valornet.com

Date: 10/14/05

<sup>\*</sup> Attach Additional Sheets If Necessary