District J 1625 N. French Dr., Hobbs, NM 88240 District II 811 S, First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S, St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NRM2002948523
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible	Party XT	O Energy			OGRID	5380	
Contact Name Kyle Littrell			Contact Telephone 432-221-7331				
Contact email Kyle Littrell@xtoenergy.com				Incident # (assigned by OCD)			
Contact mail			d, Carlsbad, NM				
			Location	of R	elease So	Source	
Latitude 32.	Latitude <u>32.412235</u> Longitude <u>-104.064223</u>						
			(NAD 83 in de	cimal deş	grees to 5 decim	imal places)	
Site Name	BEU 156 (E	BEGS) CS			Site Type	Well Location	
Date Release	Discovered	12/04/2019			API# (if app	pplicable) 30-015-35269 (Big Eddy Unit #156)	
Unit Letter Section Township Range County							
D	11	22S	Range 28E		Coun EDDY	mty	
Surface Owner	r: State		ibal Private (Name:)	
			Nature and	d Vol	ume of F	Release	
	Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)						
Crude Oi	1	Volume Release	d (bbls) 0.0			Volume Recovered (bbls) 0.0	
□ Produced	Water	Volume Release	d (bbls) 41.65			Volume Recovered (bbls) 41.65	
Is the concentration of dissolved chloride produced water >10,000 mg/l?			in the	in the Yes No			
☐ Condensate Volume Released (bbls) 4.63				Volume Recovered (bbls) 4.63			
☐ Natural Gas Volume Released (Mcf)		Volume Recovered (Mcf)					
Other (describe) Volume/Weight Released (provide units)		Volume/Weight Recovered (provide units)					
Cause of Rel	ease: Two	tanks overflowed	due to an unantic	ipated	slug of fluid	d moving through the system. All fluids were recovere	
A 48-hour advance notice of liner inspection was provided by email to NMOCD District 2. The liner was visually inspected and located							
I WO HOIES. AC	two holes. Additional delineation for deferral will be completed by a third party contractor.						

Page 2

Oil Conservation Division

	1 1150 2
Incident ID	NRM2002948523
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the response	onsible party consider this a major release?					
release as defined by							
19.15.29.7(A) NMAC?	YES – An unauthorized release of fluid	over 25 barrels.					
⊠ Yes □ No							
If YES, was immediate no	otice given to the OCD? By whom? To w	hom? When and by what means (phone, email, etc)?					
YES, by Amy Ruth: Mike Morgan; by email December 0-	Bratcher; Rob Hamlet; Victoria Venegas; "Griswold	, Jim, EMNRD"; blm_nm_cfo_spill@blm.gov; Crisha					
Morgan, by email becember of	1, 2019 10:39 AM						
	Initial R	desponse					
The responsible p	arty must undertake the following actions immediate	ely unless they could create a safety hazard that would result in injury					
	ase has been stopped.						
	s been secured to protect human health and	the environment.					
	<u> </u>	dikes, absorbent pads, or other containment devices.					
	coverable materials have been removed a	-					
If all the actions described	l above have <u>not</u> been undertaken, explain	why:					
Per 10 15 20 8 B (A) NIM	AC the regnerable party may commence	wanted a district in the state of the state					
has begun, please attach a	narrative of actions to date. If remedial	remediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred					
within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.							
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and							
regulations all operators are i	required to report and/or file certain release not	ifications and perform corrective actions for releases which may endanger					
public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In							
addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.							
and/or regulations.							
Printed Name: Kyle	Littrell	Title: SH&E Supervisor					
Signature:	Mull	Date:12/17/2019					
	7	Dutc12/1/12019					
email:Kyle_Littrell@:	xtoenergy.com	Telephone:					
OCD Only							
	Marcus						
Received by: Ramona	Ividicus	Date: 1/29/2020					

Location:	BEU 156 (BEGS) CS				
Spill Date:	12/4/2019				
Approximat	Approximate Area = 259.84				cubic ft.
		TOTAL VO	DLUME OF LEAK		
Total Produ	ced Water =			41.65	bbls
Total Conde	ensate =			4.63	bbls
		VOLUM	E RECOVERED		
Total Produ	ced Water =			41.65	bbls
Total Conde	ensate =			4.63	bbls

NRM2002948523