Received by OCD: 2/21/2020 2:56:25 PM

1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

)

Incident ID	NRM2005548076
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party XTO Energy	OGRID 5380
Contact Name Kyle Littrell	Contact Telephone 432-221-7331
Contact email Kyle_Littrell@xtoenergy.com	Incident # (assigned by OCD)
Contact mailing address 522 W. Mermod, Carlsbad, NM 88220	F

Location of Release Source

Latitude <u>32.2 77</u> <u>69</u>

Longitude -103.942959 (NAD 83 in decimal degrees to 5 decimal places)

Site Name Remuda 100 Battery	Site Type Tank Battery
Date Release Discovered 02/08/2020	API# (if applicable) N/A

Unit Letter	Section	Township	Range	County	
E	25	238	29 E	Eddy	

Surface Owner: State Federal Tribal Private (Name:

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls) .05	Volume Recovered (bbls) 0
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release. The VRT compressor went down sending condensate out of the flare creating a small fire on the ground just below flare. The fire burned itself out and there was no standing fluid to recover. Remediation of de minimis staining around the flare stack to be completed by hand digging with disposal at an approved site.

Received by OCD: 2/21/202 Page 2	0 2:56:25 PM ate of New Mexico Oil Conservation Division	Incident ID District RP Facility ID Application ID	NRM2005548078ge 2 of
Was this a major release as defined by 19.15.29.7(A) NMAC? Yes No	If YES, for what reason(s) does the responsible pa An unauthorized release of a volume that results		
Yes by Kyle Littrell to M	otice given to the OCD? By whom? To whom? W like Bratcher; Rob Hamlet; Victoria Venegas; 'Grisw n Sunday, February 9, 2020 at 8:30 AM.		email, etc)?

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \square The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have <u>not</u> been undertaken, explain why:

There were no fluids to be contained via the use of berms or dikes, absorbent pads, or other containment devices. There were no fluids released to be removed and managed.

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Kyle Littrell	Title: <u>SH&E Supervisor</u>
Signature: Contract	Date:2/21/20
email: Kyle_Littrell@xtoenergy.com	Telephone:
OCD Only	
Received by: Ramona Marcus	Date: 02/24/2020

NRM2005548076

Location:	Remuda 100		
Spill Date:	2/8/2020		
Approximat	te Area =	a = 400.00 sq. ft.	
Average Sat	turation (or depth) of spill =	0.3	0 inches
Porosity Fac	ctor =	0.0	3

TOTAL VOLUME OF LEAK				
Total Oil =	0.05	bbls		
VOLUME RECOVERED				
Total Oil =	0.00	bbls		