power wash containment.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

	Form C-141
Revise	ed August 24, 2018
Submit to appropriate (DCD District office

Incident ID	NRM2007850252
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

				1	J	
Responsible Party: Cimarex Energy Co. Of Colorado			OGRID: 162683			
Contact Name: Gloria Garza			Contact Telephone: 432.571.7800			
Contact email: ggarza@cimarex.com				Incident # ((assigned by OCD)	
Contact mail 79701	ling address:	600 N Marienfel	d Ste. 600 Midlar	nd, TX		
			Location	n of R	telease So	ource
Latitude 32.1	7124		(NAD 83 in a	lecimal de	Longitude -: grees to 5 decim	104.31147
Site Name: New Mexico DD State Com 4			Site Type:	Tank Battery		
Date Release	Date Release Discovered: 3.3.2020			API# (if applicable) 30-015-34704		
		1 11	T ==	1		
Unit Letter	Section	Township	Range	D 11	County	
J	32	24S	26E	Edd	y	
Surface Owner: State Federal Tribal Private (Name:) Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)						
Crude Oi		Volume Release		on caroural	ions of specific	Volume Recovered (bbls)
Produced Water Volume Released (bbls)			Volume Recovered (bbls)			
Is the concentration of dissolved chloride produced water >10,000 mg/l?			e in the	☐ Yes ☐ No		
Condensa	ate	Volume Released (bbls) 55 bbls				Volume Recovered (bbls) 55 bbls
Natural G	as	Volume Released (Mcf)				Volume Recovered (Mcf)
Other (de	escribe)	Volume/Weight Released (provide units))	Volume/Weight Recovered (provide units)
Cause of Rel	ease: Mecha	 nnical Failure – Sa	fety			<u></u>
Oil spilled out of the production oil tank thief hatch into the lined containment due to the water dump not working on 250 vessel						
causing all fl	luids to dum	p out of the oil d	ump. The high le	vel kill	on the oil tan	nk did not work and the equalizing line between the oil
tanks was closed. We found that the water dump on the separator was not set correctly and this has been corrected. The high level						
switch has b	een repaired	l, tested and is wo	orking correctly.	We have	e also had the	e discussion with the lease operator about leaving the
equalizing li	ne open bet	ween oil tanks. O	il spilled into a li	ined con	tainment, oil	was recovered and placed back in oil tank. We will



State of New Mexico Oil Conservation Division

Incident ID	NRM2007850252
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release? The amount of the release is over 25 barrels.		
⊠ Yes □ No			
	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?		
By Gloria Garza To Mike Bratcher, Robert By email	t Hamlet, Victoria Venegas and Jim Griswold		
	Initial Response		
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury			
The source of the rele	ease has been stopped.		
	as been secured to protect human health and the environment.		
Released materials ha	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.		
All free liquids and re	ecoverable materials have been removed and managed appropriately.		
If all the actions described	d above have not been undertaken, explain why:		
Dor 10 15 20 9 D (4) NIM	IAC the responsible party may commence remediation immediately after discovery of a release. If remediation		
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.			
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			
Printed Name: Gloria Gar	rza Title: ESH Specialist		
	<u>Pla garza</u> Date: 3/13/20		
email: ggarza@cimarex.c	Telephone: 432.234.3204		
OCD Only			
Received by: Ramon	<u>na Marcus</u> Date: <u>3/18/2020</u>		

Received by OCD: 3/13/2020 3:26:55 PM